

Well Inspection History

Well Name & No.: DAUGHERTY STATE API Number: **30-015-02589-00-00**

County Name: EDDY Operator: SANDLOTT ENERGY (JACKIE BREWER DB : District: ARTESIA

Field: DAUGHERTY STATE Legal: S: 4 T: 18S R: 28E

Well Type: OIL (PRODUCING)

Insp. By Viol. SNC Failed Codes Insp. Dt. Insp. Type Insp. Purpose Insp. No. RmdvRaDt 209

8/4/2008 Routine/Periodic Normal Routine Activity iGEG0821736

Well is not pumping. Took photos.

211 7/20/2007 Routine/Periodic iMLB07201506 Normal Routine Activity

Contamination at well head area. Well is pumping. Unit came on during inspection. Some contamination at tank battery situated North of well

10/20/2005 Compliance Verification Normal Routine Activity iCLB05293417 212

> Took samples along north side of tanks. Sample 1: 32.78334N 104.18598W 3-6 inches Sample 2: 32.78328N 104.18597W 3-6 inches Sample 3: 32.78339N 104.18586W 3-6 inches

1: 32.78329N 104.18590W

2: 32.78330N 104.18595W 3: 32.78339N 104.17595W

8/30/2005 Routine/Periodic Normal Routine Activity iMLB05242353 211

Well is pumping. Stuffing box leaking. Heavy contamination at well head area extending out onto location. Some contamination at tank battery

for this well.

8/19/2004 Routine/Periodic iGEG0423247 209 Normal Routine Activity

Wellhead leaking. Well is pumping.

2/4/2004 Compliance Verification iGEG0403546 209 Normal Routine Activity

Leak stopped. Needs work around well head.

1/26/2004 Routine/Periodic iGEG0402639 209 Normal Routine Activity

Stuffing box leak

11/22/2002 Routine/Periodic Normal Routine Activity iMLB02326477 211

Equipment and Location needs minor attention. PJ---B/T

1/31/2001 Routine/Periodic Normal Routine Activity iPCH0103136 210

Equipment and Location needs minor attention. B/T

207 10/19/1999 Routine/Periodic iELG0002836 Status Check

A-OK. All Equipment and Location in Good Shape. B/T

Total Inspections Performed: 10

Jackie Brewer D/B/A Sandlott Energy De Novo Case 14074 OCD Exhibit No. 5