

Form 3160-5
(June 1990)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OPERATOR'S COPY

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator
DEVON SFS OPERATING, INC.3. Address and Telephone No.
20 NORTH BROADWAY, SUITE 1100, OKLAHOMA CITY, OKLAHOMA 73102 (405) 228-75124. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980' FSL & 1980' FEL, Sec 9-T22S-R32E, Unit J

5. Lease Designation and Serial No.

NM-77057

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

White Swan 9 Federal #3

9. API Well No.

30-025-32301

10. Field and Pool, or Exploratory Area

N/A

11. County or Parish, State

Lea County, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒
- Notice of Intent
-
- ☐
- Subsequent Report
-
- ☐
- Final Abandonment Notice

TYPE OF ACTION

- ☐
- Abandonment
-
- ☐
- Recompletion
-
- ☐
- Plugging Back
-
- ☐
- Casing Repair
-
- ☐
- Altering Casing
-
- ☐
- Other Plug & Abandon


- ☐
- Change of Plans
-
- ☐
- New Construction
-
- ☐
- Non-Routine Fracturing
-
- ☐
- Water Shut-Off
-
- ☐
- Conversion to Injection
-
- ☐
- Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Devon SFS Operating, Inc. request approval to Plug and Abandon the above referenced well. Below is the Plugging procedure.

1. MIRU PU. ND WH & NU BOP.
2. POOH w/206 jts 2 7/8" tbg.
3. RU WL. RIH w/5 1/2" CIBP to 7000', set CIBP & dump 35' of cmt on top.
4. RIH w/tbg to 6950'. Displace hole w/mud.
5. PU to 4750', spot 150' cmt plug from 4750-4600'. POOH w/tbg
6. Cut off csg @ ±4000'. POOH laying down csg.
7. RIH w/tbg to cut off. Spot 140' plug across cut off.
8. PU to 960', spot 140' cmt plug from 960' - 850' across top of salt. Tag plug.
9. PU to 660', spot 110' cmt plug from 660' - 550' across 13 3/8" show. Tag plug.

SEE ATTACHED FOR
CONDITIONS OF APPROVALMUST SQUEEZE "SURFACE SHOE PLUG" TO
fill annulus as much as possible to get 100 Ft
across shoe. SEE DIAGRAM

14. I hereby certify that the foregoing is true and correct.

Signed: *Karen A. Cotton*
(This space for Federal or State office use)

Karen A. Cotton

Title: Engineering Technician

Date: February 8, 2002

APPROVED

Approved by: _____
Conditions of approval, if any: _____

Title: _____

Date: _____

FEB 20 2002

Title 18 U.S.C. Section 1001, makes it a crime for any person to knowingly and willfully make to any department or agency of the United States any false, fictitious or fraudulent statements or representations to any matter within its jurisdiction.

PETROLEUM ENGINEER

Gary Gourley 505-627-0249

*See Instruction on Reverse Side

OIL CONSERVATION DIVISION

CASE NUMBER

12771-A

Devon

EXHIBIT

1

BUREAU OF LAND MANAGEMENT
Roswell Field Office
2909 West Second Street
Roswell, New Mexico 88201
505-627-0272

**Permanent Abandonment of Federal Wells
Conditions of Approval**

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within ninety (90) days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.
2. Notification: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 505-627-0272. Eddy County call 505-234-5972; for wells in Lea County call 505-393-3612.
3. Blowout Preventers: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
4. Mud Requirement: Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.
6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer, such as metes and bounds).
7. Subsequent Plugging Reporting: Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show date well was plugged.
8. Trash: All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.

