


- Down-to-North Fault
- Down-to-South Fault
- Active Dakota Producing Well
- BHL
- Surface

 Cross Timbers Oil Company
UTE DOME FIELD San Juan County, New Mexico
STRUCTURE: Top of Dakota
November, 1998 GKB/MSV

NEW MEXICO
GAME AND CONSERVATION DIVISION

EXHIBIT **3**

CASE NO. _____