


R14W



— Down-to-North Fault

— Down-to-South Fault

○ Active Dakota Producing Well



Cross Timbers Oil Company

UTE DOME FIELD

San Juan County, New Mexico

STRUCTURE: Top of Dakota

November, 1998

GKB/MSV

PERMIT TO
WILDLIFE CONSERVATION

EXHIBIT 4

CASE NO. _____