PRINCIPAL:

POE PROPERTIES, INC. 36355

SURETY:

United States Fire Insurance Company

76131

BOND NO.:

610 082418 6

18801 NO1

\$50,000 Blaket Plugging Bond

TYPE:

November 22, 1983

APPROVED:

CFL - January 15, 1988 10 well 4-19-94

CANCELLED:

WELL LOCATION:

BEFORE EXAMINER STOGNER

2531 CASE NO.

Hebert, Lyn

From:

Prichard, Billy

Sent:

Tuesday, October 10, 2000 11:54 AM

To:

Hebert, Lyn

Cc:

Wink, Gary, Williams, Chris

Subject:

SCH

Lyn, I am mailing today information on Poe Properties,Inc..Well is the Ivey # 1,UL J, Sec 29, T4S, R33E, API # 30-041-20723.. This well is in need of plugging and the bond was released in 1994. Attached is picture if



xx,29,4,33a.jpeg

needed.

Thanks

Billy Prichard

U.S. Fre Insurance Grapany

Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Res	WELL API NO.
District II 811 South First, Artesia, NM 88210	OIL CONSERVATION DIVIS	SION 30-041-20723
District III	2040 South Pacheco	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE 🗖 FEE 🔀
District IV 2040 South Pacheco, Santa Fe, NM 87505	Sana 1 0, 1111 0 1 3 0 3	6. State Oil & Gas Lease No.
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLIED	Titalite.	
PROPOSALS.)	Ivey	
1. Type of Well:		
Oil Well Gas Well	Other	
2. Name of Operator Poe Properties, Inc		8. Well No.#1
3. Address of Operator		8. Pool name or Wildcat
P O Box 9769, Ft. Worth, Tx 7610	7	Peterson - Miss
4. Well Location		
Unit LetterJ:	2310feet from theSouth lin	te and1980feet from theEastline
Section 29	Township 4S Range 3	3E NMPM Roosevelt County
Section 29	10. Elevation (Show whether DR, RKB,	
	4376 GL	
	ppropriate Box to Indicate Nature of	
NOTICE OF IN	SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔀 REME	DIAL WORK ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS COMM	IENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	ı	G TEST AND
	COMPLETION CEME	NT JOB
OTHER:	OTHER	
		etails, and give pertinent dates, including estimated date
of starting any proposed work) or recompilation.	. SEE RULE 1103. For Multiple Completi	ons: Attach wellbore diagram of proposed completion
•	ulated to plastic lined pit or steel tank	
2) See attached plugging pro-		
z) see amen a pragging pro		
I hereby certify that the information	above is true and complete to the best of m	y knowledge and helief
	·	
SIGNATURE	TITLE	DATE
Type or print name		Telephone No.
(This space for State use)		
APPPROVED BY	TITLE	DATE
Conditions of approval, if any:		*



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

Mo listing on H. Worth

Oil conservation division
DISTRATS

OIL CONSERVATION DIVISION
DISTRICT I HOBBS
1625 N. FRENCH DRIVE, HOBBS, NM 88240
(505) 393-6161
FAX (505) 393-0720

Jennifer A. Salisbury CABINET SECRETARY

March 2, 2000

Poe Properties, Inc. P.O. Box 9769 Fort Worth, TX 76107

RE:

IVEY #1 - DRY HOLE

UNIT J-S29-T4S-R33E

30-04/-20723

Gentlemen:

Through routine inspection it has come to our attention that the above referenced well has been shut-in, for an extended period of time. Our records show that August 7, 1985, Jerry Sexton approved a C-103 Notice of Intent to Plug and Abandon the subject well. The plug and abandonment of this well was never performed, and when I checked with Dorothy Phillips, of our Santa Fe office, the \$50,000 Blanket Surety Bond issued by U. S. Fire Insurance co. was released April 19, 1994.

I would like to know how this bond was released without the well being plugged. I will be sending a copy of this letter along with the well file information to Lynn Hebert, Oil Conservation Division Attorney, Santa Fe, requesting a show cause hearing why this well should be plugged.

I would appreciate a reply to this letter within 10 days of receipt of letter. If I can be of any assistance to you please do not hesitate in contacting me @ 505-393-6161 ext. 114.

Sincerely,

OIL CONSERVATION DIVISION

GARY WINK

gw/sad

cc:

Chris Williams

Lynn Hebert

Æile

ERGY AND MINERA		TMENT		` ` (CONSI	ERV#	ATIO	N DIV	VISIO	N É		75 "G.A.	inta "ii"u		
DIST ALBUTIO			C CONSERVATION DIVISION :							State Fee					
SANTA PE	" -	 	SANTA FE, NEW MEXICO 87501						5. State Oil & Gas Lease No.						
FILE													•		
U.S.G.S.		Ⅲ w	ELL	COMPLE	TION OI	RREC	OMPLE	TION	REPOR	T AND	LOG	rrr	7777	mm	177
LAND OFFICE					.,								////		$^{\prime\prime\prime}$
OPERATOR		1										7777	7777	7117777	77)
TYPE OF WELL			_	•				·				/, Unit /	igreeme	ent Name	
		# E L I	ıΠ	GAS WELL		DRY		THER							
TYPE OF COMPLE	ETION		_				,				1 '	•		se Name	
WELL OV		DEEPE	<u>. L.J</u>	PLUG		SVA.	. ا	THER				IVE		····	
Name of Operator											1). Well N	io.		
	OPERTI	ES, 11	NC.									<u> </u>			
Address of Operator										•	,			Poul, or Wilde	
P. 0.	Box 97	69, Fo	ort V	North, 1	Texas 7	76107					[٢	eters	on-M	lississi) qc
ocation of Well												1111	III	[[[]]	T_L
													7///	///////	III
LETTERJ	LOCA	res	310	FEET FF	OM THE	south	LIN	IE AND	1980	FECT	FROM	11111	////	.//////	$^{\prime\prime\prime}$
 -								1111	11111	11111	////	2. Coun	-	1111	M
east	sec. 2	9 ,,	wp.	1S	. 33E	- - HMPH	. [[]]		IIXII		1111	Roose	velt		111
Date Spudded	16. Date	T.D. R	eached	17. Date	Compl. (R	eady to		18. Ele	vations (DF, RKB.	RT, GR	, etc.) 1	9. Ele	v. Castingh	ad
4-11-84	5-	6-84						4	376' 0	S.L.					
Total Depth		21. Plug	Back	т.D.		Il Multip	le Comp		23. Int	ervals		Teols	, (Cable Tools	
8300¹						Many		-	Dr —	illed By	0-83	001	!		
Producing Interval	s), of this	completi	ion – T	op, Bottom	, Name						·			Was Direction	nal S
													\ \ \ \	Mude	
None														No	
Type Electric and	Other Logs	Run										27	. Was V	Well Cored	
			ŧv -	Neutron	n Dua	1						ł		No	
· · · · · · · · · · · · · · · · · · ·					ING RECO		ort all's	trings se	et in well)	<u> </u>					
CASING SIZE	WELG	HT LB./	ET	DEPTH			LE SIZE			MENTIN	G RECOR	· · · · · · · · · · · · · · · · · · ·		AMOUNT F	2111 1
13 3/8"							1/2"						-+	AMOUNT !	
8 5/8"		4.5# 4.0#						1/2" 375 Sx (circ.) " 700 Sx (circ.)							
5 1/2"		7.0#		830		11	7/8"		<u>700 Sx</u> 600 Sx		ــــــــــــــــــــــــــــــــــــــ		-		
3 1/2	- '	7.0#		باره	,0		1/0		000 3x	·					
			NED D	ECORD					30.		711	BING RE	EC ORD		
						1			+	[T		
SIZE	. TOI		80	TTOM	SACKS C	EMENT	SCH	REEN	SI	(E	DEP	THSET		PACKER	36
									 						
	···			<u> </u>	<u> </u>		T		1						
Perforation Record	(interval,	size and	numbe	7)			32.			, FRACT				ZE, ETC.	
8251-8	258' (14 ho!	les)					EPTH IN		100				ATERIAL I	SEO
								51-82			00 gal				
8110-8	1301 (20 hol	les)				L	51-82						0# Sand	
				-			81	10-81	<u> </u>	C02				WG-18 ar	ıd
							<u> </u>				16 s	acks	<u>sand</u>	•	
			<u>.</u>				UCTION								
a First Production		Produc	tion Me	thod (Flow	ring, gas l	ijt, pump	ing - Si	ze and t	ype pump)	1				rod. or Shut-i	n)
None		<u> </u>										Prep	<u>. to</u>	Plug	
of Test	Hows To	ested	Che	oke Size	Prod'n. Test Pe		OII - B	ы.	Gas -	MCF	Water -	- Вы.	Gai	s - Oli Ratio	
			_l						<u> </u>						
Tubing Press.	Casing	Stess me		culated 24- x Rate	OII - BI	bl.	, Ga	s - MCF	•	Water —	вы.	C	II Grav	vity - API (Corr.
	<u></u>									l		1			
Disposition of Gas	(Sold, used	for fuel	, vente	d, etc.)							Test W	itnessed	Ву		
٠	£ .										1				
.ist of Attachments									 						
Deviat	ion Rep	ort											-4		
hereby certify the	the inform	ation sh	own on	both sides	of this fo	rm is tru	e and co	mplete u	o the best	of my kn	owledge	and beli	e f.		
) /	18	>	_ ()											
SIGNA S	Eert	*/)く	with	red		. ~	A	+					7-26	_Q S	
SICHED	nac A	kinsuf	كستهد			LE	<u>Agen</u>	٠			¤	ATE	<u> </u>	-02	

ENERGY AND MINERALS DEPARTMENT	P. O. BC	ATION DIVISION DX 2088 W MEXICO 87501		Form C-103 Revised 10
U.S.G.S. LAND OFFICE OFFRATOR ****		WEXICO OF SU	State Oll 6 Gar	Foe
SUNDRY NI 100 HET USE THIS FORM FOR PROPOSAL	OTICES AND REPORTS ON	N WELL'S BACK TO A DIFFERENT HEBERVOIR. CEN PROPOSALS:)	7. Unit Agreement	Name
	Dry Hole			
2. Name of Operator			8. Firm or Lease	liame
POE PROPERTIES, INC.	**************************************	<u></u>	JVEY 3. Well No.	
P. 0. Box 9769, Fort	Worth, Texas 76107		11	
t. Location of Well	10 courth	1000	10. Field and Poo	
UNIT CETTER J Z3	10 FEET FROM THE SOUTH	LINE AND 1900 FELT	Peterson	- MISS.
THE <u>east</u> LINE, SECTION_	29 TOWNSHIP 4S	MANGE 33E	MPM. ()	
	15. Elevation (Show whethe	r DF, RT, GR, etc.)	12. County	
	4376' G.L.		Roosevelt	-077777
Check Appr NOTICE OF INTER		Nature of Notice, Report or subsequ	Other Data ENT REPORT OF:	
CENT ON MINISMEN MINISMEN	PLUG AND ABANDON	HEMEDIAL WORK	ALTERI	IG CASING
TEMPORARICE ABANDON		COMMENCE DRILLING OPHS.	PLUG An	IO ABANDOHMENT
PULL OF ALTEN CASENG	CHANGE PLANS	CASING TEST AND CEMENT JOB		
OTHER		OTHER		
	(C)	1	dina antimated data of a	
17, Describe Proposed or Completed Operation work) SEE RULE 1103.	ons (Clearly state all pertinent de	taits, and give pertinent dates, inclu	aing extimated date of si	arting any prop
TD - 8300'. (13 3/8"-375'- Perforations - 8110-8130',		-circ) (5 1/2"-8300†-6	00 sx, Est. TC	- 4478†)
Spot 20-sack cement p Spot 20-sack cement p Cut & salvage ± 4478¹ Spot 28-sack cement p Spot 35-sack cement p Spot 35-sack cement p Spot 7-sack cement pl	blug from 7280-7130'. of $5\frac{1}{2}$ " casing. blug 50' in and out oblug from 3120-3020'. blug from 1950-1850'.	f 5½" stub. Tag		
Heavy mud will be placed be	etween plugs and regu	lation 4" marker will	be placed over	well.
This abandonment program is on 7-30-85.	in accordance with	plugging program outli	ned by Mr. Jerr	y Sexton
18. I hereby serilly that the information above	\mathcal{Q}	of my knowledge and belief. Agent	DATE 38-2-8	
ares A. Knauf	TITLE	, nygitt.		
ORIGINAL SIGNED BY JERRY DISTRICT I SUPERVISO	, SEXTON OR		"AUG-	7 1985

Plugging Procedure Poe Properties Ivey # 1 UL J, Sec 29, T4S, R33E API # 30-041-20723

13 3/8" csg set at 375 feet, cement circulated 8 5/8" csg set at 1896 feet, cement circulated 5 ½" csg set at 8300 feet, cement with 600 xs cmt, calculated TOC 4478 feet Perfs 8110-8258 feet

- 1. Move in rig up plugging unit
- 2. Check well head for presence of tubing
- 3. Nipple up BOP
- 4. Run sinker bar with wireline, tag PBTD
- 5. If PBTD allows run gauge ring to 8060 feet
- 6. Run and set cast iron bridge plug at 8060 feet
- 7. Cap CIBP with 35 feet of cmt by dump bailer
- 8. Run tubing to 8020 feet
- 9. Displace well with MLF
- 10. Pull tubing to 7280 feet
- 11. Spot 25 sx cmt plug
- 12. Pull tubing
- 13. Weld on pull nipple and stretch casing
- 14. Cut and pull csg from free point
- 15. Run tubing to 50 foot inside of casing stub
- 16. Spot 35 sx cmt
- 17. Pull tubing and WOC
- 18. Run tubing and tag cement plug
- 19. Maximum depth is casing stub minus 50 feet
- 20. Pull tubing to 3120 feet
- 21. Spot 35 sx cmt
- 22. Pull tubing to 1950 feet
- 23. Spot 35 sx cmt
- 24. Pull tubing and WOC
- 25. Run tubing and tag cement plug
- 26. Maximum depth 1846 feet
- 27. Pull tubing to 425 feet
- 28. Spot 35 sx cmt plug
- 29. Pull tubing and WOC
- 30. Run tubing and tag cmt plug
- 31. Maximum depth is 325 feet
- 32. Pull tubing to 60 feet and circulate cement to surface
- 33. Pull tubing and cut off well head and install PA marker
- 34. Rig down move out plugging unit
- 35. Cut off anchors and clean location