




PERDIDOS

EL RIO DE LAS ANIMAS

SAN JUAN PLAZA NORTH

TWENTIETH ST

BARGER'S MARKET

12

SAN JUAN PLAZA

EAST MAIN STREET
DENVER & RIO GRANDE WESTERN RAILROAD

TOWN OF FARMINGTON
GLENN P. MYCOFF

WAYNE TARPLEY

WAYNE TARPLEY

M.H. ENGELBRECHT

* IE

FEDERAL

L.P. LANG

FEDERAL

M.P. WOOLMAN

M.H. ENGELBRECHT

JACK WHEAT

J.R. WOOLMAN

J.W. SPRAGG

MARY ELLEN WOOLMAN

12

J.N. TINNIN

FEDERAL

FEDERAL

B.A. BURNHAM

C.S. LINDBERG

L.P. WOODS

R.H. NORDHAUSEN

V.C. STEPHENS

L.O. BURNHAM

W.R. JOHNSTON

FEDERAL

RAY PHILLIPS, JR.

FEDERAL

FEDERAL

FEDERAL

T.E. ADWIN

T.A. DUGAN

FEDERAL

P.J. CLOTE

E.L. EEDS

J.M. NEWMAN

GRADY

R.E. DWYER

FEDERAL

FEDERAL

J.H. STOLWORTHY

C.E. MATHEWS

FEDERAL

C.G. PISTOLE

J.D. LEGG

F.S. COURTER

J.M. CLARK

FEDERAL

FEDERAL

F.S. ALEXANDER

Z.B. PATRUM

FEDERAL

FEDERAL

FEDERAL

FEDERAL

BEFORE EXAMINER STOGNER
OIL CONSERVATION DIVISION
EXHIBIT 1.0.

CASE NO. 8489

ANIMAS LODGE

B.E. DUSTIN

C
STATE NEW MEXICO
COUNTY San Juan SEC. 12 T. 29N R. 13W
FIELD OR AREA Kutz- Fulcher LOCATION 304' N, 2242' W
LEASE Sutton, John C. WELL NO. 1
COMPANY Animas Oil Co. SPD. 6-27-25 COMPLETED 1-18-26
ELEV. 5300' T.D. 512' P.B. _____
CASING _____
SHOT OR ACID _____
PERF. _____
I. P. _____
PRODUCING FORM. _____
PRODUCTIVE DEPTH OR INTERVAL _____

REMARKS:

P&A

8489

2

Case 8489


COUNTY San Juan STATE NEW MEXICO NW NE SW
FIELD OR AREA ~~Kuts-Eulohar~~ Carman SEC. 12 T. 29N R. 13W
LEASE Sutton, John G. LOCATION 304' / S 224' / W
COMPANY Antmas Oil Co. : Cross, Gould WELL NO. 2
ELEV. 5300' T.D. 512' COMPLETED 1-18-26
P.B. _____
CASING _____
SHOT OR ACID _____
PERF. _____
I. P. log
PRODUCING FORM. _____
PRODUCTIVE DEPTH OR INTERVAL _____

REMARKS:

P&A 1931 Jan.

8489

3



1000 RIO BRAZOS ROAD
AZTEC, NEW MEXICO 87410
(505) 334-6178

Animas Oil Co.
John C. Sutton #1
304' FNL, 2242' FWL
C-12-T29N-R13W, San Juan County, N.M.

1. Locate well.
2. Clean out/or drill out to 512'.
3. Set cement plug inside and outside of casing, if present, from T.D. - surface.
4. Set dry hole marker.
5. Clean and restore location to original condition.
6. All plugs shall be of Class A, B, or C neat cement and may be accelerated by up to 3% CaCl_2 .

5

CASE NO. 8489