


NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		1
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		



Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>DRY HOLE</b>		7. Unit Agreement Name
2. Name of Operator <b>ODESSA NATURAL CORPORATION</b>		8. Farm or Lease Name <b>ODESSA NATURAL CORP.</b>
3. Address of Operator <b>P. O. Box 3908, Odessa, Texas 79760</b>		9. Well No. <b>2</b>
4. Location of Well UNIT LETTER <b>A</b> <b>864</b> FEET FROM THE <b>North</b> LINE AND <b>821</b> FEET FROM THE <b>East</b> LINE, SECTION <b>16</b> TOWNSHIP <b>30N</b> RANGE <b>19E</b> N.M.P.M.		10. Field and Pool, or Wildcat <b>Wildcat</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>GR 7200' KB 7213'</b>		12. County <b>Colfax</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**AUGUST 2, 1972 TD 5402' PBTD 5267'**

It is intended to plug and abandon this well as follows:

- (1) Cut off 4-1/2" OD casing at free point.
- (2) Set 20 sacks regular cement plug on top of 4-1/2" OD casing stub.
- (3) Set 35 sacks regular cement plug 200-300' (Bottom of surface casing)
- (4) Set 5 sacks regular cement plug at surface w/4" OD x 4' high dry hole marker.

**Distribution:**

3/NMCCC-Santa Fe, 1/WSRanch, 1/RIH, 1/JH, 1/JJS, 1/WFile, 2/LC

I, Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John J. Strojek TITLE MANAGER - PRODUCTION DEPT. DATE 8/2/72  
JOHN J. STROJEK SO  
 APPROVED BY J. K. Kestina TITLE Oil & Gas Inspector DATE 8/10/72  
W. H. II  
 CONDITIONS OF APPROVAL, IF ANY: