

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	John H. Hendrix Corporation	Contact	Carolyn Doran Haynes
Address	P. O. Box 3040, Midland, TX 79702	Telephone No.	432-684-6631
Facility Name	Morning Glory	Facility Type	Production Battery
Surface Owner	P	Mineral Owner	API No. 30-025-24244

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	17	22S	37E	1880	North	330	East	Lea

Latitude 32.393944° Longitude -103.177521°

### NATURE OF RELEASE

Type of Release Produced	Water	Volume of Release	100-150 bbl	Volume Recovered	15-20 bbls
Source of Release	water tank failure	Date and Hour of Occurrence	04/18/15	Date and Hour of Discovery	04/18/15 9:30 am
Was Immediate Notice Given?	As soon as info was gathered <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	Carolyn Doran Haynes	If YES, To Whom?	Call to Maxey Brown; w/follow-up Email of C-141 to Tomáš Oberding		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Date and Hour	04/18/15 10:15 am	
If a Watercourse was Impacted, Describe Fully.*		If YES, Volume Impacting the Watercourse.			

**RECEIVED**

By OCD; Dr. Oberding at 9:07 am, Apr 20, 2015

#### Describe Cause of Problem and Remedial Action Taken.\*

Steel Tank seam failure, releasing produced fluids into the facility berm. Some water flowed from a break in the berm onto the surrounding caliche pad and roadway. All standing fluid was recovered and disposed at Sundance Disposal. The water tank will be replaced.

#### Describe Area Affected and Cleanup Action Taken.\*

Area affected was inside the facility berm, facility caliche pad area and roadway as depicted in attached sketch. Soils inside the berm will be excavated as applicable and replaced. Affected caliche pad surrounding the facility will be scraped-up, disposed at Sundance and replaced. Photos and further clean-up will be submitted.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Carolyn Doran Haynes</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Carolyn Doran Haynes	Hydrologist	Approved by Environmental Specialist: <i>[Signature]</i> P40
Title: Engineer	Approval Date: 04/20/2015	Expiration Date:
E-mail Address: cdoranhaynes@jhhc.org	Conditions of Approval: Site samples required. Delineate and remediate area as per NMOCD guides.	Attached <input type="checkbox"/>
Date: 04/18/15 Phone: 432-684-6631	Provide geotagged photographs of remediation.	12024

\* Attach Additional Sheets If Necessary

nTO1511034459

pTO1511034770