AP - <u>44</u>

STAGE 1 & 2 WORKPLANS

DATE: July, 2005



Highlander Environmental Corp.

Midland, Texas

CERTIFIED MAIL RETURN RECIEPT NO. 7004 1160 0000 4837 8614

July 7, 2005

Mr. Daniel Sanchez New Mexico Energy, Minerals, & Natural Resources Oil Conservation Division, Environmental Bureau 1220 S. St. Francis Drive Santa Fe, New Mexico 87504

RE: STAGE I ABATEMENT PLAN H-13 LEAK, EME SWD SYSTEM UNIT "H", SEC. 13, T20S, R36E NMOCD Case #1R0429

Mr. Price:

RICE Operating Company (ROC) has retained Highlander Environmental Corp. (Highlander) to address potential environmental concerns at the above-referenced site. ROC is the service provider (operator) for the Eunice Monument Eumont (EME) SWD System and has no ownership of any portion of the pipeline, well, or facility. The System is owned by a consortium of oil producers, System Partners, who provide all operating capital on a percentage ownership/usage basis. In general, project funding is not forthcoming until NMOCD approves the work plan. Therefore, your timely review of this submission is requested. The following Stage I Abatement Plan is for the EME H-13 Site.

Should you have any questions, please contact me at (432) 682-4559. Your prompt review of this submission is appreciated. Thank you for your attention to this matter.

Highlander Environmental Corp.

2005 JUL 15 PRODE 2001 JUL 1991 PRISE SH

Timothy M. Reed, P.G. Vice President

cc: Wayne Price – NMOCD Kristin Farris Pope - ROC

STAGE I ABATEMENT PLAN H-13 LEAK, EME SWD SYSTEM UNIT "H", SEC. 13, T-20-S, R-36-E

NMOCD CASE #1R0429

Prepared for

RICE OPERATING COMPANY

JULY 2005



Highlander Environmental Corp.

Midland, Texas

TABLE OF CONTENTS

SECTION 1	EXECUTIVE SUMMARY	1
SECTION 2	CHRONOLOGY OF EVENTS	1
SECTION 3	BACKGROUND AND PREVIOUS WORK	2
SECTION 4	GEOLOGY AND HYDROGEOLOGY	3
4.1	Regional and Local Geology	3
4.2	Regional and Local Hydrogeology	3
4.3	Water Well Inventory	3
SECTION 5	SUBSURFACE SOILS	3
SECTION 6	GROUNDWATER QUALITY	4
6.1	Monitoring Program	4
6.2	Hydrocarbons in Groundwater	4
6.3	Other Constituents of concern	4
SECTION 7	STAGE I ABATEMENT PLAN	4
SECTION 8	QUALITY ASSURANCE/QUALITY CONTROL	5
SECTION 9	PROPOSED SCHEDULE OF ACTIVITIES	5
Table 1	Sample Analysis/Chloride, TDS Graph	
Figure 1 Figure 2	Lea County, New Mexico Topographic Map EME H-13 Site Map	
Photographs		
Appendix A	Disclosure Package	

Highlander Environmental Corp.

Midland, Texas

1

L

ł



Highlander Environmental Corp.

Midland, Texas

STAGE I ABATEMENT PLAN H-13 LEAK, EME SWD SYSTEM UNIT "H", SEC. 13, T20S, R36E NMOCD Case #1R0429

1.0 EXECUTIVE SUMMARY

RICE Operating Company (ROC) discovered an accidental discharge at the Eunice Monument Eumont (EME) SWD H-13 location on July 3, 2002. The soil had settled underneath a 4" asbestos/concrete system line causing it to break. According to the C-141 form (Initial) filed on July 11, 2002, the total volume spilled was 10 barrels with 5 barrels recovered and disposed of into the EME SWD system. The pipeline leak was permanently repaired to minimize the potential for further impairment.

Two delineation trenches and a soil boring have been installed. Based upon the chloride concentrations and relatively shallow groundwater (~31' bgs), this soil boring was completed as a monitoring well. The monitoring well has been sampled on a quarterly basis since October 2002. The only constituent of concern observed is chloride, with concentrations ranging from 177 mg/L to 2,610 mg/L.

2.0 CHRONOLOGY OF EVENTS

July 3, 2002	ROC discovered an accidental discharge at the above referenced site.
July 11, 2002	A C-141 form (Initial) was filed. The total volume spilled was 10 barrels with 5 barrels recovered and disposed of into the EME SWD system. The pipeline leak was permanently repaired to
	minimize the potential for further impairment.
July 22, 2002	Two delineation trenches were excavated, one on the east side of
September 25, 2002	the system line and one on the west side of the line. A soil boring was installed to further delineate the depth of impact. Based upon the chloride concentrations and relatively shallow groundwater (~31' bgs), this soil boring was completed as a monitoring well. The well was completed to a total depth of 41' bgs.
October 29, 2002 December 13, 2002	Monitor Well (MW-1) was purged and sampled. NMOCD director notified of groundwater impact.

1910 N. Big Spring • Midland, Texas 79705 ¹ • (432) 682-4559 • Fax (432) 682-3946

March 6, 2003 May 29, 2003 August 22, 2003	Monitor Well (MW-1) was purged and sampled. Monitor Well (MW-1) was purged and sampled. Monitor Well (MW-1) was purged and sampled.
November 19, 2003	Monitor Well (MW-1) was purged and sampled.
February 18, 2004	Monitor Well (MW-1) was purged and sampled.
May 27, 2004	Monitor Well (MW-1) was purged and sampled.
September 7, 2004	Monitor Well (MW-1) was purged and sampled.
November 24, 2004	Monitor Well (MW-1) was purged and sampled.
January 14, 2005	2004 Monitor Well Report/Summary Sampling submitted to the NMOCD.
March 17, 2005	Investigation & Characterization Plan (ICP) submitted to the NMOCD.
March 30, 2005	Monitor Well (MW-1) was purged and sampled.
May 5, 2005	Daniel Sanchez (NMOCD) requested a Rule 19, Stage I Abatement Plan for this site.
June 21, 2005	Monitor Well (MW-1) was purged and sampled.

3.0 BACKGROUND & PREVIOUS WORK

ROC discovered an accidental discharge at the above referenced site on July 3, 2002. The soil had settled underneath a 4" asbestos/concrete system line causing it to break. According to the C-141 form (Initial) filed on July 11, 2002, the total volume spilled was 10 barrels with 5 barrels recovered and disposed of into the EME SWD system. The pipeline leak was permanently repaired to minimize the potential for further impairment. The site location is shown on Figure 1.

Two delineation trenches were excavated on July 22, 2002, one on the east side of the system line and one on the west side of the line. Chloride concentrations in the east trench decreased to 254 mg/kg at a depth of 8' below ground surface, while the west trench exhibited elevated chloride levels to 12' below ground surface (bgs). A soil boring was installed on September 25, 2002 to further delineate the depth of impact. Based upon the chloride concentrations and relatively shallow groundwater (~31' bgs), this soil boring was completed as a monitoring well. The well was completed to a total depth of 41' bgs.

The monitoring well has been sampled on a quarterly basis since October 2002. The most recent sampling was performed on June 21, 2005, and the data was submitted to the NMOCD most recently on January 14, 2005, in the Annual Ground Water Report. In the quarterly sampling events to date, the only constituent of concern observed was chloride, with concentrations ranging from 177 mg/L to 2,610 mg/L. Total dissolved solid concentrations have ranged from 751 mg/L to 5,600 mg/L.

4.0 GEOLOGY & HYDROGEOLOGY

4.1 Regional and Local Geology

This site is located in the Laguna Valley physiographic subdivision of southern Lea County. Laguna Valley is the eastern part of a vast sand dune area covering approximately 400 square miles. The site is immediately south-southwest of Mescalero Ridge. Sediments of Quaternary age are present in this area in the form of alluvial deposits, probably both of Pleistocene and Recent age and the dune sands of Recent age. The alluvium was deposited in topographically low areas where the Ogallala formation had been stripped away. The dune sands mantle the older alluvium in most places, with some dunes locally extending to 20-40 feet high. The Quaternary alluvium is underlain by the Dockum group of Triassic age. The uppermost formation of the Dockum Group is the Chinle.

4.2 Regional and Local Hydrogeology

Along the southern edge of the High Plains, water leaves the Ogallala formation and enters the Quaternary fill which underlies the Laguna Valley area. The saturated thickness of the sediments in the Quaternary fill of the Laguna Valley area ranges from about 15 to 30 feet, and water levels are approximately 30 feet below the land surface. The movement of groundwater in this area is primarily to the southeast. The depth to water in monitor well MW-1 is approximately 31' (TOC).

4.3 <u>Water Well Inventory</u>

A water well inventory will be performed to encompass a ¹/₂ mile radius around the facility. The inventory will include a review of water well records on the New Mexico Office of the State Engineer W.A.T.E.R.S. database and United States Geologic Survey (USGS) website. Any water wells denoted on the USGS 7.5 minute topographic quadrangle map within the search radius will be inspected.

5.0 SUBSURFACE SOILS

The soils in the vicinity of this site are of the Pyote soils and Dune land association. Typically, the surface layer is light-brown fine sand about 30 inches thick. The subsoil is fine sandy loam approximately 18 inches thick. The subsoil, to a depth of approximately 60 inches is pink fine sandy loam. The soil boring at this site indicated sand with some caliche stringers to a depth of approximately 40 feet.

6.0 **GROUNDWATER QUALITY**

6.1 Monitoring Program

The monitoring well has been sampled on a quarterly basis since October 2002. The most recent sampling was performed on June 21, 2005, and the data was submitted to the NMOCD most recently on January 14, 2005, in the Annual Ground Water Report. Quarterly sampling of this well and any additional well(s) will continue.

6.2 Hydrocarbons in Groundwater

To date, no hydrocarbon impact has been detected in MW-1, and as such is not considered a Constituent of Concern at this site.

6.3 Other Constituents of Concern

In the quarterly sampling events to date, the only constituent of concern observed was chloride, with concentrations ranging from 177 mg/L to 2,610 mg/L. Total dissolved solid concentrations have ranged from 751 mg/L to 5,600 mg/L.

7.0 STAGE I ABATEMENT PLAN

Highlander proposes to install soil borings in the vicinity of the leak, in order to further delineate the vertical and horizontal extent of vadose zone impact. Highlander also proposes to install two additional monitoring wells. The monitor wells will be placed appropriately to evaluate groundwater impact and hydraulic gradient. The monitor wells will be constructed according to EPA and industry standards.

Following installation, the wells will be developed either by bailing with a rig or hand bailer, or pumping with an electric submersible pump to remove fine grained sediment disturbed during drilling and to ensure collection of representative groundwater samples. Water removed from the well will be disposed of in the EME SWD System.

As part of the Stage I Abatement Plan, the residual impact to Vadose Zone soils will be evaluated by various methods to determine what, if any remediation/isolation techniques will be required at the Site.

The information will be evaluated and utilized to design a groundwater remedy if needed. The groundwater remedy that offers the greatest environmental benefit while causing the least environmental impairment will be selected. Such recommendations and findings will be presented to NMOCD in a subsequent Stage II Abatement Plan. When evaluating any proposed remedy or investigative work, ROC will confirm that there is a reasonable relationship between the benefits created by the proposed remedy or assessment and the economic and social costs.


8.0 QUALITY ASSURANCE/ QUALITY CONTROL

All monitor wells will be constructed to EPA and industry standards. All downhole equipment (i.e., drill rods, drill bits, etc.) will be thoroughly decontaminated between each use with a steam cleaner.

The wells will be inspected for the presence of phase-separated hydrocarbons (PSH) and, if present, a sample will be collected and analyzed by gas chromatography (GC) to determine composition and origin. The wells will be properly purged and sampled with clean, dedicated, polyethylene bailers and disposable line. The groundwater samples will be submitted to a laboratory for analysis of Benzene, Toluene, Ethylbenzene, and Xylene (BTEX) by method EPA 8021B, and chloride by method 300.0.

9.0 **PROPOSED SCHEDULE OF ACTIVITIES**

Upon approval, the work outlined above will be implemented in a timely manner, dependent upon availability of local drilling contractors. Quarterly sampling of the existing monitor well will be continued and all results will be submitted in an annual summary report within the first quarter of 2006.



Respectfully submitted, Highlander Environmental Corp.

Timothy M. Reed, P.G. Vice President



Rice Operating Company EME H-13 Monitor Well Lea County, New Mexico

H:O&G/23057MW Table 6-28-05

.

I.

i.

MW# Date			A CALL AND					- 「「「「「」」」」」」」」」」」」」」」」」」」」」」」」」」」」」」」」	本語の時間には、「大学の学びに、「たんたい」の語った。	
	Water	Depth	Volume	Purged	Chlorides	SAT	Benzene	Toluene	Ethylbenzene	Xylenes
10/29/2002	33.19	43.94	1.72	5.25	1770	5180	<0.001	<0.001	<0.001	<0.001
3/6/2003	33.18	43.90	1.71	5.10	2600	5340	<0.001	<0.001	<0.001	<0.001
5/29/2003	33.20	43.91	1.21	5.10	2360	5600	<0.001	<0.001	<0.001	<0.001
8/22/2003	33.40	43.90	1.68	5.04	2000	4700	<0.001	<0.001	<0.001	<0.001
11/19/2003	33.35	43.91	1.60	5.00	1600	4180	<0.001	<0.001	<0.001	0.001
2/18/2004	33.41	43.90	1.67	5.00	1500	3580	<0.002	<0.002	<0.002	<0.006
5/27/2004	33.56	43.90	1.65	5.00	$\begin{pmatrix} 777 \end{pmatrix}$	751	<0.001	<0.001	<0.001	<0.001
9/7/2004	33.4	44.10	1.71	5.14	1680	3510	<0.001	<0.001	<0.001	<0.001
11/24/2004	32.85	44.10	1.80	5.4	1590	3900	<0.001	<0.001	<0.001	<0.001
3/30/2005	32.19	44.10	1.91	25	1850	3890	<0.001	<0.001	<0.001	<0.001
6/21/2005	31.93	44.10	1.95	10	2610	5520	<0.001	<0.001	<0.001	<0.001


- -----


,


İ

MW-1 Chlorides vs TDS










PHOTOGRAPHS

and Same second and the second sec







RICE Operating Company

122 West Taylor • Hobbs, New Mexico 88240 Phone: (505)393-9174 • Fax: (505) 397-1471

July 11, 2002

Sylvia Dickey NMOCD Hobbs Office 1625 N. French Dr. Hobbs, NM 88240

Re: EME SWD System UL-H Sec 13 T20S R36E Lea County, New Mexico

Dear Ms. Sylvia Dickey:

Rice Operating Company (ROC) discovered an accidental discharge at the above referenced site on July 3, 2002. The soil settled underneath a 4" A/C system line causing it to break. 10 bbls were released out onto the pasture affecting 152 square feet. 5 bbls were recovered and hauled to an EME SWD disposal facility. ROC will delineate the site as well as develop a remediation plan.

ROC requests approval of this C-141 form as an initial report. If you have any questions, please do not hesitate to call me at the above number.

Sincerely,

Chris Collique

Chris Rodriguez C Environmental Technician

Enclosed: C-141 Initial Report Drawing Generic Spill and Leak Remediation Work Plan Sheet



District I P.O. Box 1980, Hobbs, NM 38241-1980 District II 811 South First, Artesia, NM 88210 District III 1000 Rio Brazos, Aztec, NM 87410 District IV 2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 2040 South Pacheco Santa Fe, NM 87505 OPERATOR'S MONTHLY REPORT

Form C-141 Originated 2/13/97

Submit 2 copies to Appropriate District Office in accordance with Rule 116 on back side of form

i.

]	Rel	ease Notification a		l Corrective A ATOR	ction	र ज	T (at a b	Denest C1	~~ 1 m
Name							Contact			mila	Report 🗆 I	Final Report
Rice Operat	ing Comp	any			_		Chris Rodrig	uez				
Address 122 West T	aylor			Н	obbs, NM 88240		Telephone No. 505-393-9174	4				······
Facility Name EME SWD	System				, <u>, , , , , , , , , , , , , , , , , , </u>		Facility Type System Line				·····	
					<u></u>						······	
Surface Owner		<u></u>	,	M	fineral Owner				Lease No.			
State			_								-	
					LOCATION (<u>.</u>	DELEVEE					
Unit Letter	Section	Township	Range		Feet from the		rth/South line	Feet	from the	Ea	st/West Line	County
Н	13	208	36E		1000' N Jct I-13							LEA
						E T	DET FASE					
Type of Release		<u> </u>	·		NATURE O	<u>r r</u>	Volume of Rele	ase			Volume Recover	ed.
Produced w							10 bbls				5 bbls	
Source of Relea							Date and Hour of				Date and Hour of	
4" A/C line								1:00 ar	n	'	7-3-02 11:	:00 am
Was Immediate	Notice Giver		Yes [X	No		If YES, To Who	om?				
By Whom?			105 1				Date and Hour					
Was a Watercou	urse Reached?	?	X	7			If YES, Volume	Impactio	ng the Water	course	ð.	
If a Watercours	e was Impacte				ditional Sheets If Neces	sarv	<u> </u>				10:00	
		,	.,)		/\$ ^{\$\$} **			
								, '	(13) (24)	Č.		
								<u> </u>	·	-1715 	<u></u>	·
					Attach Additional Sheets by 4" A/C line causing			یر در ۱۰ سب	· ,		(Fo) 3	;
		ken at the time		•				7	ri C	0005 CD	50 g	
									····	Ŭ.		
Describe Area A 152' square fe			Taken. (At	taci	Additional Sheets If Ne	eces	sary)					
•			ols and ha	ule	d it to an EME SWD o	disp	osal facility.			مر میں است		
Rice Operatin	g Company	will delineate	the site as	we	il as develop a remed	iati	on plan.					
					plete to the best of my kn							
• •					rform corrective actions for t relieve the operator of lia		-					•
contamination th	at pose a threa		. human hea	dth (or the environment. In add							
Signature:			ocal laws an	<u>u /0</u>			- <u>, , , , , , , , , , , , , , , , , , ,</u>	OIL CO	NSERVATI	2010	IVISION :	
A has	s t	du	· alla						-H	14	V Jerne	k
Printed Name: (- 7	773			('	pproved by istrict Supervisor:		U	0	<u> </u>	1
Title: Environm							nnroval Date:	6.03	ENVI	ROI	Extending Date	NGINEER
Date: July 3, 20	02				505 393-9174	Co	onditions of Appro		· ·		Attached 🛛	
					1					1		

DRILL	ING LOG	Site Name/Location	BOR	ING/WELL	INFORMA	TION	Logged by: Eac	des
RICE Oper	arting Company	H-13	Well No. SB-1/MW	Date Drilled: 9/2	25/02	Driller: Eades	Completion:	
122 V	lest Taylor	13-T20S-R36E	Well Depth:	Boring Depth: 4		Well Material:	Plugge	d
	w Mexico 88240	EME SWD System	Casing Length	Boring Diamete		Casing Size:	with	
) 393-9174	Lea County, NM	Screen Length:	Drilling Method:		Slot Size:	cutting	•
	, 000 0174	Lea county, min	L		uits (ppm)			з.
DEPTH	SUBSURI	FACE LITHOLOGY	SAMPLE TYPE	Cl	TPH	REMARKS	Boring	1
	Ground surface			Titrate	EPA 418.1			
5 6 7 8 9 10 11 12 13 14 15 16 17	Topsoil					cuttings		
21 22 23 24	Caliche Dry	Sand	Grab	1503		bentonite		
26 27 28 29			Grab	557		screen		
31 32 33 34 35 36 37 38 39 40			Grab	370		water		

|

. 1

i

!

|

}