

Received 7/21/2016

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | |
|---|----------------------------|
| Name of Company: Linn Energy | Contact: EL Gonzales |
| Address: 2130 W Bender, Hobbs, NM 88240 | Telephone No. 575-738-1739 |
| Facility Name: Skelly #247 | Facility Type: Oil |
| Surface Owner: Federal | Mineral Owner: Federal |
| API No. 30-015-28788 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|-----------|----------------|--------|
| N | 21 | 17S | 31E | 1110 | South | 2515 | West | Eddy |

Latitude: 32.8158761231942 Longitude: -103.875077780113

NATURE OF RELEASE

| | | |
|--|---|--|
| Type of Release: Produced Water | Volume of Release: 30 gal | Volume Recovered: 0 gal |
| Source of Release: Pipeline | Date and Hour of Occurrence 06/04/2012 7:00 am | Date and Hour of Discovery 06/04/2012 7:30 am |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? M. Bratcher – NMOCD; Terry Gregston – BLM | |
| By Whom? Joe Hernandez | Date and Hour: 06/04/2012 1:30 pm | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Injection header north of SU #247, 3" steel line had pin-hole spray 30"x20" on ground. Shut in header to stop and repair leak. Pin hole caused by corrosion.

Describe Area Affected and Cleanup Action Taken.

The contaminated soil was removed from the site and properly disposed of at a NMOCD approved facility. The excavation was backfilled with clean, imported soil to ground surface and contoured to the surrounding area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | |
|--|---------------------------------------|-----------------------------------|
| Signature:  | <u>OIL CONSERVATION DIVISION</u> | |
| Printed Name: EL Gonzales | Approved by Environmental Specialist: | |
| Title: Production Supervisor | Approval Date: 7/25/2016 | Expiration Date: N/A |
| E-mail Address: elgonzales@linenergy.com | Conditions of Approval: | Attached <input type="checkbox"/> |
| Date: 7/21/2016 Phone: 575-504-8002 | FINAL | |

* Attach Additional Sheets If Necessary

2RP-1188