

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/18/2017
NMOCD Dist 2

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW1321853027

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Matador Resources	Contact Casey Snow
Address 500 N Main St Suite 1 Roswell NM 88201	Telephone No. (972) 371-5439
Facility Name Salt Draw 11 Fed Com #1	Facility Type Tank Battery

Surface Owner BLM	Mineral Owner BLM	API No. 30-15-23692
-------------------	-------------------	---------------------

LOCATION OF RELEASE

Unit Letter G	Section 11	Township 25S	Range 28E	Feet from the 1880	North/South Line North	Feet from the 1980	East/West Line EAST	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32° 8'46.05"N Longitude 104° 3'23.75"W

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 252 bbls	Volume Recovered 71
Source of Release Oil Tank	Date and Hour of Occurrence 7-31-2013 est 3 am	Date and Hour of Discovery 7-31-2013 9 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NM OCD Artesia District Office; BLM Carlsbad Field Office	
By Whom? Rickie Anguiano	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*



Cause: A bull plug in a 1" threaded connection near the bottom of the tank failed.

Remedial Action: Shut down pumping unit immediately. Leaking tank was taken out of service. Repair or replacement to be determined.

Describe Area Affected and Cleanup Action Taken.*

All work completed as OCD guidance. Back fill request was approved by OCD on 2-18-2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Casey Snow		Approved by Environmental Specialist: 	
Title: Manager Regulatory, Environmental, & Safety		Approval Date: 8/21/17	Expiration Date: N/A
E-mail Address: csnow@matadorresources.com		Conditions of Approval:	
Date: August 2, 2017, 2017 Phone: (972) 371-5439		Like Approval from BLM	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-1791