From:	Weaver, Crystal, EMNRD
То:	"Sheldon Hitchcock"; Bratcher, Mike, EMNRD
Cc:	Franklin, Melvin; rcox@bridgergroup.com; David Adkins
Subject:	RE: Bridger Group: Cedar Canyon 22 CTB Initial C-141
Date:	Tuesday, August 1, 2017 10:00:00 AM
Attachments:	1. 4274 - COAs and signed C-141 Initial.pdf
	image001.png

RE: Bridger Logistics \* (OXY location) Cedar Canyon 22 CTB \* Fab1718140445 \* 2RP-4274

Melvin and Sheldon,

Sorry for the delay on this one. It and quite a few others had been misplaced. I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4274. Considering the delay OCD will accept release characterization work plans 15 days from today's date.

Thank you,

## **Crystal Weaver**

Environmental Specialist OCD – Artesia District II 811 S. 1<sup>st</sup> Street Artesia, NM 88210 Office: 575-748-1283 ext. 101 Cell: 575-840-5963 Fax: 575-748-9720

From: Sheldon Hitchcock [mailto:slhitchcock@talonlpe.com]
Sent: Tuesday, June 27, 2017 12:05 PM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD
<mike.bratcher@state.nm.us>
Cc: Franklin, Melvin <mfranklin@bridgergroup.com>; rcox@bridgergroup.com; David Adkins
<dadkins@talonlpe.com>
Subject: Bridger Group: Cedar Canyon 22 CTB Initial C-141

Crystal,

Bridger had a release of approximately 12bbls of oil on the Oxy Cedar Canyon 22 CTB location. The initial C-141 with all of the details is attached. We have initiated remedial activities as part of the emergency response. I will provide a closure report describing remedial actions and confirmation soil sampling when the project is complete. Please let me know if you have any questions.

Respectfully,

Sheldon Hitchcock

Project Manager Office: 575.746.8768 Direct: 575.616.4021 Cell: 575.689.5198 Fax: 575.746.8905 Emergency: 866.742.0742 Web: <u>www.talonlpe.com</u>

