

Bratcher, Mike, EMNRD

From: DeLeon, Josepha <JDXD@chevron.com>
Sent: Thursday, October 26, 2017 3:25 PM
To: Bratcher, Mike, EMNRD
Subject: RE: Rustler Bluff 33 Spill
Attachments: Rustler Buff.jpg

Mike, I am going through open RP's and Cliff Brunson has submitted a workplan for this area. I realized I never sent the correct picture to you. Attached is the picture and we submitted a revised C141. Can you advise if RP is still required?

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Thursday, March 02, 2017 10:03 AM
To: DeLeon, Josepha <JDXD@chevron.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: [**EXTERNAL**] RE: Rustler Bluff 33 Spill

Yes, please revise the C-141. There should at least be an estimate of volume recovered. If fluid hits the ground, 100% recovery is not likely.

Thanks,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia NM 88210
575-748-1283 Ext 108
mike.bratcher@state.nm.us

From: DeLeon, Josepha [mailto:JDXD@chevron.com]
Sent: Thursday, March 2, 2017 9:46 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: RE: Rustler Bluff 33 Spill

Mike, Eli (our Production Supervisor in Carlsbad) is obtaining a picture for you. The containment is a unlined berm. He contacted Cliff Brunson with BBC for remediation.

He relayed this message.

From: Barakat, Eli
Sent: Thursday, March 02, 2017 8:44 AM
To: DeLeon, Josepha <JDxD@chevron.com>
Subject: RE: Rustler Bluff 33 Spill

I will get you a pic, I understand his concern, there was no way to estimate what was sucked in the ground without taking sample

The vacuum truck is not accurate to be able to tell. You can estimate up to the 10th barrel in a 125 vac truck.

If you want to send him my response and I am more than happy to provide any more info.

Thanks!

Eli Barakat
Production Supervisor

Carlsbad Production Team
MCBU - CNAEP
3150 East Greene Street
Carlsbad, New Mexico
Cell (575) 602-2995

Do you think we need to revise "Recovered" amount to allow for saturation??

Let me know if you need more information. As soon as I get the picture, I will forward on. Thank you.

*Josie DeLeon, HES Specialist -
Compliance Support - Environmental*

Chevron - MCBU
(New Mexico, East Texas and Ft. Stockton Areas)

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

jdxd@chevron.com

<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red – The Doing Thinker

From: Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]

Sent: Thursday, March 02, 2017 8:37 AM

To: DeLeon, Josepha <JDxD@chevron.com>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: [**EXTERNAL**] RE: Rustler Bluff 33 Spill

Josie,

The C-141 indicates the release was in a containment with all fluid recovered. I am not familiar with a containment for the well head area (stuffing box leak) that would hold this volume. If you would, please possibly have one of your field personnel take a photo of the containment and send to me. We may be able to enter this C-141 as Initial/Final and save us all some paperwork.

Thank you,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia NM 88210
575-748-1283 Ext 108
mike.bratcher@state.nm.us

From: DeLeon, Josepha [<mailto:JDxD@chevron.com>]
Sent: Wednesday, March 1, 2017 2:59 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: FW: Rustler Bluff 33 Spill

Attached is the C141 for the Rustler Bluff spill.

*Josie DeLeon, HES Specialist -
Compliance Support - Environmental*

Chevron - MCBU
(New Mexico, East Texas and Ft. Stockton Areas)
1616 W. Bender Blvd.
Hobbs, NM 88240
575-263-0424
432-425-1528 - cell
jdxd@chevron.com
<https://www.chevroncontractorsafety.com/contractormcbu/> - CHESM Contractor Website



Green/Red – The Doing Thinker