



LT Environmental, Inc.
3300 North A Street, Building 1, #103
Midland, Texas 79705
T 432.704.5178

December 23, 2019

Mr. Jim Raley
Environmental Specialist
WPX Energy Permian, LLC
5315 Buena Vista Drive
Carlsbad, New Mexico 88220

**RE: Containment Liner Inspection
2RP-5681
Tucker Draw 9 4 Federal Com #001H
Eddy County, New Mexico**

Dear Mr. Raley:

LT Environmental, Inc. (LTE) is pleased to present the following letter report to WPX Energy Production, LLC (WPX) summarizing the response efforts and liner inspection associated with a produced water release at the Tucker Draw 9 4 Federal Com #001H well pad. On September 29, 2019, a leak developed in a produced water flowline, resulting in approximately 150 barrels (bbls) of fluids being released onto the fully lined containment area. All fluids were contained and recovered immediately. WPX reported the release to the New Mexico Oil Conservation Division (NMOCD) on a Release Notification and Corrective Action Form C-141 on October 9, 2019, and was subsequently assigned Remediation Permit (RP) Number 2RP-5681.

On November 14, 2019, LTE personnel competent in the inspection of on-site equipment and facilities visited the site to visually inspect the liner. Prior to conducting the liner inspection, the NMOCD was provided a 48-hour notice of planned activities. LTE verified that there was no visual evidence of a breach in the liner. Photographs taken during the liner inspection are included as an attachment.

If you have any questions or comments, please do not hesitate to contact Chris McKisson at (970) 285-9985 or cmckisson@ltenv.com.

Sincerely,
LT ENVIRONMENTAL, INC.

A handwritten signature in black ink, appearing to read 'Chris McKisson'.

Chris McKisson
Project Environmental Scientist

A handwritten signature in black ink, appearing to read 'Ashley L. Ager'.

Ashley L. Ager, M.S., P.G.
Senior Geologist

Attachments:

Attachment 1 – Photographic Log



ATTACHMENT 1: PHOTOGRAPHIC LOG




PHOTOGRAPHIC LOG



Photograph 1: View east of liner.



Photograph 2: View west of liner.



Photograph 3: View northeast of liner.



Photograph 4: Cleaned liner.

