**Photo Number:** 

1

**Photo Direction:** 

West

**Photo Description:** 

View of the Initial Release.



**Photo Number:** 

2

**Photo Direction:** 

West

**Photo Description:** 

View of the affected pipeline and surface staining from the initial release.



**Photo Number:** 

3

**Photo Direction:** 

North

**Photo Description:** 

View of Excavation Activities.



**Photo Number:** 

4

**Photo Direction:** 

Southwest

**Photo Description:** 

View of Excavation Activities.



**Photo Number:** 

5

**Photo Direction:** 

North

**Photo Description:** 

View of Excavation Activities.



**Photo Number:** 

6

**Photo Direction:** 

Northwest

**Photo Description:** 

View of Excavation Activities.



**Photo Number:** 

7

**Photo Direction:** West-Northwest

Photo Description:

View of Excavation Activities.



**Photo Number:** 

8

**Photo Direction:** 

West

### **Photo Description:**

View of portion of the excavated area and impacts remaining insitu beneath High Pressure Buried Pipeline.

