



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Oil Conservation Division

*Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"*

29-Mar-04

MERIT ENERGY CO

12222 MERIT DR

STE 1500

DALLAS TX 75251-0000

**NOTICE OF VIOLATION and SHUT-IN DIRECTIVE
Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

J L KEEL A No.014

30-015-05102-00-00

Active Injection - (All Types)

1-7-17S-31E

Test Date: 3/22/2004 2:18:45 PM

Permitted Injection PSI:

Actual PSI: 1550

Test Reason: Annual IMIT

Test Result: F

Repair Due: 6/25/2004

Test Type: Bradenhead Test

FAIL TYPE: Tubing

FAIL CAUSE:

Comments on MIT: Continuous blow on surface casing valve.

HUDSON FEDERAL No.001

30-015-05208-00-00

Active Injection - (All Types)

A-18-17S-31E

Test Date: 3/22/2004 1:25:41 PM

Permitted Injection PSI:

Actual PSI: 1800

Test Reason: Annual IMIT

Test Result: F

Repair Due: 6/25/2004

Test Type: Bradenhead Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Comments on MIT: Well is overpressured

TURNER A No.003

30-015-05211-00-00

Active Injection - (All Types)

K-18-17S-31E

Test Date: 3/22/2004 12:37:27 PM

Permitted Injection PSI:

Actual PSI: 1750

Test Reason: Annual IMIT

Test Result: F

Repair Due: 6/25/2004

Test Type: Bradenhead Test

FAIL TYPE: Permit Violation

FAIL CAUSE:

Comments on MIT: Well is overpressured

TURNER A No.011

		Active Injection - (All Types)	30-015-05215-00-00
			P-18-17S-31E
Test Date:	3/22/2004 11:02:13 AM	Permitted Injection PSI:	Actual PSI: 1750
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured		

C A RUSSELL No.006

		Active Injection - (All Types)	30-015-05219-00-00
			C-18-17S-31E
Test Date:	3/22/2004 1:01:26 PM	Permitted Injection PSI:	Actual PSI: 1800
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured		

C A RUSSELL No.008

		Active Injection - (All Types)	30-015-05221-00-00
			G-18-17S-31E
Test Date:	3/22/2004 1:37:07 PM	Permitted Injection PSI:	Actual PSI: 1800
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured		

C A RUSSELL No.009

		Active Injection - (All Types)	30-015-05222-00-00
			B-18-17S-31E
Test Date:	3/22/2004 1:14:58 PM	Permitted Injection PSI:	Actual PSI: 1750
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured		

TURNER A No.012

		Active Injection - (All Types)	30-015-05238-00-00
			A-19-17S-31E
Test Date:	3/22/2004 11:05:48 AM	Permitted Injection PSI:	Actual PSI: 1750
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured		

TURNER A No.014

		Active Injection - (All Types)	30-015-05239-00-00
			2-19-17S-31E
Test Date:	3/22/2004 11:15:44 AM	Permitted Injection PSI:	Actual PSI: 1800
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Over pressure limit		

FREN OIL COMPANY No.013

		Active Injection - (All Types)	30-015-05261-00-00
			P-19-17S-31E
Test Date:	3/22/2004 9:29:15 AM	Permitted Injection PSI:	Actual PSI: 1980
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured		

TURNER B No.054

		Active Injection - (All Types)	30-015-05443-00-00
			F-29-17S-31E
Test Date:	3/22/2004 10:15:48 AM	Permitted Injection PSI:	Actual PSI: 1800
Test Reason:	Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type:	Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT:	Well is overpressured		

TURNER B No.059**30-015-05446-00-00**

A-29-17S-31E

Test Date:	3/22/2004 10:24:09 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1900
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT:	Well is overpressured				

TURNER B No.068**30-015-05452-00-00**

P-29-17S-31E

Test Date:	3/22/2004 9:58:48 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1100
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Casing	FAIL CAUSE:	
Comments on MIT:	SHUT-IN. Continuous blow on int casing valve.				

TURNER B No.048**30-015-05458-00-00**

C-29-17S-31E

Test Date:	3/22/2004 10:30:49 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1900
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT:	Over Pressure				

MAX FRIESS MA No.001**30-015-05459-00-00**

B-30-17S-31E

Test Date:	3/22/2004 9:34:30 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1900
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT:	Well is overpressured				

MAX FRIESS MA No.002**30-015-05469-00-00**

A-30-17S-31E

Test Date:	3/22/2004 10:39:23 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1750
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT:	Over Pressure Limit.				

TURNER B No.053**30-015-05472-00-00**

I-30-17S-31E

Test Date:	3/22/2004 9:47:50 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1825
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT:	Well is overpressured				

TURNER A No.035**30-015-20097-00-00**

H-19-17S-31E

Test Date:	3/22/2004 10:52:30 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1750
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT:	Well is overpressured				

TURNER A No.036**30-015-20098-00-00**

G-19-17S-31E

Test Date:	3/22/2004 10:54:48 AM	Active Injection - (All Types)	Permitted Injection PSI:	Actual PSI:	1900
Test Reason:	Annual IMIT		Test Result:	Repair Due:	6/25/2004
Test Type:	Bradenhead Test		FAIL TYPE: Permit Violation	FAIL CAUSE:	
Comments on MIT:	Well is overpressured				

C A RUSSELL No.011**30-015-21258-00-00**

C-18-17S-31E

Test Date: 3/22/2004 1:10:00 PM	Active Injection - (All Types) Permitted Injection PSI:	Actual PSI: 1800
Test Reason: Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type: Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT: Well is overpressured		

HUDSON FEDERAL No.006**30-015-26008-00-00**

H-18-17S-31E

Test Date: 3/22/2004 1:19:48 PM	Active Injection - (All Types) Permitted Injection PSI:	Actual PSI: 1950
Test Reason: Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type: Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT: Well is overpressured		

HUDSON FEDERAL No.009**30-015-28790-00-00**

H-18-17S-31E

Test Date: 3/22/2004 1:31:11 PM	Active Injection - (All Types) Permitted Injection PSI:	Actual PSI: 1650
Test Reason: Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type: Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT: Well is overpressured		

TURNER A No.057**30-015-29000-00-00**

C-19-17S-31E

Test Date: 3/22/2004 12:49:57 PM	Active Injection - (All Types) Permitted Injection PSI:	Actual PSI: 1770
Test Reason: Annual IMIT	Test Result: F	Repair Due: 6/25/2004
Test Type: Bradenhead Test	FAIL TYPE: Permit Violation	FAIL CAUSE:
Comments on MIT: Well is overpressured		

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,



Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.