Form 3160-5 (August 1999)

N.M. Oil Cons. DIV-Dist, 2

UNITED STATES 1301 W. Grand Avenue OMB N Expires

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT 1951a, NM 88210

5. Lease Serial No.

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS						4	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SÜBMIT IN TRI	PLICATE - Other instru	tions on re	verse side		7. If Unit or C	CA/Agreement, Nam	e and/or No.
	Other				8. Well Name		
Name of Operator Chesapeake Operating, Inc.					Benson Shugart Waterflood Unit 28		
3a. Address		3b. Phone No. (include Preside IVED		30-015-04547			
 P. O. Box 11050 Midland TX 79702-8050 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 		(432)685-4310 AUG 1 7 2004		10. Field and Pool, or Exploratory Area Shugart-Yates-SR-Q-GR			
330' FSL & 330' FEL, Secti	SIND MATERIA			11. County or Parish, State Eddy New Mexico			
12. CHECK AP	PROPRIATE BOX(ES) TO	INDICATE:	NATURE O	F NOTICE, RI	EPORT, OR	OTHER DATA	
TYPE OF SUBMISSION			TYPE O	F ACTION			
X Notice of Intent	☐ Acidize	☐ Deepen		Production (Start	-	☐ Water Shut-Off	
☐ Subsequent Report	☐ Alter Casing ☐ Casing Repair	☐ Fracture Tre	_	Reclamation Recomplete	[[☐ Well Integrity ☐ Other	
☐ Final Abandonment Notice	Change Plans	☐ Plug and Al		Temporarily Aba	ndon		
That Abandonnent Notice	Convert to Injection	☐ Plug Back		Water Disposal			
Attach the Bond under which the following completion of the inv	ectionally or recomplete horizontal he work will be performed or prov- rolved operations. If the operation hal Abandonment Notices shall be by for final inspection.)	ide the Bond No. results in a multip	on file with BL	M/BIA. Required or recompletion in	subsequent repo	orts shall be filed wit a Form 3160-4 shall	thin 30 days be filed once
Chesapeake, respectfully, plan to P&A the well as so		attached plu	g and aban	donment prod	cedure and v	wellbore diagra	m. We
APPROVAL SUBJ GENERAL REQUI SPECIAL STIPUL				Accepted fo	r record - N	MOCD	
I hereby certify that the foregoing is true and correct Name (Printed/Typed) Brenda Coffman			Title Regulatory Analyst				
Signature Coloman			Date 08/11/2004				
	THIS SPACE F	OR FEDERAL	ORSTATE	OFFICE USE		949 14 31	
Approved by (ORIG. S	GD.) ALEXIS C. SWOBO	DA	PEFF	ROLEUM EN	IGINEER*	* AUG 1	3 2004
Conditions of approval, if any are	attached. Approval of this notic	e does not warra	nt or Office				

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or

(Instructions on reverse)

certify that the applicant holds legal or equitable title to those rights in the subject lease

fraudulent statements or representations as to any matter within its jurisdiction.

which would entitle the applicant to conduct operations thereon.

BSWU 28

Plug and Abandonment Procedure Eddy County, NM

- 1. File Form C-103.
- 2. Notify the Artesia office of the NM OCD and the Carlsbad office of the BLM 24 hours prior to commencing P&A operations.
- 3. MIRU. POOH w/4 jts 2 3/8" TBG.
- 4. RIH with PKR and 2 3/8" TBG to 1611' and tag 2 3/8" TBG left in hole.
- 5. Pull up 50' and circulate w/9.5# brine and 25# of gel per barrel. (Min. viscosity of 40 cp.)
- 6. Pull up to 1550' and set PKR.
- 7. Bullhead 108 sx CMT to bottom to isolate perfs and Yates/Seven Rivers. Pull up 10'. WOC and tag plug.
- 8. POOH w/PKR.
- 9. RIH w/perf gun and perf from 775' 785' (4 SPF).
- 10. POOH w/perf gun.
- 11. RIH w/CMT retainer and 2 3/8" TBG. Set CMT retainer at 805'.
- 12. POOH w/TBG.
- 13. RIH w/PKR to 755' and SQZ 6 sx CMT and bail 6 sx CMT onto retainer. (12 sx CMT total.) Pull up 10'. WOC and tag plug.
- 14. POOH w/2 3/8" TBG and PKR.
- 15. RIH w/perf gun and perf from 28' 38'. (4 SPF.)
- 16. POOH w/perf gun.
- 17. RIH w/CMT retainer and 2 3/8" TBG. Set CMT retainer at 63'.
- 18. POOH w/TBG.
- 19. RIH w/PKR to 3' and SQZ 3 sx CMT and bail 7 sx CMT onto retainer. (10 sx CMT total.) POOH. Wellbore should remain full for at least 30 minutes.
- 20. RDMO. Cut off all CSG 3' below ground level. Weld on ID plate and make requisite surface restorations.

Proposed Wellbore Diagram Post-P&A Chesapeake Operating, Inc.

Well: Benson Shugart WFU #28

Location: 330' FSL & 330' FEL, Unit P, Sec. 25-18S-30E (SE 1/4 of SE 1/4 of 25-18S-30E)

County: Eddy

State: NM

Field: Shugart (Yates-Seven Rivers-Queen-Grayburg)


Elevation: 3559' DF

Federal Lease #: NMNM01375A

API#: 30-015-04547 Spud Date: 08/10/1961

Completion Date: 09/01/1961

Unit #: NMNM88499X



Prepared By: Robert S. Crews Phone: (505) 391-1462 Ext. 11

Date:

07/27/2004