

Submit 3 Copies To Appropriate District State of New Mexico Office	Form C-103			
District I Energy, Minerals and Natural Resources	June 19, 2008			
1625 N French Dr., Hobbs, NM 88240	WELL API NO.			
District II 1301 W. Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION	30-015-02637 5. Indicate Type of Lease			
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE S FEE			
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. E-7179			
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Donnelly Kelly State			
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other	8. Well Number 1			
2. Name of Operator	9. OGRID Number			
Alamo Permian Resources, LLC	274841 10. Pool name or Wildcat			
3. Address of Operator 415 W. Wall St., Suite 500 Midland, TX 79701	Artesia: QN-GB-SA			
4. Well Location				
	980 feet from the East line			
Section 8 Township 18S Range 28E 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Eddy County			
3623' DF				
E such a property consistency and adjustment of the such and the such as the such				
12. Check Appropriate Box to Indicate Nature of Notice	, Report or Other Data			
NOTICE OF INTENTION TO: SUE	SSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	RK ALTERING CASING			
TEMPORARILY ABANDON	RILLING OPNS. P AND A			
PULL OR ALTER CASING	OCD 24			
DOWNHOLE COMMINGLE To One 24 hrs				
OTHER: RE-enter and Plug & Abandon OTHER: \(\)	Work done			
OTHER: RE-enter and Plug & Abandon OTHER: OTHER: OTHER:	SEE ATTACHED			
of starting any proposed work). See ROLE 1103. For Multiple Completions.	RILLING OPNS. PAND A DION OF SEE ATTACHED			
OTHER: RE-enter and Plug & Abandon 13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: or recompletion. Well originally plugged 05/16/1957	CONDITIONS OF			
or recompletion. Well originally plugged 05/16/1957				
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well:	CONDITIONS OF APPROVAL			
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface center and Re-Plug & Abandon well:	CONDITIONS OF APPROVAL			
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface center and clean out well by drilling out surface cement plug; drilling Re-enter 8-5/8" casing (cut-off at 260"); circ out mud in 6-3/4" open	CONDITIONS OF APPROVAL nent plug ll out 10 sx cement plug from +/-250'-278';			
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface center and clean out well by drilling out surface cement plug; drilling Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800'	CONDITIONS OF APPROVAL nent plug ll out 10 sx cement plug from +/-250'-278';			
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface center and clean out well by drilling out surface cement plug; drilling Re-enter 8-5/8" casing (cut-off at 260"); circ out mud in 6-3/4" open	APPROVAL nent plug ll out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450'			
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cer 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug	CONDITIONS OF APPROVAL nent plug il out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED			
Or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cere. 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open. 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug. 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug. 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @	CONDITIONS OF APPROVAL nent plug ll out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED			
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cer 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug	conditions of APPROVAL nent plug lout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cent. 2. Re-enter and clean out well by drilling out surface cement plug; drilling Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open. 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug. 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug. 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug. 9. Set final 175 sx cement plug from 260' to surface. 10. Set P & A marker.	CONDITIONS OF APPROVAL nent plug il out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED			
or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface center and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260"); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450" to 1800" 4. WOC & tag plug 5. Spot 160 sx cement plug from 900" to 450" 6. WOC & tag plug 7. Spot 65 sx cement plug from 310" to 210" (over 8-5/8" casing stub @ 8. WOC & tag plug 9. Set final 175 sx cement plug from 260" to surface	conditions of APPROVAL nent plug lout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cere. 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260"); circ out mud in 6-3/4" open. 3. Spot 250 sx cement plug from 2450" to 1800" 4. WOC & tag plug. 5. Spot 160 sx cement plug from 900" to 450" 6. WOC & tag plug. 7. Spot 65 sx cement plug from 310" to 210" (over 8-5/8" casing stub @ 8. WOC & tag plug. 9. Set final 175 sx cement plug from 260" to surface. 10. Set P & A marker. 11. Clean & restore location.	conditions of APPROVAL ment plug flout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011 NMOCD ARTESIA			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cere. 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260"); circ out mud in 6-3/4" open. 3. Spot 250 sx cement plug from 2450" to 1800" 4. WOC & tag plug. 5. Spot 160 sx cement plug from 900" to 450" 6. WOC & tag plug. 7. Spot 65 sx cement plug from 310" to 210" (over 8-5/8" casing stub @ 8. WOC & tag plug. 9. Set final 175 sx cement plug from 260" to surface. 10. Set P & A marker. 11. Clean & restore location.	conditions of APPROVAL nent plug lout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface center and Re-enter and clean out well by drilling out surface cement plug; drill Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug 9. Set final 175 sx cement plug from 260' to surface 10. Set P & A marker 11. Clean & restore location	conditions of APPROVAL ment plug flout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011 NMOCD ARTESIA			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cer 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug 9. Set final 175 sx cement plug from 260' to surface 10. Set P & A marker 11. Clean & restore location Spud Date: Rig Release Date:	conditions of APPROVAL nent plug ll out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011 NMOCD ARTESIA			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface center and Re-enter and clean out well by drilling out surface cement plug; drill Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug 9. Set final 175 sx cement plug from 260' to surface 10. Set P & A marker 11. Clean & restore location	conditions of APPROVAL nent plug ll out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011 NMOCD ARTESIA			
Or recompletion. Well originally plugged 05/16/1957 Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cer 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug 9. Set final 175 sx cement plug from 260' to surface 10. Set P & A marker 11. Clean & restore location Spud Date: O4/16/1957 Rig Release Date:	conditions of APPROVAL nent plug ll out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED JUN 2 2 2011 NMOCD ARTESIA			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cer 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug 9. Set final 175 sx cement plug from 260' to surface 10. Set P & A marker 11. Clean & restore location Spud Date: Rig Release Date:	conditions of APPROVAL nent plug lout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cere. 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open. 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug. 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug. 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug. 9. Set final 175 sx cement plug from 260' to surface. 10. Set P & A marker. 11. Clean & restore location. Spud Date: O4/16/1957 Rig Release Date: TITLE Regulatory Affairs Coc.	CONDITIONS OF APPROVAL nent plug out 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cere. 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open. 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug. 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug. 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug. 9. Set final 175 sx cement plug from 260' to surface. 10. Set P & A marker. 11. Clean & restore location. Spud Date: O4/16/1957 Rig Release Date: TITLE Regulatory Affairs Coc. Type or print name. Joanne Keating. E-mail address: ikeating@alan.	CONDITIONS OF APPROVAL nent plug lout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED			
Proposed plan to attempt to re-enter and Re-Plug & Abandon well: 1. Locate P&A marker for the subject well and dig around surface cere. 2. Re-enter and clean out well by drilling out surface cement plug; dril Re-enter 8-5/8" casing (cut-off at 260'); circ out mud in 6-3/4" open. 3. Spot 250 sx cement plug from 2450' to 1800' 4. WOC & tag plug. 5. Spot 160 sx cement plug from 900' to 450' 6. WOC & tag plug. 7. Spot 65 sx cement plug from 310' to 210' (over 8-5/8" casing stub @ 8. WOC & tag plug. 9. Set final 175 sx cement plug from 260' to surface. 10. Set P & A marker. 11. Clean & restore location. Spud Date: O4/16/1957 Rig Release Date: TITLE Regulatory Affairs Coc.	CONDITIONS OF APPROVAL nent plug lout 10 sx cement plug from +/-250'-278'; hole to top of 10 sx cement plug at +/-2450' RECEIVED			



NOTE: All plugs will be tagged before setting the next plug.

	175 sx
	65 sx
	160 sx
	250 sx
total	650 sx

PROPOSED RE-PLUG WELL



Existing P & A Well condition

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 1301 W. GRAND AVENUE ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator:	Alamo	Permia	n Resour	a-s, LLC
Well Nam	e & Number:	Donne	114 K.114	51. #/
	30-0			

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- **4.** A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 5. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- **6.** Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

DG

Date: 6-23-2011



June 21, 2011

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 811 S. First St. Artesia, NM 88210

Certified Mail 7009 2250 0000 0594 1152

TRANSMITTAL

Dear Sirs:

Please find enclosed the NMOCD Form C-103 for the following well:

Donnelly Kelly State #1 - Re-entry & Re-P&A

Do not hesitate to contact me for further information or needed data at the following 432.897.0673, ext. 16.

Sincerely;

Joanne Keating

Regulatory Affairs Coordinator

Enclosures

RECEIVED

JUN 22 2011

NMOCD ARTESIA