<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

					iiiii i	0, 1111 073	03						_	
Release Notification and Corrective Action														
		OPERA	ΓOR		☐ Initia	ıl Report		Final Repo	rt					
Name of Co	ompany De	Contact Tracy Kidd												
Address PC		Telephone No. 575.513.0628												
Facility Na		Facility Type Oil Well												
Surface Ow														
				Mineral C	N OF RE	TEASTE								
Unit Letter	Section	Township	Range	Feet from the		h/South Line	Feet from the	Fast	/West Line	County				
B 34 24S 31E 330						North	1980	Lust	East Eddy					
Latitude: 32.180117040773 Longitude: 103.763554613439														
NATURE OF RELEASE														
Type of Rele	ase Spill	Volume of Release 60bbls Volume Recovered 50bbls												
Source of Re	lease mecha	Date and Hour of Occurrence Date and Hour of Discovery 11/16/20 9:49PM						11/16/2013,						
Was Immedi	ate Notice (If YES, To Whom? Tracy Kidd- Production Foreman												
By Whom? C	Chris McCu	Date and Hour 11/16/2013												
Was a Water		If YES, Volume Impacting the Watercourse. N/A												
If a Watercon	urse was Im	pacted, Descr	ibe Fully.*	k									_	
If a Watercourse was Impacted, Describe Fully.* N/A														
		em and Reme												
Gasket rupture on fire tube in heater treater caused oil spray. RW Trucking recovered 50bbls of oil and soil samples will be taken. Gasket was replaced on														
heater treater. Oil spill remained on location. RW Trucking recovered 50bbls and soil sampling will be done.														
Describe Area Affected and Cleanup Action Taken.*														
Talon/LPE had been contracted to perform the remedial actions. The impacted areas in the vicinity of sample locations S-1 and S-2, under the														
separators, heater treaters, were hand-excavated to the best extent as reasonable, feasible and as safely as possible. The current and														
historical areas were then treated with mircoblaze as a bioremediation agent. The impacted area in the vicinity of sample location S-3 was														
excavated to a depth of 1.5-feet deep. A confirmation sample was taken and the results were within the RRAL's (see below). The														
1	impacted soil was transported to Lea Land, LLC. The excavated area at S-3 was backfilled using new material from a local borrow pit and re-contoured to match the surrounding location. No further action is required.													
re-contoure	d to match	the surround	ding loca	tion. No further	action	n is required.								
T h anabyr a ant	Grathat tha	information of	tron abarra	e is true and comp	loto to	the best of my	len aveladas an	Lundovat	and that name	uent to NIM	OCD *	ulas and	-	
				nd/or file certain r										
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health														
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other														
federal, state	, or local la	ws and/or regu	ulations.											
							OIL CONSERVATION DIVISION							
Signature: S	andra:													
Printed Nam	e: Sandra I	Approved by Environmental Specialist:												
Title: Field	Admin Sup		Approval Da	te: 8/29/	2014	4 Expiration Date: NA								
		.Farley@dvr	ı.com			Conditions o								
						Attached								
Date: 8/27/2	2014	Final												

^{*} Attach Additional Sheets If Necessary