

**From:** [Blevins, Bradley](#)  
**To:** [Bratcher, Mike, EMNRD](#); [Patterson, Heather, EMNRD](#)  
**Cc:** [Blevins, Bradley](#)  
**Subject:** FW: Initial C-141 2RP-3199  
**Date:** Wednesday, August 26, 2015 10:11:00 AM  
**Attachments:** [doc04529720150826090644.pdf](#)

---

Mike, Heather

Please find the correct C-141 for the PLU 105 flowline release. I made reference in the C-141 to the miss communication as to 84/105 release notification. If you need further info please let me know.

Thank you.

---

**From:** Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]  
**Sent:** Monday, August 24, 2015 2:37 PM  
**To:** Blevins, Bradley; Patterson, Heather, EMNRD  
**Subject:** RE: Initial C-141 2RP-3199

Brad,

Just send a new Initial C-141 with some mention of the current 2RP-3199 sent in error, and we can fix the rest on our end, or you can send a Final C-141 for the 84 and an Initial for the 105.

**Mike Bratcher**  
**NMOCD District 2**  
**811 S. First Street**  
**Artesia, NM 88210**  
**O: 575-748-1283 X108**  
**C: 575-626-0857**  
**F: 575-748-9720**

---

**From:** Blevins, Bradley [<mailto:BBlevins@BassPet.Com>]  
**Sent:** Monday, August 24, 2015 1:16 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD  
**Cc:** Blevins, Bradley  
**Subject:** Initial C-141 2RP-3199

Mike, Heather

Upon further investigation the PLU 84 was not the line that leaked. The PLU 105 was the actual well that had the flowline fail. These lines are buried and the pumper turned in the wrong well, Do I need to file an additional C-141 or can changes be made to the original? Thank you.

API for the PLU 105 is 3001527895

Brad Blevins  
Remediation Foreman (PLU)  
BOPCO, LP  
522 W. Mermod, Suite 704  
Carlsbad, NM 88220  
Office-575-887-7329  
Cell-1-432-214-3704  
[bblevins@basspet.com](mailto:bblevins@basspet.com)