


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

### Release Notification and Corrective Action

0MLB/133940457

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating <u>269324</u>	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner B North Battery- Turner B 95	Facility Type: Water flood

Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001526612
--------------------	--------------------	---------------------

#### LOCATION OF RELEASE

Unit Letter L	Section 20	Township 17S	Range 31E	Feet from the 2610	North/South Line S	Feet from the 1000	East/West Line W	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	-----------------------	-----------------------	---------------------	----------------

Latitude: 32° 49' 11.5" Longitude: -103° 53' 50.1"

#### NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 14 / 1	Volume Recovered: 9 / 0.5
Source of Release: Steel Pipeline	Date and Hour of Occurrence: 11/3/2011 7:15am	Date and Hour of Discovery: 11/3/2011 7:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher- NM OCD / T. Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 11/3/2011 9:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: 2" steel flow line was buried under fire wall and was not wrapped with tape. The line was in very poor condition and already had a couple of repair clamps on it. Line only had 45 psi on it, but a weak spot in the line gave out.

Describe Area Affected and Cleanup Action Taken.\* : Remedial action pending

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Joe Hernandez	Signed By Approved by District Supervisor.	
Title: Production Foreman	Approval Date: <b>DEC 05 2011</b>	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval: Remediation per OCD Rules & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:</b> <u>1/5/2012</u>	Attached <input type="checkbox"/>
Date: 11/18/2011 Phone: 575-942-9492		

\* Attach Additional Sheets If Necessary

2RP-965