Office	iate District	State of I	New Me	xico	Form C-103
District I		Energy, Minerals	and Natu	ral Resources	May 27, 2004
1625 N. French Dr., Hobbs, I	NM 88240				WELL API NO. 30-015-23968
<u>District II</u> 1301 W. Grand Ave., Artesia	rand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				5. Indicate Type of Lease
District III	Prozes Rd. Aztes NM 87410 1220 South St. Francis Dr.				STATE FEE
District IV	NM 8/410	Santa Fe	, NM 87	505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa	a Fe, NM				
87505	DRY NOTIC	CES AND REPORTS ON	JWELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					BIG EDDY UNIT
1. Type of Well: Oil V	Well 🗌 🤄	Gas Well X Other			8. Well Number 84
2. Name of Operator			F	RECEIVED	9. OGRID Number
Bass Enterprises Production Co.  3. Address of Operator P. O. Box 2760					001801
3. Address of Operator	P. O. Box	2760		AUG 1 0 2005	10. Pool name or Wildcat
A 337 11 7 .*	Midland, 7	1X 19102	Q	DD-MHT度的M	GOLDEN LANE (WOLFCAMP)
4. Well Location	<u>.</u>	1980 feet from the	NODTU	15	20 C.C. I EAST 11
Unit Letter G	<u>'                                      </u>			line and 198	
Section 18		Township 215		nge 29E	NMPM CountyEDDY
		3308'	einer DK,	KKD, KI, GK, elc.)	
Pit or Below-grade Tank Ap	plication 🗌 or		· · · · <del></del>		
Pit typeDept	h to Groundwa	terDistance from nea	rest fresh w	ater well Dista	ance from nearest surface water
Pit Liner Thickness:	mil	Below-Grade Tank: Vol			nstruction Material
				-	
12	Check A	ppropriate Box to in	dicate in	ature of Notice,	Report or Other Data
NOTIC	CE OF IN	TENTION TO:		SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL	. WORK 🗌	PLUG AND ABANDON	X	REMEDIAL WORK	
TEMPORARILY ABAN		CHANGE PLANS		COMMENCE DRI	LLING OPNS.□ P AND A □
DILL OF ALTER OAC	NC T	MULTIPLE COMPL		CASING/CEMENT	I IOR 🖂
PULL OR ALTER CASI	ING 🗌	MOLI II LE COMI E			300
		WOLTH LE GOWN E			
OTHER:				OTHER:	[X]
OTHER:  13. Describe propos	sed or compl	eted operations. (Clearly	state all r	OTHER: pertinent details, and	X give pertinent dates, including estimated date
OTHER:  13. Describe propos	sed or compl proposed wo	eted operations. (Clearly	state all r	OTHER: pertinent details, and	[X]
OTHER:  13. Describe propose of starting any propose or recompletion MIRU PU.	sed or compl proposed wor	eted operations. (Clearly rk). SEE RULE 1103. F	state all r	OTHER: pertinent details, and	X give pertinent dates, including estimated date
OTHER:  13. Describe propose of starting any propose or recompletion MIRU PU.  Set CICR at 4050'. Square.	sed or compl proposed wor a. eeze. 40 sx C	eted operations. (Clearly rk). SEE RULE 1103. F	state all por Multip	OTHER: pertinent details, and le Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe propose of starting any propose or recompletion MIRU PU.  Set CICR at 4050'. Square point 5-1/2" 17# cs.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P	state all por Multip	OTHER: pertinent details, and le Completions: Att	X give pertinent dates, including estimated date
OTHER:  13. Describe propose of starting any por recompletion MIRU PU. Set CICR at 4050'. Square point 5-1/2" 17# cs. Spot 55 sx Class "C" Care	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873'	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag	state all por Multip	OTHER: pertinent details, and le Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proportion of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squire Free point 5-1/2" 17# c.  Spot 55 sx Class "C" C.  Spot 55 sx Class "C" C.  Spot 20 sx Class "C" C.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proportion of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squire Free point 5-1/2" 17# c.  Spot 55 sx Class "C" C.  Spot 55 sx Class "C" C.  Spot 20 sx Class "C" C.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proportion of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squire Free point 5-1/2" 17# c.  Spot 55 sx Class "C" C.  Spot 55 sx Class "C" C.  Spot 20 sx Class "C" C.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proportion of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squire Free point 5-1/2" 17# c.  Spot 55 sx Class "C" C.  Spot 55 sx Class "C" C.  Spot 20 sx Class "C" C.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proportion of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squire Free point 5-1/2" 17# c.  Spot 55 sx Class "C" C.  Spot 55 sx Class "C" C.  Spot 20 sx Class "C" C.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proportion of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squire Free point 5-1/2" 17# c.  Spot 55 sx Class "C" C.  Spot 55 sx Class "C" C.  Spot 20 sx Class "C" C.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe proportion of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squire Free point 5-1/2" 17# c.  Spot 55 sx Class "C" C.  Spot 55 sx Class "C" C.  Spot 20 sx Class "C" C.	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe propose of starting any proposed of starting any proposed of starting and proposed of starting any proposed of starting any proposed of starting any proposed of starting and proposed of starting and starti	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe propose of starting any proposed of starting any proposed of starting and proposed of starting any proposed of starting any proposed of starting any proposed of starting and proposed of starting and starti	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: Dertinent details, and de Completions: Att	I give pertinent dates, including estimated date tach wellbore diagram of proposed completion
OTHER:  13. Describe propose of starting any proposed of starting any proposed of starting and proposed of starting any proposed of starting any proposed of starting any proposed of starting and proposed of starting and starti	sed or compl proposed wor a. eeze. 40 sx C sg. RIH and c ement. 2873' ement. 606' t ement. 0' to 6	eted operations. (Clearly rk). SEE RULE 1103. F Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 50'. Surface Plug.	state all por Multip	OTHER: pertinent details, and the Completions: Att down csg. Circulate cation.	give pertinent dates, including estimated date tach wellbore diagram of proposed completion well with 10# ppg salt gel mud
OTHER:  13. Describe propose of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Clas	sed or complete proposed work.  eeze. 40 sx Cosg. RIH and dement. 2873' ement. 606' to ement. 0' to 6 ackfill work.	eted operations. (Clearly rk). SEE RULE 1103. For Class "C" Cement. Cut casing at free point. Pto 3073'. WOC & Tag. 806'. WOC & Tag. 50'. Surface Plug. pit, clean location. Rip are	state all por Multiple OH & lay	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate cation.	give pertinent dates, including estimated date tach wellbore diagram of proposed completion well with 10# ppg salt gel mud
OTHER:  13. Describe propose of starting any or recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Class	sed or complete proposed work.  eeze. 40 sx Cosg. RIH and dement. 2873' ement. 606' to ement. 0' to 6 ackfill work.	eted operations. (Clearly rk). SEE RULE 1103. For Class "C" Cement. Cut casing at free point. Pto 3073'. WOC & Tag. 806'. WOC & Tag. 60'. Surface Plug. pit, clean location. Rip articles to the surface of the surface Plug.	state all por Multiple OH & lay ad seed loo	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate cation.  Accepted to NMOC st of my knowledge	give pertinent dates, including estimated date tach wellbore diagram of proposed completion well with 10# ppg salt gel mud  Or record  and belief. I further certify that any pit or below.
OTHER:  13. Describe propose of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Clas	sed or complete proposed work.  eeze. 40 sx Cosg. RIH and dement. 2873' ement. 606' to ement. 0' to 6 ackfill work.	eted operations. (Clearly rk). SEE RULE 1103. For Class "C" Cement. Cut casing at free point. Program to 3073'. WOC & Tag. 150'. Surface Plug. Pit, clean location. Rip are closed according to NMOCD gram to NMOCD	state all por Multiple OH & lay ad seed loc	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate cation.  ACCOPTED to NMOC st of my knowledge l, a general permit   or other cation.	give pertinent dates, including estimated date tach wellbore diagram of proposed completion well with 10# ppg salt gel mud
OTHER:  13. Describe propose of starting any or recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Class	sed or complete proposed work.  eeze. 40 sx Cosg. RIH and dement. 2873' ement. 606' to ement. 0' to 6 ackfill work.	eted operations. (Clearly rk). SEE RULE 1103. For Class "C" Cement. Cut casing at free point. Program to 3073'. WOC & Tag. 150'. Surface Plug. Pit, clean location. Rip are closed according to NMOCD gram to NMOCD	state all por Multiple OH & lay ad seed loc	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate cation.  Accepted to NMOC st of my knowledge	give pertinent dates, including estimated date tach wellbore diagram of proposed completion well with 10# ppg salt gel mud  Or record  and belief. I further certify that any pit or below.
OTHER:  13. Describe propose of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Clas	sed or complete proposed work.  eeze. 40 sx Cosg. RIH and dement. 2873' ement. 606' to ement. 0' to 6 ackfill work information a constructed or constructed	class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 60'. Surface Plug. pit, clean location. Rip ar	state all por Multiple OH & lay ad seed loo	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate distance dis	I give pertinent dates, including estimated date each wellbore diagram of proposed completion well with 10# ppg salt gel mud  E well with 10# ppg salt gel mud  The correct of the correct
OTHER:  13. Describe propose of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Clas	sed or complete proposed work.  eeze. 40 sx Cosg. RIH and dement. 2873' ement. 606' to ement. 0' to 6 ackfill work information a constructed or constructed	eted operations. (Clearly rk). SEE RULE 1103. For Class "C" Cement. Cut casing at free point. Pto 3073'. WOC & Tag. 806'. WOC & Tag. 806'. Surface Plug. Ppit, clean location. Rip ar albove is true and complete closed according to NMOCD grant and	state all por Multiple OH & lay ad seed loo e to the beguidelines	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate cation.  ACCOPTED to NMOC st of my knowledge l, a general permit   or other cation.	give pertinent dates, including estimated date each wellbore diagram of proposed completion well with 10# ppg salt gel mud  or record  and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan   DATE 08/08/2005
OTHER:  13. Describe propose of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Clas	sed or complete proposed work.  eeze. 40 sx Cosg. RIH and dement. 2873' ement. 606' to ement. 0' to 6 ackfill work information a constructed or constructed	eted operations. (Clearly rk). SEE RULE 1103. F  Class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 60'. Surface Plug. pit, clean location. Rip ar	state all por Multiple OH & lay ad seed loo e to the beguidelines	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate distance dis	I give pertinent dates, including estimated date each wellbore diagram of proposed completion well with 10# ppg salt gel mud  E well with 10# ppg salt gel mud  The correct of the correct
OTHER:  13. Describe propose of starting any por recompletion MIRU PU.  Set CICR at 4050'. Squaree point 5-1/2" 17# cspot 55 sx Class "C" Cspot 55 sx Class "C" Cspot 20 sx Clas	sed or complete proposed work.  eeze. 40 sx C sg. RIH and cement. 2873' ement. 606' to ement. 0' to 6 ackfill work information a constructed or cement.	class "C" Cement. cut casing at free point. P to 3073'. WOC & Tag o 806'. WOC & Tag. 60'. Surface Plug. pit, clean location. Rip ar	state all por Multiple OH & lay ad seed loo e to the beguidelines	OTHER: Dertinent details, and the Completions: Att  down csg. Circulate distance dis	I give pertinent dates, including estimated date each wellbore diagram of proposed completion well with 10# ppg salt gel mud  E well with 10# ppg salt gel mud  The correct of the correct