

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1231248032

OPERATOR <input checked="" type="checkbox"/> Initial Report <input type="checkbox"/> Final Report		
Name of Company: Devon Energy Production LP <i>6137</i>	Contact: Daniel Suniga	
Address: P.O. Box 250 Artesia, N.M. 88211	Telephone No. (575)390-5850	
Facility Name: Todd 24B # 2	Facility Type: Oil Well # 30-015-27691	
Surface Owner	Mineral Owner	Lease No. NM0533177-A


LOCATION OF RELEASE

Unit Letter B	Section 24	Township 23S	Range 31E	Feet from the 660'	North/South Line North	Feet from the 1980'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release: Spill	Volume of Release: 70 bbls	Volume Recovered: 70 bbls
Source of Release: transfer pump malfunction	Date and Hour of Occurrence: 5/23/2012, 8:00 AM	Date and Hour of Discovery 5/23/2012, 8:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM-Eddy County	
By Whom? Daniel Suniga-Production Foreman	Date and Hour: 10/27/12, 3:55 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N/A



Describe Cause of Problem and Remedial Action Taken.*

At the Todd 24B # 2 battery, a contract Lease Operator discovered produced water spilling over the tank due to a transfer pump malfunction that caused a 70 bbl. produced water spill with 70 bbls. recovered.

Describe Area Affected and Cleanup Action Taken.*

The affected location was the Todd 24B # 2 battery. The Lease Operator contacted a vacuum truck to haul the produced water and then contacted his foreman where he was advised to shut in the location. The transfer pump was repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Raga</i>		OIL CONSERVATION DIVISION	
Printed Name: Rebecca Raga		Approved by District Supervisor:	Signed By: <i>Mike Brennan</i>
Title: Field Tech	Approval Date: NOV 07 2012	Expiration Date:	
E-mail Address: rebecca.raga@dv.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 10/30/2012 Phone: (575) 746-5564			

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**

Dec. 7th 2012

2RP-1391