


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1232053733 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 192463	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Nagooltee Peak 5 Com #2	Facility Type	Production

Surface Owner	Mineral Owner	Lease No. NM#81217
---------------	---------------	--------------------

LOCATION OF RELEASE

API #30-015-28074

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	5	22S	24E	1562	N	1202	W	Eddy County, NM

Latitude N 32.41777° Longitude W 104.51753°

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	10 bbls	Volume Recovered	0 bbls
Source of Release	Failure of 2 7/8" steel production line	Date and Hour of Occurrence	10/29/2012	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD, Terry Gregston-BLM		
By Whom?	Christopher Jones	Date and Hour	11/7/2012 @ 6:59 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Failure of a 2 7/8" steel production line caused 10 bbls of produced water to spill onto the ground. 0 bbls of water were recovered. Remediation will be performed according to OCD and BLM approved remediation plans.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 200' x 40'. Failure of a 2 7/8" steel production line caused 10 bbls of produced water to spill onto the ground. 0 bbls of water were recovered. Remediation will be performed according to OCD and BLM approved remediation plans.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Christopher Jones		Approved by District Supervisor: Signed By <i>M. Bratcher</i>	
Title: HES Specialist		Approval Date: NOV 15 2012	Expiration Date:
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval:	
Date: 11-14-12 Phone: (575) 628-4121		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
Dec. 15, 2012

2RP-1407