


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmw 1235238684 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Chevron USA Inc.	4323	Contact	Bradley Blevins
Address	PO Box 190, Hobbs, NM 88241		Telephone No.	(575) 391-1462
Facility Name	Government D #4		Facility Type	Well location

Surface Owner	Mineral Owner	Lease No. API#30-015-24921
---------------	---------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	1	21S	27E	1554	North	1980	East	Eddy County, NM

Latitude N 32.51812° Longitude W 104.14147°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	90 bbls	Volume Recovered	70 bbls
Source of Release	Hole in the discharge	Date and Hour of Occurrence	12/03/2012 @ 2:00 pm		
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required				
By Whom?	Cliff Brunson for Bradley Blevins	If YES, To Whom?	Mike Bratcher-NMOCD		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No				
Date and Hour	12/03/2012 @ 4:17 pm				
If YES, Volume Impacting the Watercourse.					

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A hole in the discharge caused 90 bbls of produced water to leak onto the ground. 70 bbls of produced water were recovered via vacuum truck. The hole was repaired.

Describe Area Affected and Cleanup Action Taken.*

A hole in the discharge caused 90 bbls of produced water to leak onto the ground. 70 bbls of produced water were recovered via vacuum truck. Further remediation will be performed in accordance with a NMOCD-approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor:	Signed By <i>Mike Bratcher</i>
Title: HES Specialist	Approval Date: DEC 17 2012	Expiration Date:
E-mail Address: Bradley.blevins@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 12/11/12	Phone: (575) 391-1462	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. **SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:**
January 17th 2013

2RP-1455