Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> – (575) 393-6161 Energy	y, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283		WELL API NO. 30-015-30725
811 S. First St., Artesia, NM 88210 OIL	CONSERVATION DIVISION	5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr.	STATE S FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		·
SUNDRY NOTICES AND R		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRIL DIFFERENT RESERVOIR. USE "APPLICATION FOR P		F
PROPOSALS.)	_	Foran State 8. Well Number 2
1. Type of Well: Oil Well Gas Well	Other	
2. Name of Operator COG Operation	_ ~ I.C	9. OGRID Number 229137
3. Address of Operator	g, LLC	10. Pool name or Wildcat.
One Concho Center, 600 W. Illinois	Avenue, Midland, TX 79701	Fren; Glorieta-Yeso
4. Well Location		<u> </u>
Unit Letter H : 1650	feet from the North line and	330 feet from the <u>East</u> line
Section 16	Township 17S Range 31E	NMPM County Eddy
	on (Show whether DR, RKB, RT, GR, etc.	
	3863 GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION	LTO: SUB	SEQUENT REPORT OF:
	DABANDON ☐ REMEDIAL WOR	
TEMPORARILY ABANDON CHANGE	_	
PULL OR ALTER CASING MULTIPLE		—
DOWNHOLE COMMINGLE		
OTHER: Deepen	□ OTHER:	
		d give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
See Attachment for Deepening and Completion procedures.		
\wedge	0+	DECEIVED
1) I having I CIO	5 upon completion	m RECEIVED
Provide revised C10	0	IAN 0 9 2013
		į į
		NMOCD ARTESIA
,		
Spud Date:	Rig Release Date:	
·	·	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
\supset \land		·
SIGNATURE 5 - Li	TITLE Regulatory Analyst	DATE 1/8/13
DATE 1/0/15		
Type or print name Brian Majorino	E-mail address: <u>bmaiorino@conch</u>	o.com PHONE: 432-221-0467
For State Use Only		- <u>-</u>
APPROVED BY: / CSMMW	TITLE GOOLOGIST	DATE 1/9/2013
Conditions of Approval (if any):		DATE

Foran State #2 30-015-30725

Deepening Procedure

- 1. MIRU rig.
- 2. LD production equipment.
- 3. Sqz Paddock w/ +/-400sx of Class C neat.
- 4. Drill out squeeze. Test squeeze to 500 psi for 20 minutes using chart recorder.
- 5. PU 4-3/4" bit and drill 4-3/4" from 5517' to 6550'.
- 6. POOH w/ bit and drillstring.
- 7. RIH w/ logs and log from TD to 4900'.
- 8. RIH w/ 4", 11.3# casing. See next attachment for general centralizer program.
- 9. Cement casing from TD to 5450' w/ 100 sxs Class C cmt. Drop plug and open DV tool. Circ cmt off DV tool. Drop plug to close DV tool.
- 10. PU workstring and RIH and drill out DV tool. POOH and LD workstring.
- 11. RDMO rig.

Completion Procedure

- 1. MIRU rig.
- 2. RIH/ w/ perforating guns and perforate Yeso from 6150'-6350' w/ 1 spf, 28 holes.
- 3. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand. Set plug at 6100'.
- 4. RIH w/ perforating guns and perforate Yeso from 5880'-6080'.
- 5. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand. Set plug at 5830'.
- 6. RIH w/ perforating guns and perforate Yeso from 5470-5670'.
- 7. Acidize w/ 2500 gals of 15% HCl. Frac zone w/ 179,800 # of sand.
- 8. RIH and drill out plugs at 5830 and 6100.
- 9. RIH and cut or back off 4" casing at 5450'. POOH w/ 4" casing. Leave 4" liner from 5450' to 6550' (TD).
- 10. RIH w/ tbg and locate end of tbg at 5300'.
- 11. RIH w/ rods and pump.
- 12. RDMO rig.

