

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 5 2013

Form C-141
Revised October 10, 2003

NMOCD ARTESIA

Submit 3 copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJM 1303932155

OPERATOR

☐ Initial Report

☐ Final Report

Name of Company	Oxy Permian Ltd.	16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM		Telephone No.	(575) 397-8216
Facility Name	Sterling Silver 3 Federal #6 Battery		Facility Type	Gathering

Surface Owner	BLM	Mineral Owner		Lease No.	NM-55142
---------------	-----	---------------	--	-----------	----------

LOCATION OF RELEASE

30-015-27638

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	3	24S	31E	1980	North	2310	West	Eddy

Latitude N 32.24812°

Longitude W 103.76672°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	200 bbls water, 1 bbl oil	Volume Recovered	180 bbls
Source of Release	Rubber brushing failure between pump and motor caused tank to spill over	Date and Hour of Occurrence	1/23/13	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD; James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	1/24/13 @ 1:54 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Rubber brushing failure between a pump and motor caused a tank to spill over releasing 200 bbls of produced water and 1 bbl of oil onto the ground. 180 bbls were recovered via vacuum truck and the brushing was repaired.

Describe Area Affected and Cleanup Action Taken.*

Rubber brushing failure between a pump and motor caused a tank to spill over releasing 200 bbls of produced water and 1 bbl of oil onto the ground. 180 bbls were recovered via vacuum truck and the brushing was repaired. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Chancey Summers	Approved by District Supervisor: Signed By	<i>Mike Bratcher</i>
Title: HES Specialist	Approval Date: FEB 08 2013	Expiration Date:
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2-4-13	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	

* Attach Additional Sheets If Necessary

March 8, 2013

2RP-1546