

Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District H. (577 749, 1202)	Form C-103
District II $-(575)$ 748-1283	Revised August 1, 2011 WELL API NO. 30-005-62663
811 S. First St., Artesia, NM 88210OIL CONSERVATION DIVISIONDistrict III - (505) 334-61781220 South St. Francis Dr.1000 Rio Brazos Rd., Aztec, NM 87410Santa Fe, NM 87505	<ul> <li>5. Indicate Type of Lease</li> <li>STATE STATE FEE</li> <li>6. State Oil &amp; Gas Lease No.</li> </ul>
1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS	LG-9154         7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Energy AFY State 8. Well Number
1. Type of Well: Oil Well   Gas Well   Other     2. Name of Operator   Gas Well   Gas Well	1 9. OGRID Number
Yates Petroleum Corporation 3. Address of Operator	025575 10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210	Foor Ranch; Pre-Permian
4. Well Location Unit Letter <u>C</u> : <u>990</u> feet from the <u>North</u> line and	1980 feet from the <u>West</u> line
Section36Township9SRange26E11. Elevation (Show whether DR, RKB, RT, GR, end	NMPM Chaves County
11. Elevation (Show whether DR, RAB, R1, GR, et al. 3840'GR	
12. Check Appropriate Box to Indicate Nature of Notice	e. Report or Other Data
	IBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK       PLUG AND ABANDON       REMEDIAL WORK         TEMPORARILY ABANDON       CHANGE PLANS       COMMENCE D	
PULL OR ALTER CASING     Image: Multiple complement     Image: Casing/Ceme       DOWNHOLE COMMINGLE     Image: Casing/Ceme	
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, a of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple C proposed completion or recompletion.	
Yates Petroleum Corporation plans to plug and abandon this well as follows:	· · ·
<ol> <li>MIRU WSU, NU BOP. Rig up any safety equipment as needed. No casing recovery</li> <li>Set a CIBP at 5997' with 35' cement on top. This puts a plug over Ordovician perfora</li> <li>Set a CIBP at 5218' with 35' cement on top. This puts a plug over non producing and</li> <li>Spot a 25 sx Class "C" cement plug from 4544'-4644'. This puts a 100' plug across t</li> <li>Spot a 25 sx Class "C" cement plug from 2297'-2447'. This puts a 150' plug across t</li> </ol>	ations. I squeezed Wolfcamp perforations. op of the Abo. op of the Glorieta and DV tool. surface casing shoe. WOC and tag plug.
<ul> <li>6. Spot a 25 sx Class "C" cement plug from 1143'-1243'. This puts a 100' plug across s</li> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulated and clean location.</li> </ul>	uon.
<ul> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulat</li> <li>Wellbore schematics attached</li> </ul>	De
<ul> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulat</li> <li>Wellbore schematics attached</li> </ul>	nted providing work RECEIVED
<ul> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulat</li> <li>Wellbore schematics attached Approval Gran</li> </ul>	nted providing work RECEIVED
<ul> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulat</li> <li>Wellbore schematics attached</li> <li>NOTE: Yates Petroleum Corporation will use steel pits</li> <li>and no earth pits is complete by</li> <li>Spud Date:</li> </ul>	nted providing work RECEIVED MAR 1 4 2013 NMOCD ARTESIA
<ul> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulat</li> <li>Wellbore schematics attached</li> <li>Approval Gran</li> <li>NOTE: Yates Petroleum Corporation will use steel pits and no earth pits is complete by</li> <li>Spud Date:</li> <li>I hereby certify that the information above is true and complete to the best of my knowled</li> </ul>	nted providing work RECEIVED MAR 1 4 2013 NMOCD ARTESIA
<ul> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulat</li> <li>Wellbore schematics attached Approval Gran</li> <li>NOTE: Yates Petroleum Corporation will use steel pits and no earth pits is complete by</li> <li>Spud Date: Rig Release Date: Rig Release Date:</li> <li>I hereby certify that the information above is true and complete to the best of my knowled</li> <li>SIGNATURE Time Tina Huerta</li> <li>Type or print name Tina Huerta</li> </ul>	A providing work RECEIVED MAR 1 4 2013 NMOCD ARTESIA dge and belief.
<ul> <li>7. Spot a 15 sx Class "C" cement plug from 60' up to surface.</li> <li>8. Remove all surface equipment, weld dry hole marker and clean location as per regulat</li> <li>Wellbore schematics attached Approval Gran</li> <li>NOTE: Yates Petroleum Corporation will use steel pits and no earth pits is complete by</li> <li>Spud Date: Rig Release Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowled</li> <li>SIGNATURE SIGNATURE TITLE Regulatory Reporting</li> </ul>	Adge and belief. Supervisor DATE March 13, 2013 PHONE:





## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT Operator: <u>Jates Pet. Corp</u> Well Name & Number: <u>Energy AFY</u> <u>State #1</u> API #: <u>30-005-62663</u>

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: March 18-2013

APPROVED BY: Robels

## GUIDELINES FOR PLUGGING AND ABANDONMENT

## DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
   Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).