

Submit I Copy To Appropriate District Office State of New Mexico DistrictII - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240 DistrictII - (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION DistrictIII - (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS Santa Fe, NM 87505 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Water Injection 2. Name of Operator CHEVRON MIDCONTINENT, L.P. 3. Address of Operator 15 Smith Road Midland, TX 79705	Form C-103 Revised August 1, 2011 WELL API NO. 30-015-26036 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name PARDUE FARMS 27 8. Well Number: 7 9. OGRID Number: 241333 10. Pool name or Wildcat E. LOVING; BRUSHY CANYON			
4. Well Location Unit Letter A : _ 560 feet from the NORTH line and 560 Section 27 Township 23-S Range 28-E I1. Elevation (Show whether DR, RKB, RT, GR, etc.) 3047' KB	NMPM County EDDY			
12. Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE	SEQUENT REPORT OF: K			
OTHER: OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.				
 TD-7508' PBTD-7275' PERFS: 6040' - 7027' CIBP @ 6000'2 SKS CMT SURF CSG: 8-5/8" 24# @ 495' w/475 sx, HOLE SZ: 12-1/4", T PROD. CSG: 5-1/2" 15.5 & 17# @ 7508' w/560 sx, HOLE SZ: DV TOOL @ 5002' MIRUWSU. NDWH. NUBOPE. Tag CIBP @ 6000' w/25 sx of C cement Pressure Test casing to 500 psi and record/report findings. Set plug w/30 sks of C cement @ 5102' - 4902' CTOC.(DV TOOL) Perf & Sqz w/50 sks of C cement @ 3560. WOC & TAG, (Top of Cement) Perf & Circulate 70 sks of C cement 650'-Surface., (Top of Salt, & Shoe) Cut off wellhead and anchors 3' below grade. Weld on dry hole marker. Clean loc 	APR 0 4 2013 NMOCD ARTESIA Approval Granted providing work			
Spud Date: Rig Release Date:				
I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLE Representative Type or print name Robert Holden For State Use Only E-mail address: rholden@keyene APPROVED BY: PODDE Conditions of Approval (if any): SEE Afthached Cond's	DATE <u>04/01/2013</u> rgy.com PHONE: <u>432-523-5155</u>			

Well: Pardue Farms #27-7




By: Bob Hall



Well: Pardue Farms #27-7

Field: Loving East



By: Bob Hall

PARDUE	FARMS 27-7	Permit # : Rig Mobe Date: Rig Demobe Date: Rig Demobe Date:							
Le	a Co.								
Time			or pumps	Has any hazardous waste been disposed of in system?					
				-					
					<u> </u>			·	
					<u> </u>			<u> </u>	
								<u> </u>	
	·							<u> </u>	
			<u>.</u>		ļ				
							+	ł	
							+	<u> </u>	
———							<u> </u>		
					 	ļ	<u> </u>		1
	Le	Lea Co.	PARDUE FARMS 27-7 Permit # : Lea Co.	PARDUE FARMS 27-7 Permit # : Lea Co. Any drips or leaks free	PARDUE FARMS 27-7 Permit # : Lea Co. Any drips or leaks from steel ta	PARDUE FARMS 27-7 Permit # : Rig Mobe Lea Co. Rig Demo Any drips or leaks from steel tanks, lines of leaks from steel tanks, lines steel tanks, lines from steel tanks, lines	PARDUE FARMS 27-7 Permit # : Rig Mobe Date: Lea Co. Rig Demobe Date: Any drips or leaks from steel tanks, lines or pumps	PARDUE FARMS 27-7 Permit # : Rig Mobe Date: Lea Co. Rig Demobe Date: Any drips or leaks from steel tanks, lines or pumps Has any h	PARDUE FARMS 27-7 Permit # : Rig Mobe Date: Lea Co. Rig Demobe Date: Any drips or leaks from steel tanks, lines or pumps Has any hazardous w


All circulating systems to be inspected DAILY during drilling operations. *Any leak of the steel tanks, lines or pumps shall be reported to the NMOCD and repaired within 48 hours.

New Mexico Daily Circulating System Inspection - Closed loop

.







NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT
Operator: Chevrow Mid Continent
Well Name & Number: Par due Farms 27-7
API #: 30 - 015 - 26036

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- **3.** Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.10. Plugs may be combined after consulting with and getting approval from NMOCD.11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: 04/11/2013

APPROVED BY: ARDacle

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).