

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87401  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

MAR 28 2013

NMOC ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

nJM W 1310239402

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sand Dunes 28 Federal #1 SWD	Facility Type	SWD

Surface Owner	BLM	Mineral Owner		Lease No.	NM 40659
---------------	-----	---------------	--	-----------	----------

#### LOCATION OF RELEASE

30-015-26194

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	28	23S	31E					Eddy

Latitude N 32.27641° Longitude W 103.78047°

#### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	650 bbls	Volume Recovered	590 bbls
Source of Release	Tank overflow due to broken triplex pump	Date and Hour of Occurrence	03/24/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen, James Amos-BLM and Mike Bratcher-OCD		
By Whom?	Chancey Summers	Date and Hour	03/25/2013 @ 9:08 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*


A broken triplex pump caused a tank to overflow spilling 650 bbls of produced water onto the ground. 590 bbls of produced water were recovered via vacuum truck and the pump was repaired.

Describe Area Affected and Cleanup Action Taken.\*

A broken triplex pump caused a tank to overflow spilling 650 bbls of produced water onto the ground. 590 bbls of produced water were recovered via vacuum truck and the pump was repaired. Remediation will be performed in accordance with an approved plan from the NMOC and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature: 


Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 3-27-13 Phone: (575) 397-8216

Approved by District Supervisor:

Signed By 

APR 12 2013

Approval Date:

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

May 12, 2013

Attached ☐

2RP-1617

\* Attach Additional Sheets If Necessary