


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NJM 1312748135

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Chevron Delaware Basin 4323	Contact	Bradley Blevins
Address	PO Box 190, Hobbs, NM 88241	Telephone No.	(575) 391-1462
Facility Name	Benson Shugart #11 Well and Battery	Facility Type	WFO

Surface Owner	BLM	Mineral Owner		API #	30-015-20528
---------------	-----	---------------	--	-------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	26	18S	30E	2310	South	330	East	Eddy County, NM

Latitude N 32.71690° Longitude W 103.93508°

NATURE OF RELEASE

Type of Release	Produced Water	Volume of Release	133 bbls	Volume Recovered	90 bbls
Source of Release	Injection line leak	Date and Hour of Occurrence	05/01/2013 @ 1:00 am	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD; James Amos- BLM		
By Whom?	Bradley Blevins	Date and Hour	05/01/2013 @ 4:25 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

An injection line leak caused 133 bbls of produced water to leak onto the ground. 90 bbls of fluid were recovered via vacuum truck and the line was repaired.

Describe Area Affected and Cleanup Action Taken.*

The area affected was approximately 100' x 250'. An injection line leak caused 133 bbls of produced water to leak onto the ground. 90 bbls of fluid were recovered via vacuum truck and the line was repaired. Further remediation will be performed in accordance with a NMOCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Bradley Blevins</u>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by District Supervisor:	Signed By: <u>Mike Bratcher</u>
Title: HE Specialist	Approval Date: <u>MAY 07 2013</u>	Expiration Date:
E-mail Address: <u>Bradley.blevins@chk.com</u>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05/06/2013 Phone: (575) 391-1462	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>June 7, 2013</u>	

* Attach Additional Sheets If Necessary

2RP-1646