Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103
	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	NA Figure 1850	WELL API NO.
District II – (575) 393-6161  1625 N. French Dr., Hobbs, NM 88240  District II – (575) 748-1283  811 S. First St., Artesia, NM 88210  District III – (505) 334-6178  UNA C — 2005 1220 South St. Francis Dr.		30-015-24723
District III – (505) 334-6178 IIIN 2 = 2014 1220 South St. Francis Dr.		5. Indicate Type of Lease  STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 874-10 <sup>3</sup> C t) CUIJ Santa Fe, NM 87505		STATE X FEE  6. State Oil & Gas Lease No.
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, MM 535 87505	JCD	o. State on & das Lease No.
	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Cave Pool Unit
· · · · · · · · · · · · · · · · · · ·	Well Other	8. Well Number #59
2. Name of Operator		9. OGRID Number
State of New Mexico formerly Marks And Garner		14070
3. Address of Operator		10. Pool name or Wildcat
811 S. First Street Artesia, NM 88210		Cave GB/SA
4. Well Location		
Unit LetterJ:	1650feet from theSouth line and _	1650feet from theEastline
Section 5	Township 17S Range 29	PE NMPM Eddy County
<del>工作的。</del>	1. Elevation (Show whether DR, RKB, RT, GR, e	etc.)
		·
12. Check App	ropriate Box to Indicate Nature of Notic	e, Report or Other Data
NOTICE OF INTE	INITION TO:	IDOCOLICAT DEDODE OF.
		JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  TEMPORARILY ABANDON  CHANGE PLANS  COMMENCE DRILL		<del>_</del>
	IULTIPLE COMPL  CASING/CEMI	
PULL OR ALTER CASING   N DOWNHOLE COMMINGLE	IDETIFEE COMPL	IN JOB
50,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
OTHER:	☐ OTHER:	
	SEE RULE 19.15.7.14 NMAC. For Multiple 0	and give pertinent dates, including estimated date Completions: Attach wellbore diagram of
5/13/2013 MIRU. No tubing or at 2284'.	rods. Installed BOP and picked up work string v	with scrapper. POOH with scrapper and set CIBP
	25 sx cement on CIBP. POOH to 1806' and spotalled marker and cut off anchors.	tted 25 sx cement. POOH to 407' and circulated
	•	
•		•
Spud Date:	Rig Release Date:	
I hereby certify that the information abo	ve is true and complete to the best of my knowle	dge and belief
· · ·	· ·	oge and ponen.
SIGNATURE		D. A. EDE
	TITLE	DATE
Turn on mint name		
Type or print name	TITLEE-mail address:	PHONE:
Type or print name  For State Use Only		PHONE:
· · · — — — — — — — — — — — — — — — — —		