

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 24 2013

Form C-141
Revised August 8, 2011

NMOCD ARTESIA

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nJMW 1318353692

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	Harroun 9-1	Facility Type	Well location

Surface Owner	BLM	Mineral Owner		API No.	30-015-34997
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	9	24S	29E	530	South	330	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	40 bbls oil	Volume Recovered	0 bbls oil
Source of Release	Mechanical error sent oil down a gas line causing tank to overflow	Date and Hour of Occurrence	06/13/2013	Date and Hour of Discovery	06/13/2013
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Jennifer Van Curen, James Amos- BLM		
By Whom?	Chancey Summers	Date and Hour	06/17/2013 @ 8:03 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A mechanical error sent oil down the gas line causing the tank to overflow and leak 40 bbls of oil to leak onto the ground. No fluids were recovered and mechanical error was corrected.

Describe Area Affected and Cleanup Action Taken.*

A mechanical error sent oil down the gas line causing the tank to overflow and leak 40 bbls of oil to leak onto the ground. No fluids were recovered and mechanical error was corrected. Remediation will be conducted in accordance with a plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Chancey Summers

Title: HES Specialist

E-mail Address: Chancey.Summers@oxy.com

Date: 6-24-13 Phone: (575) 397-8216

* Attach Additional Sheets If Necessary

OIL CONSERVATION DIVISION

Approved by Environmental Specialist:

Signed By: Mike Bratcher

Approval Date:

JUL 02 2013

Expiration Date:

Conditions of Approval:

Remediation per OCD Rule & Guidelines, & like approval by BLM. **SUBMIT REMEDIATION**

PROPOSAL NO LATER THAN:

August 2, 2013

Attached ☐

2RP-1699