Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No. NMNM100541

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to le talter and	
handoned well. Use form 3160-3 (APD) for such proposate	AHTERIA

SUNDRY NOTICES AND REPORTS ON WELLS				TAMINIMITOUS				
Do not use this form for proposals to drill or to legante and ARTESIA abandoned well. Use form 3160-3 (APD) for such proposals D ARTESIA					6. If Indian, Allottee or	Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	ment, Name and/or	r No.	
Type of Well	ner				8. Well Name and No. PURDY 8 FEDER	AL 1	· .	
Name of Operator COG OPERATING LLC	Contact: · E-Mail: bmaiorino@	BRIAN MAIC Concho.com	PRINO		9. API Well No. 30-015-36273			
3a. Address ONE CONCHO CENTER 600 MIDLAND, TX 79701	W. ILLINOIS AVE	3b. Phone No Ph: 432-22	. (include area code 1-0467)	10. Field and Pool, or Exploratory BONE SPRING			
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description))			11. County or Parish, and State			
Sec 8 T23S R26E NENE 114	OFNL 1240FEL				EDDY COUNTY	, NM		
12 CHECK APPL	ROPRIATE BOX(ES) TO) INDICATE	NATURE OF	NOTICE R	FPORT OR OTHER	R DATA		
TYPE OF SUBMISSION	COLKIATE BOX(E3) TO			F ACTION	EI OKI, OK OTHER			
111E OF SODIMISSION		· · · · · · · · · · · · · · · · · · ·					0.66	
Notice of Intent ■ Notice of Intent	☐ Acidize	☐ Dee		_	ion (Start/Resume)	☐ Water Shut-		
☐ Subsequent Report	☐ Alter Casing		cture Treat	Reclam		□ Well Integri	ity	
_ , ,	Casing Repair		Construction	□ Recomp		Other		
☐ Final Abandonment Notice	∴ Change Plans ☐ Convert to Injection	🗀 Plug			rarily Abandon			
determined that the site is ready for form of the Bone Spring. Please seems of the Bone Spring. Install back pressure valve. Remove wellhead & install BC Attempt to release from on/off cut off) Pull tubing and visually inspective of the Bone Set CIBP @ 10935? capped well and the Bone Set CIBP @ 10935? capped well and the Bone Set CIBP @ 10935?	ully request to abandon the ee attached current and pr P. tool. (If cannot release, p	roposed well bunch hole in	tubing, and if no	ecessary,	SUBJECT TO APPROVAL I SEE ATTACI CONDITION DESCRIPTION OF System OF SYSTEM OF STREET OF STR	LIKE BY STATE HED FOR		
14. I hereby certify that the foregoing is	strue and correct.		Provi	de C	102 Acco	riod ion	ਦਟਰਾਨ	
	Committed to AFMSS for p	PERATING L	C, sent to the C JOHNNY DICKE	ell Information arisbad ERSON on 05/	n System (10/2013 ()	NMOCD	10	
Name(Printed/Typed) BRIAN MA	AIORINO		Title AUTHO	ORIZED REP	PRESENTATIVE	·	η & ₩	
Signature (Electronic S	Submission)		Date 05/09/2	2013	APPROV	/FD	1 4 1	
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE CONTRACTOR			
Approved By			Title		AJUL 2	2013 Date		
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the applicant to conduct the applicant the applicant the applicant the applicant the applicant to conduct the applicant the appli	uitable title to those rights in the	not warrant or subject lease	Office		BURAU OF LAND MA	NAGEMENT O	2	
Fitle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a estatements or representations as	crime for any po to any matter w	erson knowingly and ithin its jurisdiction	d willfully to m	ake to any department or	OFFICE agency of the Unit	ed .	

Additional data for EC transaction #206917 that would not fit on the form

32. Additional remarks, continued

9

TIH with tubing open ended Spot Class H cement mixed at 16.4# gal from 9100 ? 9500 (Liner top @ 9408? & Wolfcamp top @ 9190?) Circulate well clean & TOH Pressure test casing to 8000 psi Run GR/CCL from PBTD to 4000? Perforate 3rd Bone Spring @ 8964? (16 holes), 8894? (14 holes) and 8845? (10 holes) and 8790? (10 holes) w/6 spf, 600 phasing utilizing Schlumberger open hole log dated 7/3/08. TIH w/tubing & packer. Spot acid across perfs. Set packer at 8700? Acidize zone with 3000 gallons 15% HCl at 3 ? 5 BPM while dropping balls Shut-in 1 hour & flow back Pull tubing and packer Set frac valve & prepare for frac. Frac well utilizing attached procedure. Set flow through composit plug at 6700? Perforate 2nd Bone Spring @ 6562? (16 holes), 6494? (14 holes) and 6458? (10 holes) w/6 spf, 600 phasing utilizing schlumberger open hole log dated 7/3/08. Frac well utilizing attached procedure. Set flow through composit plug at 6250? Perforate 1st Bone Spring @ 6138? (12 holes), 6087? (16 holes), 6032? (12 holes) w/6 spf, 600 phasing utilizing Schlumberger open hole log dated 7/3/08. Frac well utilizing attached procedure. Shut-in well for 24 hours Flow well back until dead. TIH with tubing and drill out plugs. TOH TIH with tubing ag gas lift equipment. Place well on test

Author:	Stroup			
Well Name	Purdy 8 Fed	Well No.	#1	
Field	Carlsbad S Morrow	API#.	30-015-36273	
County	Eddy	Prop#		
State	New Mexico	Zone	Strawn	
Date	4/5/2013			
GL	3369'			****
кв	3396.5'			


Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8	H40 _	48	525	520	Surface
Inter Csg	9 5/8	K55	36	2,465	900	Surface
Prod Csg	7	P110_	26	9,750	1,200	Surface
Liner	4 1/2	P110	13.50	9408 - 12415	300	TOL

Current Well Bore

ECP @ 150'


17 1/2" hole 13-3/8" (H40 - 48#) @ 525' w/520 sx TOC @ surface

2-3/8" N80 Tbg - 339 jts



Author:	Stroup			
Well Name	Purdy 8 Fed	Well No.	#1	
Field	Carlsbad S Morrow	API#:	30-015-36273	
County	Eddy	Prop #:	, , , , , , , , , , , , , , , , , , , ,	
State	New Mexico	Zone:	Bone Spring	
Date	4/5/2013			
GL	3369'			
KB	3396 5'			

Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8	H40	48	525	520	Surface
Inter Csg	9 5/8	K55	36	2,465	900	Surface
Prod Csg	7	P110	26	9,750	1,200	Surface
Liner	4 1/2	P110	13.50	9408 - 12415	300	TOL



TD @ 12415'

Proposed Well Bore

ECP @ 150'

17 1/2" hole 13-3/8" (H40 - 48#) @ 525' w/520 sx TOC @ surface

2-3/8" N80 Tbg - 339 jts

12 1/4" hole

9-5/8" (K55 - 36#) @ 2465' w/900 sx TOC @ surface

Halliburton Versaflex Hanger @ 9408

8 3/4" hole

7" (P110 - 26#) @ 9750' w/1200 sx TOC @ Surface - 1" to 600'

1st Bone Spring: 6032, 6087, 6138

2nd Bone Spring: 6458, 6494, 6562

3rd Bone Spring: 8790, 8845, 8894, 8964

Wolfcamp Cement plug 9100-9500

CIBP @ 10935' w/35' cement

11035-40 & 11066-80

Strawn

CIBP @ 11225' w/15' cement

12110-24, 12026-28, 12019-21, 12010-14

CIBP @ 12160'

Morrow

12308' - 12314'

6 1/8" hole

4-1/2" (P110 - 13.5#) @ 12415' w/300 sx TOC @ Liner Top

Purdy 8 Federal 1 30-015-36273 COG Operating LLC July 2, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by October 2, 2013.

- 1. Operator shall drill out CIBP at 11,225' that was set without approval.
- 2. Operator shall tag CIBP at 12,160'. Operator can either place 230' of Class H cement on top of the CIBP or set a CIBP at 12,060' and spot 220' of Class H cement on top to seal off the Morrow formation. Tag required.
- 3. Operator shall place a CIBP at 10,985' and place a minimum of 25 sx of class H cement on top to cover the perforations. Tag required.
- 4. Operator shall spot Class H cement from 9,800'-9,358' to cover 7" shoe and 4-1/2" liner top. Tag required.
- 5. The operator shall place a balanced class H cement plug from 9,200'-9000' to seal off the Wolfcamp formation. Tag required ensuring the Wolfcamp formation is sealed off.
- 6. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 7. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 8. Surface disturbance beyond the originally approved pad must have prior approval.
- 9. Closed loop system required.

- 10. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 11. Operator to have H2S monitoring equipment on location.
- 12. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 13. Subsequent sundry required detailing work done and completion report for the new formation. Operator to include new well plat and well bore schematic of current well condition when work is complete.

JAM 070213