Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103	
District I – (575) 393-6161 Energy, Minerals and Natural Reso	wrces Revised August 1, 2011 WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	20.015.27942	
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISI	5. Indicate Type of Lease	
District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE S	
District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number	
PROPOSALS.) 1. Type of Well: Oil Well	5	
2. Name of Operator	9. OGRID Number	
Yates Petroleum Corporation	025575	
3. Address of Operator	10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM 88210	N. Dagger Draw U/Penn	
4. Well Location		
Unit Letter P : 660 feet from the South line a		
Section 8 Township 19S Range	25E NMPM Eddy County	
11. Elevation (Show whether DR, RKB, RT	GR, etc.)	
3533' GR		
12 Charle Annuarieta Dan to Indicate Natura of	Nisting Demont on Other Detail	
12. Check Appropriate Box to Indicate Nature of	Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:	
<u> </u>	IAL WORK ALTERING CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMME	ENCE DRILLING OPNS. P AND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING	G/CEMENT JOB	
DOWNHOLE COMMINGLE		
OTHER OTHER		
OTHER: OTHER 13. Describe proposed or completed operations. (Clearly state all pertinent of the complete operation).		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Mu		
proposed completion or recompletion.	miple completions. Attach wendere diagram of	
Yates Petroleum Corporation plans to Plug and Abandon this well as follows:		
1. MI RU WSU. ND Wellhead NU BOP. RU all H2S and safety equipment. No casing recovery will be attempted. POOH with		
production equipment.		
2. MI RU WL to make a GR & JB run to 7,748', then set CIBP @ 7,708'. Tally tubing and RIH open ended to tag the CIBP at 7,708' and cap it with 25 sx of class "H" cement. Load the hole with plugging mud. Move the tubing to 5,633' and spot a 249'		
plug from 5,384' to 5,633'. Pull 5 stands and reverse circulate to clean out tubing. This will leave a plug across the Wolfcamp		
top and the DV tool.	F-100 1111 1111 1111 1111 1111 1111 1111	
3. Move tubing to 4,670' and then spot a 150' plug from 4,520' to 4,670'.	Pull 5 stands and reverse circulate to clean out tubing.	
This will leave a plug across the Abo top. Approved for plugging of Liability under bond is ret		
Liability under bond is red	cort of Well Plugging) D Web Page unde CONTINUED ON NEXT PAGE:	
RECEIVED which may be found at OC	DD Web Page under CONTINUED ON NEAT FAGE: CONDITIONS OF APPROVAL ATTACHED	
Forms, www.cmnrd.state.t	hm.us/ocu.	
AUG 1 5 2013	Approval Granted providing work is	
Spud Date: Rig Release Date:	Completed by A	
NMOCD ARTESIA	Ac 19, 2014	
I hereby certify that the information above is true and complete to the best of my	knowledge and belief.	
SIGNATURE TITLE Regulatory Re	porting Technician DATE August 13, 2013	
//out 15 // Description of the second of the		
Type or print name Laura Watts E-mail address: laura@yatespetroleum.com PHONE: 575-748-4272		
For State Use Only		
APPROVED BY TUDOL TITLE ST REPEWISO DATE AU 19 2013		
Conditions of Approval (if any):		
Sometiment of Allarla	1112	
P OTT /THINK	UJH)	

Roy AET #5 Section 8-T19S-R25E Eddy County, New Mexico Page 2


Form C-103 continued:


- 4. Move tubing to 2,173' and then spot a 150' plug from 2,023' to 2,173'. Pull 5 stands and reverse circulate to clean out tubing. This will leave a plug across the Glorieta top.
- 5. Move tubing to 1,119' and then spot a 150' plug from 969' to 1,119'. POOH and WOC and tag plug, re-set if necessary. This will leave a plug across the Surface Casing shoe.
- 6. TIH with tubing to 150'. Load the hole with plugging mud and then spot a 150' plug to the surface. WOC and tag plug, re-set if necessary. This will leave a 150' surface plug.
- 7. Remove all surface equipment and weld dry hole marker per regulations.

Current schematic attached

Regulatory Reporting Technician

August 13, 2013





NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Yates Actobeum	
Well Name & Number: Roy AFT #5	
API#: 30-015-27843	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.
- 11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: Aug 17,2013

APPROVED BY: A Dado

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).