District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

> Oil Conservation Division 1220 South St. Francis Dr.

MAR 27 2014

RECEIVED

Form C-141 Revised October 10, 2003

NMOOD ASTERDATE District Office in ASTERDATE With 19.15.29 NMAC

Santa Fe, NM 87505 **Release Notification and Corrective Action**

						OPERATOR			☐ Initial Report ☐ Final Report			
Name of Company: Linn Operating 269324						Contact: Bri	an Wall					
Address: 2130 W. Bender Hobbs, NM 88240						Telephone No.: 575-738-1739						
Facility Name: Keel J L B #30						Facility Type: Injection						
Surface Owner: Federal Mineral Owner:						API No.: 30-015-21460						
		1		LOCA	TION	N OF REI	LEASE					
				1			West Line County					
О	06	17S	31E	430	:	South	2250	1	East		Eddy	'
Latitude: 32.85744 Longitude: -103.90692												
nHMP1409029298 NATURE OF RELEASE												
Type of Release: Produced Water						Volume of Release: '88 bbls Volume Recovered: 60 bbls						
Source of Release: Steel Pipeline						Date and Hour of Occurrence:			Date and Hour of Discovery:			
Was Immediate Notice Given?						03/26/2014						
Yes ☐ No ☐ Not Required												
By Whom? Brian Wall						Date and Hour 03/27/2014 0650						
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.						
		*	•									
If a Watercou	ırse was Im	pacted, Descri	be Fully.*	:					•			
			**									
•		1 4										
		Ş										
Describe Cause of Problemiand Remedial Action Taken.*: Drove up to keel west water station started getting gauges on control panel noticed that injection pressure was at 1875 # when usually runs 1940-1950# turn pump off went up to header and spotted line #3 dropping down quick s/I master valve turn pump back on pressure went back to normal on header and control panel went out to inj wells to look for leak found leak North side of Keel A #23 location 150'.												
		:					÷			•		
Decaribe Are	a Affactad	ir and Cleanum A	ation Tale	* . I		101	Y 45011	C11	1.11 4013	7.501 11:1		
Describe Area Affected and Cleanup Action Taken.*: Leak ran west average 10' wide X 450' long end of leak puddle 40' X 50' called vac truck and recover 60 BBLS of P/W from ground hauled to CRI dug out leak found a steel plug at the end of tee with a hole in it, had rain showers early this morning floor was wet was able to recover fluid. Site will be delineated by Diversified and the a CAP will be turned in. I will have estimate and PLA at												this
that time.		:					:					
		1										
Thereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
		ws and/or regu		tance of a C-141 F	eport d	oes not renev	e the operator of r	esponsi	ionny for c	omphance v	nın any	otner
							OIL CONS	SERV	ATION	DIVISIO	N	
Signature: JS 44						Approved by District Supervisor:						
Title: Constru	uction Fore	man II				Approval Dat	e: 3-31-19	4	Expiration	Date: 1	A	
		linnenergy.co		Conditions of				Attached				
Date: 03/27/2	2014		none: 806-	-30/-0045			on per OCD R					
		.*			Gui	idelines. S l	JBMIT REMEI	DIATIO	ON)R	17 - 2	2734

PROPOSAL NO LATER THAN: 5-1-14