RECEIVED

MAR 17 2014

District 1
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
29 Rio Brazos Road, Aztec, NM 87410
21ct IV

.220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources MOCD ARTESIA

Form C-141 Revised October 10, 2003

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

2RP-2224

Name of Company COG OPERATING LLC ZZ 9 137 Contact Robert McNeill Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077 Facility Name Myox 32 State #001H Facility Type Tank Battery Surface Owner State Mineral Owner Lease No. (API#) 30-015-41641 LOCATION OF RELEASE	port
Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077 Facility Name Myox 32 State #001H Facility Type Tank Battery Surface Owner State Mineral Owner Lease No. (API#) 30-015-41641	
Facility Name Myox 32 State #001H Facility Type Tank Battery Surface Owner State Mineral Owner Lease No. (API#) 30-015-41641	
Surface Owner State Mineral Owner Lease No. (API#) 30-015-41641	
LOCATION OF RELEASE	
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County O 32 25S 28E Feet from the North/South Line Feet from the Eddy	
Latitude 32 04.458 Longitude 104 05.434	
NATURE OF RELEASE	
Type of Release Volume of Release 12bbls of oil Volume Recovered 10bbls od Oil and produced water 30bbls of produced water 30bbls of produced water	
Source of Release Date and Hour of Occurrence Date and Hour of Discovery	
Water tank 03-07-2014 03-07-2014 10:30am	
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required ☐ Mike Bratcher - NMOCD	
By Whom? Michelle Mullins Date and Hour 03-11-2014 06:58am	
Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.	
☐ Yes ⊠ No	800 appear
If a Watercourse was Impacted, Describe Fully.*	
Describe Cause of Problem and Remedial Action Taken.*	i
Water tank ran over due to water pump malfunction and high water alarm transducer was shut in. Repaired the water pump and opened the transducer.	
Describe Area Affected and Cleanup Action Taken.*	
Initially 12bbls of oil and 30bbls of produced water were released. We were able to recover 10bbls of oil and 30bbls of produced water with a vacuum	
truck. The spill was contained inside the lined facility. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been	1
steam cleaned and we has replaced with fresh gravel as necessary. This location has been returned to its prior condition.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and	
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger	
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability	. [
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other	n
federal, state, or local laws and/or regulations.	
OIL CONSERVATION DIVISION	***************************************
Signature:	
Printed Name: Robert Grubbs Jr. Approved by District Supervisor:	
Title: Senior Environmental Coordinator Approval Date: 3/24/14 Expiration Date: NA	
Attached L	
* Attach Additional Sheets If Necessary	