

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

APR 17 2014

Form C-141  
Revised October 10, 2003

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC

### Release Notification and Corrective Action

*nHMP14/12136548* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company: Linn Operating <i>269324</i>	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: JL Keel B #10	Facility Type: Injection	
Surface Owner: Federal	Mineral Owner:	API No.: 30-015-05110

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	08	17S	31E	660	North	1980	East	Eddy

Latitude: 32.85446 Longitude: -103.88899

### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 5 bbls	Volume Recovered: 5 bbls
Source of Release: Fiber glass pipeline	Date and Hour of Occurrence: 04/13/2014	Date and Hour of Discovery: 04/13/2014 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour 04/15/2014 0715	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: received alarm for pump dwn at keel west water station noticed psi on header and control panel lower than usual noticed line 4 psi drop quick closed header line #4 started walking out lines going west to find leak found two leaks on the same trunk line north 100' of the Keel B #10

Describe Area Affected and Cleanup Action Taken.\*: first leak on line is 5 X 5 second leak is located about 400' east of the Keel B # 10 on the same right of way spill is 5 X 5, had crew digging out line and found that line was dripping from collar on both spots

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

### OIL CONSERVATION DIVISION

Signature: *Brian Wall*

Printed Name: Brian Wall

Title: Construction Foreman II

E-mail Address: bwall@linenergy.com

Date: 04/16/2014

Phone: 806-367-0645

Approved by District Supervisor: *[Signature]*

Approval Date: *5/1/14*

Expiration Date: *NA*

Conditions of Approval:

Attached ☐

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule & Guidelines, &  
like approval by BLM. **SUBMIT REMEDIATION  
PROPOSAL NO LATER THAN:**

*6/1/14*

*2RP-2275*