

UNITED STATES ^{Artesia, NM 88210}
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR

TXO Production Corp.

3. ADDRESS OF OPERATOR

900 Wilco Bldg., Midland, TX 79701

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: *1650 FNL & 1980 FEL*

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☒

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other) _____

SUBSEQUENT REPORT OF:

☐

☐

☐

☐

☐

☐

☐

☐

☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TOH w/2 3/8" tbg and UNI 6 pkr.

TIH w/GR & junk basket to 10100'.

TIH w/free pt tool (Est TOC 3850').

Set 4 1/2" CIBP @ 10100'. Dump 35' cmt.

Set 10 sx cmt @ 10020' (in 4 1/2').

Set 10 sx cmt @ 9225' (in 4 1/2').

Set 10 sx cmt @ 7300' (in 4 1/2').

Set 10 sx cmt @ 5750' (in 4 1/2').

Cut & pull 4 1/2 @ 3800' (50' above free pt).

Set 35 sx cmt @ 3850' (on 4 1/2 stub).

Tag TOC (app. 50' in OH).

Set 35 sx cmt @ 3245' (at 8 5/8 shoe).

Tag TOC (app 50' in 8 5/8).

Set 35 sx cmt @ 508' (in 8 5/8). Set ~~10 sx~~ @ surface.

Subsurface Safety Valve: Manu. and Type _____

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

Dale D. Lovely

TITLE

Engineer

DATE

July 9, 1985

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

11-14-85

CONDITIONS OF APPROVAL, IF ANY: