
Submit 1 Copy To Appropriate District State of New Mexico	Form C-103		
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District 11 – (575) 748-1283	Revised July 18, 2013 WELL API NO. 30-005-63628		
811 S. First SL, Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease		
District III ~ (505) 334-6178 1220 South St. Francis Dr.	STATE FEE		
District IV ~ (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. VO-2925		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name Trailblazer ANL State		
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other	8. Well Number #3		
2. Name of Operator Hanson Operating Company, Inc.	9. OGRID Number 009974		
3. Address of Operator	10. Pool name or Wildcat		
P O Box 1515, Roswell, NM 88202	Acme San Andres Southeast		
4. Well Location			
Unit Letter A : 990 feet from the North line and 660	feet from the <u>East</u> line		
Section 11 Township 8 South Range 27 Ea 11. Elevation (Show whether DR, RKB, RT, GR, etc.			
3974' GL			
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data		
NOTICE OF INTENTION TO: SUE	SEQUENT REPORT OF:		
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DR			
PULL OR ALTER CASING D MULTIPLE COMPL CASING/CEMEN	T JOB		
CLOSED-LOOP SYSTEM	·		
 Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Co proposed completion or recompletion. 	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of CONDITIONS OF APPROVAL ATTACHED		
Propose to Plug and Abandon the well as follows:	Approval Granted providing work is		
1. MIRU. Set cement tanks. Pull tubing.	Completed by the second		
2. Set CIBP at 2100' with 35' cement cap.	Completed by Lune 17 the 2015		
3. Circulate hole with 10# brine and 12.5 ppb salt water gel.	<u> </u>		
4. Perforate casing at 1164' with 4 holes.			
 Squeeze 25 sacks cement for solid 100' plug inside and outside 5 1/2" casing. Shut down for 2-3 hours. WOC. Tag cement plug. 			
7. Perforate casing at 400' with 4 holes.			
8. Squeeze 100 sacks cement to surface for solid 400' plug inside and outside 5 '/' o	casing.		
9. Set Dry Hole Marker.			
10. Clean and remediate location.			
Spud Data: 12/29/2003 Big Balance Data: 3/17/2004			
Spud Date: Rig Release Date: 3/17/2004			
I hereby certify that the information above is true and complete to the best of my knowledge	ze and belief		
SIGNATURE Carol & Smith TITLE Production Analyst	DATE <u>5/6/2014</u>		
Type or print name <u>Carol J. Smith</u> E-mail address: <u>hanson@dfn.co</u>	m PHONE: <u>575-622-7330</u>		
For State Use Only	· • •		
Conditions - 6 Ann Cond (if ann)	W150 DATE June 17, 2014		
A Hecked COA's			

. . .



	WELLBORI	E DIAGRAM		
WELL NAME	Trailblazer ANL State #3	FIELD Ac	me San Andres SE	
LOCATION 990' FNL & 660' FEL, A-Section 11-8S-27E, Chaves County, New Mexico				
ĞL	3974' ZERO	KB	йн нэрээлэл элэн элэн элэн элэн элэн элэн	
SPUD DATE	12/29/2003	COMPLETION DATE	3/17/2004	
COMMENTS:	API #30-005-63628	 Subsection of Subscription Statistics - Constraints 		
		in and the second s		
14 3/4" Hole				
		CASING PF	OGRAM	
	i a Citar Anna Anna	11 3/4" 42#	422'	
i se		8 5/8" 24#	1114'	
i. S		5 1/2" 17#, 15.5#	6890'	
11" Hole				
Squeeze 100 Sacks Cem	ent	11 3/4" at 422 with 400 Sacks Cement C	Sirculated	
400' Plug Inside/Outside		Squeeze Perfs at 400' 4 Holes		
Casing				
			·	
7.7/8" Hole		8 5/8" at 1114' with 500 Sacks Cement	Circulated	
			FTER	
Squeeze 25 Sacks Cemer		Squeeze Perfs at 1164 4 Holes	La Carlo Car	
100' Plug Inside/Outside C		TOC 1350 CBL		
CIBP at 2100'	i i i	San Andres		
35' Cement Cap		Perfs: 2168'-2184' 12:holes		
Retainer at 2250'				
			•	
		Squeeze Perfs 2325-2328 12 Holes with 450 Sacks Cement		
CIBP: at: 2350				
		TOC 4064 CBL	, ·	
			,	
CIBP at 5300			-	
35' Cement Cap	!			
		Wolfcamp,		
Squeezed with 225 Sacks		Perfs: 5616'-5630' 56 Holes		
		Cisco		
		<u>Cisco</u> Perfs: 6204: 629 <u>4</u> : 104 Holes		
		<u>Mississippian</u>		
		Perfs: 6524-6618' 126 Holes		
PBTD 6880'		en normal de la Bernard de la Cardador de la Contra do Contra de Contra de Contra de Contra de Contra de Contra		
		5 1/2" at 6890 with 600 Sacks Cement	Not to Scale	
	TD 6890'		5/6/2014	

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT
Operator: Hanson Operating Co.
Well Name & Number: Tralskyer All Skite # 3
API #: 30-00563628

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE:

APPROVED BY:

.

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - o Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing
 must be cut and pulled with plugs set at these depths or casing must be perforated and cement
 squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).