Form 3160-5 (August 2007) • UNITED STATES NM OIL CONSERVATION DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM25481			
SUNDRY NOTICES AND REPORTS ON WELLS 2 8 2014 Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals RECEIVED						
				6. If Indian, Allottec or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agre	ement, Name and/or N	
I. Type of Well ☐ Oil Well 🖾 Gas Well 🗖 Other				8. Well Name and No. RIO PECOS KO FEDERAL COM 1		
2. Name of Operator Contact: LAURA WATTS YATES PETROLEUM CORPORATIONE-Mail: laura@yatespetroleum.com				9. API Well No. 30-015-22899		
3a. Address 3b. Phone N 105 SOUTH FOURTH STREET Ph: 575-7 ARTESIA, NM 88210 Fx: 575-7			748-4272 WILDCAT; BC		10. Field and Pool, or WILDCAT; BON	Exploratory IE SPRING
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, and State		
Sec 28 T18S R27E NENE 660FNL 1300FEL					EDDY COUNTY, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	D INDICATE N	ATURE OF	NOTICE, RI	EPORT, OR OTHEI	R DATA
TYPE OF SUBMISSION	TYPE OF ACTION					
	Acidize	Deepei		Producti	on (Start/Resume)	□ Water Shut-Of
Notice of Intent	D Alter Casing	🗖 Fractur		🗖 Reclama		Well Integrity
Subsequent Report	Casing Repair	🗖 New C	New Construction		lete	□ Other
Final Abandonment Notice	🗖 Change Plans	🗖 Plug ar	d Abandon	Tempora	orarily Abandon	
	Convert to Injection	Convert to Injection 🛛 Plug Back 🗖 Wate		🗖 Water D	isposal .	
 MIRU WSU and all safety et POOH with existing product Run a gauge ring and junk Class H cement from 6,682 ft to perforations. Perforate Bone Spring 6,60 Set packer at 6,500 ft. Breat gelled IC HCL. Drop 50 7/8 into the perforations with 200 bbls Flow the well back until it di 	tion equipment. basket to 6,930 ft. Set a to 6,922 ft. This will place 00 ft to 6,630 ft (31 holes). akdown and acidize the p ch 1.3 SG RCN ballsealer	CIBP at 6,922 ft a plug over the erforations with rs spaced evenl	5000 gailons / throughout	ith 25 sx of Earphane 20 percent acid. Over fil	ush	DAYS TNESS IG BAC
S(2) Accessed to	.	Provide.			NDITIONS (
14. I hereby certify that the foregoing is		250432 verified b	the BLM We	II Information o the Carlsba	System J	· · · · · · · · · · · · · · · · · · ·
Name (Printed/Typed) LAURA WATTS			Title REG REPORTING TECHNICIAN			
LAUKA W					APPRN	
Signature (Electronic St	ubmission)	Da	te 06/23/2	014	<u>A NI A ANNI M</u>	
· · ·	ubmission) THIS SPACE FO				F	
· · ·		R FEDERAL (14 Date
Signature (Electronic S	THIS SPACE FO	R FEDERAL (T not warrant or subject lease	OR STATE	OFFICE US	AUG 22 20 PR Swars	
Signature (Electronic Signature (Electronic Signature Approved By and a straight of a	THIS SPACE FO	R FEDERAL (not warrant or subject lease O crime for any person	DR STATE	OFFICE US	AUG 22 20 PR Swass REAU OF LAND MAR	AGEMENT

Additional data for EC transaction #250432 that would not fit on the form


32. Additional remarks, continued


Production Department and turn the well over.

Wellbore schematics attached

. ī

٦





. •.

Conditions of Approval

Yates Petroleum Corporation Rio Pecos KO Com - 01 API 3001522899, T18S-R27E, Sec 28 August 22, 2014

1. Step 3 plug – Tag Wolfcamp plug at 6870 or higher.

- 2. A new "Well Location and Acreage Dedication Plat" (NMOCD Form C-102) is required with the notice of intent package when opening another pay zone.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Subject to like approval by the New Mexico Oil Conservation Division.
- 5. <u>Notify BLM 575-200-7902 Eddy Co. as work begins</u>. <u>Some</u> procedures are to be witnessed. If there is no response, call 575-361-2822, leave a voice mail with the API#, workover purpose, and a call back phone number
- 6. Surface disturbance beyond the existing pad must have prior approval.
- 7. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 8. Functional H_2S monitoring equipment shall be on location.
- 9. 3000 (3M) Blow Out Prevention Equipment to be used. All BOPE and workover procedures shall establish fail safe well control. Ram(s) for the work string(s) used is required equipment. Manual BOP closure system including a blind ram and pipe ram(s) designed to close on all (hand wheels) equipment shall be installed regardless of BOP design. Function test the installed BOPE to 500psig when well conditions allow. Related equipment, (choke manifolds, kill trucks, gas vent or flare lines, etc.) shall be employed when needed for reasonable well control requirements.
- 10. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 11. The BLM PET witness is to run tbg tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.
- 12. Set cement plugs to cover a minimum of 100ft plus 10ft for every 1,000ft from the bottom of the plug, rounding the number of necessary sacks up to the nearest 5 sacks. Never use less than 25sx. Examples: A cement plug set at 8000 in 7" casing would require a min of 35sx. A 25sx plug in 5 ¹/₂" casing should cover 250ft, which may exceed 100ft plus 10ft per 1000ft.

- 13. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.
- 14. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 15. After setting the top plug and before perforating, perform a BLM PET witnessed (charted) casing integrity test of 500 psig. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry for this workover.
- 16. File intermediate **subsequent sundry** Form 3160-**5** within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 17. Submit the BLM Form 3160-4 **Recompletion Report** within 30 days of the date all BLM approved procedures are complete.
- 18. Workover approval is good for 90 days (completion to be within 90 days of approval). A legitimate request is necessary for extension of that date.

An inactive/shut-in well bore is a non-producing completion that is capable of "beneficial use" i.e. production in **paying quantities** or of service use.

- 19. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5 (the original and 3 copies) before 07/15/2015.
- 20. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment.

PRS/ CRW 020314

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil_and_gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.