

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

OCT 17 2014

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB14293 3:3358

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: James Ranch Unit #48	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-27791

LOCATION OF RELEASE

Unit Letter M	Section 12	Township 22S	Range 30E	Feet from the 900	North/South Line South	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.402359 Longitude W 103.842167

NATURE OF RELEASE

Type of Release: Crude oil and Produced Water	Volume of Release: 6 Bbls. Oil and 73 Bbls. Produced water	Volume Recovered: 2 Bbls. Oil and 56 Bbls water
Source of Release: Produced water tank	Date and Hour of Occurrence: 10/15/14 time unknown	Date and Hour of Discovery: 10/15/14 at approximately 10:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Mike Bratcher and Heather Patterson BLM Jim Amos	
By Whom? Tony Savoie	Date and Hour: 10/15/14 at 3:25 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*The water transfer pump failed to start due to blow fuses in the control panel. The fuses were replaced and the pump was returned to normal operation.

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 2400 sq.ft. of earthen containment around the production tanks. The free standing fluid was recovered and the tanks were washed down. This is the second reportable spill around the tanks. The tank battery will be re-located on-site or the production will be routed to another facility, the tanks will be removed and the area impacted by the release will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Tony Savoie	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <u>Mike Bratcher</u>	
Title: Waste Management and Remediation Specialist	Approval Date: 10/20/14	Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	
Date: 10/17/2014	Phone: 432-556-8730	
SUBMIT REMEDIATION PROPOSAL NO		

* Attach Additional Sheets If Necessary

LATER THAN: 10/20/14

See A150; 2RP-1142

2RP-2556