

District I
1635 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
100 Rio Brazos Road, Aztec, NM 87410
District IV
20 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Electra Federal #006	Facility Type	Flow line
Surface Owner	Federal	Mineral Owner	API No. 30-015-34708

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	15	17S	30E					Eddy

Latitude N 32.83785° Longitude W 103.96420°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	2 bbl of oil, 10 bbls of produced water	Volume Recovered	1 bbl of oil, 8 bbls of produced water
Source of Release	Steel flow line	Date and Hour of Occurrence	10/17/2013	Date and Hour of Discovery	10/17/2013 @ 8:00 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Michelle Mullins	Date and Hour 10/28/2013 @ 7:42 am			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT

JUN 06 2014

Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the steel line due to corrosion. Shut in well and replaced the joint of steel pipe.



RECEIVED

Describe Area Affected and Cleanup Action Taken.*

Initially an estimated 2 bbls of oil and 10 bbls of produced water were released from a corroded 3" steel line. We were able to recover 1 bbl of oil and 8 bbls of produced water with a vacuum truck. The spill area is located in the pasture. BBC completed remediation in accordance with the remediation plan approved by Mike Bratcher of NMOCD in a meeting on 04/01/2014 and approved by Mike Burton of the BLM via email on 04/08/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Robert Grubbs	Approval Date: 6/6/14	Expiration Date: NA
Title: Senior Environmental Coordinator	Conditions of Approval: Final	
Email Address: rgrubbs@econcho.com	Attached <input type="checkbox"/>	
Date: 6-6-14	Phone: (432) 661-6601	

* Attach Additional Sheets If Necessary

2RP-2039