Form 3160.5 (March 2012)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB No. 1004-0137 Expires: October 31, 2014

5. Lease Serial No. NM-36975

•				14141 00010		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or	Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well				8. Well Name and No.		
Oil Well Gas Well Other 2. Name of Operator				Salt Draw "28" Federal No. 1 9. API Well No.		
Fasken Oil-and Ranch, Ltd.				30-015-26142		
3a. Address 6101 Holiday Hill Road Midland, TX 79707		3b. Phone No. (include area 432-687-1777	code)	Field and Pool or ESalt Draw; Atoka (Ga	•	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1980 FNL & 660 FEL, Sec. 28, T24S, R28E				11. County or Parish, State Eddy, New Mexico		
I2. CHEC	K THE APPROPRIATE BC	X(ES) TO INDICATE NATU	IRE OF NOTIC	E, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION		7	ΓΥΡΕ OF ACTI	ON		
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	_	iction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair	New Construction		mplete	Other	
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	· ·	orarity Abandon Disposal		
whether to plug and abandon this wand proposed Temporary Abandonr CIBP mu5t Sement on top	nent wellbore diagrams. Be 50 — (c		ρρ mos	t perfu	0/25=	
				record 18		
14. I hereby certify that the foregoing is to	ue and correct. Name (PiRE	CEIVED	NMOCI		0115	
Kim Tyson		Title Regula	atory Analyst	MAK	ONED	
Signature / Lim Dam		Date 09/05/	/2014 - 🕊	ACCEPTED F	OR RECORD	
	THIS SPACE	FOR FEDERAL OR S	TATE OF	ICE USE	100	
Approved by		Title	,	NOV	May	
Conditions of approval, if any, are attached hat the applicant holds legal or equitable t intitle the applicant to conduct operations	tle to those rights in the subject			BUREAU OF LAN CARLSBIO	D MANAGEMENT FIELD OFFICE	
Title 18 U.S.C. Section 1001 and Title 43	ILS C Section 1212 make ita	crime for any person knowingly	and willfully to	make to any denartment	or agency of the United States and	, false

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Recommended Procedure Salt Draw Fed"28" No. 1 1980' FNL & 660' FEL Sec 28, T24S R28E **AFE NA**

OBJECTIVE:	Temporary Abandonment		
WELL DATA:			
20" 106.5# K-55 ST&C casing: 13-3/8" 54.5#K55 ST&C casing: 9-5/8"43.5#&53.5# N-80,S-95,&P-110 csg: 5-1/2" 23# N-80 & P-110 Liner:	Set at 600'. Cmt w/ 2405 sx + 7 yds of gravel to surface Set at 2540'. Cmt w/ 3600 sx "C" to surface Set at 9800'. Cmt w/ 1575 sx. TOC 5730' by TS Set @ 13,450' to 9,313'. Cmt w/ 1650 sx to top of liner (0.0211 bbl/ft)		
Tubing:	(See WB diagram and 1-26-12 (tbg) & 12-17-12 (rods) pull rpts): Bull plug (0.45'), 3.5" Mother Hubbard Slotted gas anchor (31.0'), 2-3/8" x 9-5/8" TAC (35K shear) (2.90'), 2-3/8" cup type SN (1.10'), 266 jts 2-3/8" EUE AB modified N-80 tubing (8492.24'). EOT 8543,.22' KB.		
Perforations: Cmt Plug: CIBP: Perforations: CIBP: Perforations:	2 nd Bone Spring 8594'-8628' (69h, 2spf, 60 ⁰ ph, 0.41" EHD) (12-14-11) 9182'-9850' w/ 848' cement (125 sx "H") (12-13-11) 11,500' with 4sx "H" (52') cement (12-10-11) Atoka/Strawn: 11,566'-11,572', 11,604'-14', 11,660'-11,667' 45 holes, 11,690' with 7' cement (3-14-09) Atoka/Strawn: 11,695'-704'; 11,708'-14'; 11,720'-30', 11759'-63' (51 total holes) 12,250' with 35' cement Morrow: 12,625'-45'; 12,663'-68'		
TD: PBTD:	13,610' 9182' with frac sand fill to 8989'		


- 1. Notify OCD of intent to rig up and start workover. Need to give 48 hours notice prior to starting work. Make sure we have a pit permit issued prior to starting this workover.
- 2. Receive 250 bbl steel half-frac workover tank with gas buster, 7-1/6" x 10K hydraulic BOP with 11" 10K X 7-1/16" adaptor spool with 2-3/8" pipe rams and blind rams.
- 3. RUPU. Build steel flowline from wellhead to blow down tank. Bleed pressure off tubing and tubing/casing annulus to blowdown tank.
- 4. POW laying down 1-1/4"x26' PR / 1-1/2"x14' liner, 1- 7/8" N-97 pony rod (8.0'), 128-7/8" N-97 rods, 204-3/4" N-97 rods, 13-1.5" Flexbar C sinker bars, 21k Shear tool, 1-1.5" Flexbar C sinker bar, 1-2"x1.25"x24' RXBM pump.
- 5. NDWH and remove 11" wrap around, NU 11" 10K X 7-1/16" 10K spool and NU 7-1/16" 10K hydraulic BOP. (NDWH and NU DSA 11" 10M x 11" 5M, Spool 11" 5M x 11" 3M x 14" tall, BOP 11", 3M, 2-3/8" pipe rams and blind rams: per 12-6-11 WO report summary AFE 2321).
- 6. Release TAC, POW with 266 its 2-3/8" EUE 8rd AB modified N-80 tubing, SN, TAC, 3.5" Mother Hubbard Slotted Gas Anchor, Bull Plug.
- 7. RU Gray WL and full lubricator. RIW with 8-3/8" OD gauge ring (53.5# 9-5/8" surf-6009' 8.379" drift, 43.5# too 9800' 8.599" drift) and junk basket to 8550'. POW with gauge ring, and RIW with 9-5/8" CIBP and set @ 8,500'. Dump 14 sx (35') "H" cement on CIBP. RDWL.


9. RIW with 2-3/8" notched collar, SN and 2-3/8" EUE 8rd AB mod N-80 tubing to GBP @ 8550'. Establish circulation with pump truck. Circulate well with fresh water containing to GBP @ 8550'. oxygen scavenger, and inhibitor.

- 10. ND BOP and NUWH.
- 11. Call BLM representative and set up a MIT test time and date. Run MIT test on casing to 500 psi for 30 minutes with chart recorder. Release pressure. Shut well in as Temporarily Abandoned.

CWB 9-5-14

M:\Common\WELLFILE\S\Salt Draw 28 Fed 1\Engineering\SaltDraw28Fed1 TA proc 9-5-14.doc





BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 6 months ending 05/05/2015 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Salt Draw 28 Federal 1

- 1. Well is approved to be TA/SI for a period of 12 months or until 05/05/2015
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 05/05/2015
- 4. COA's met at this time.