
(Warch 2012)	-	UNITED STATES			.	FORM APPROVED OMB No. 1004-0137		
DEPARTMENT OF THE IN BUREAU OF LAND MANAG						Expires: October 31, 2014 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS						NMNM 08277		
Do not u	use this form for ed well. Use F	or proposals to	o drill or to re	enter an		6. If Indian, Allottee o	or Tribe Name	
SUBMIT IN TRIPLICATE Other instructi				age 2.	ĺ	7. If Unit of CA/Agre	ement. Name and/or No.	
1. Type of Well   Image: Oil Well Image: Gas Well Other				. ,		8. Well Name and No Saladar Federal #1		······
2. Name of Operator MNA Energy, LTD Co.,				9. API 30-015			API Well No -015-24181	
3a. Address 106 W Alabama, Hobbs, NM 88242			3b. Phone No. (include area code) 10.			10. Field and Pool or Saladar: Yates	Exploratory Area	
4. Location of Well (Foolage, Sec., T.R., M., or Survey Description, 1315 FSL & 1325 FWL: Sec 33, T20S, R28E			) Eddy			11. County of Parish, Eddy	State	
	12. CHECK THE	APPROPRIATE BO	X(ES) TO INDIC	ATE NATURE	E OF NOTIC	E, REPORT OR OTH	IER DATA	
TYPE OF SUBMIS	SSION		TYPE OF ACTION			ON	· · · · · · · · · · · · · · · · · · ·	
Notice of Intent		Acidize Alter Casing	Deepen Fracture	Treat	pursuing .	ction (Start/Resume)	Water Shut-Off	
Subsequent Report		Casing Repair	New Cor	struction		nplete	Other	
Final Abandonment	نسبب ا	Change Plans Convert to Injection	Plug and Plug Bac			orarily Abandon Disposal		
Attach the Bond under following completion testing has been comp determined that the sit	pen directionally or re r which the work will of the involved opera- steted. Final Abandon te is ready for final in	ecomplete horizontall be performed or pro- ations. If the operation nment Notices must b spection.)	y, give subsurface vide the Bond No. on results in a mult	locations and on file with B iple completio	measured and LM/BIA. Re n or recomple	d true vertical depths equired subsequent re etion in a new interva	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator	ionies, days id once has ERV
the proposal is to deep Attach the Bond unde following completion testing has been comp	pen directionally or re r which the work will of the involved opera- steted. Final Abandon te is ready for final in	ecomplete horizontall be performed or pro- ations. If the operation nment Notices must b spection.)	y, give subsurface vide the Bond No. on results in a mult	locations and on file with B iple completio	measured and LM/BIA. Re n or recomple	d true vertical depths equired subsequent re etion in a new interva	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS	id once has TRIC
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a Install 31/2" by 2" swage Using a kill truck, pump	pen directionally or re of the involved opera- stated. Final Abandon te is ready for final in Abandon this well and tubing e and valve 15 bbls water (dout	complete horizontally be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r	y, give-subsurface vide the Bond No, on results in a mult e filed only after a	locations and on file with B iple completio Il requirement	measured and LM/BIA. Ro n or recomple s, including r	d true vertical depths ( equired subsequent re etion in a new interva reclamation, have beet	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC <b>01</b>	id once has TRIC
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a install 31/2" by 2" swage	pen directionally or re r which the work will of the involved oper- oleted. Final Abandor te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa	complete horizontally 1 be performed or pro- ations. If the operation mient Notices must b spection.) as follows: ble capacity) while r ce to TD.	y, give subsurface vide the Bond No. or results in a mult be filed only after a monitoring backs	locations and on file with B iple completio II requirement	measured and RLM/BIA. Ro n or recomple s, including r injectability	d true vertical depths equired subsequent re etion in a new interva reclamation, have been and test for holes in	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC <b>01</b>	ed once has ERV/ STRIC
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sit We propose to Plug and POH laying down rods a install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fi	pen directionally or re r which the work will of the involved oper- oleted. Final Abandon te is ready for final in I Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged.	complete horizontally be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we we	y, give subsurface vide the Bond No, or results in a mult be filed only after a monitoring backs vill WOC 3 hrs an	locations and on file with B iple completio Il requirement ide to insure d fill casing v	measured and NLM/BIA. Ro n or recomple s, including r injectability with cernent	d true vertical depths equired subsequent re etion in a new interva reclamation, have been and test for holes in to surface.	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC <b>01</b> n casing <b>RECEI</b>	ed once has ERV/ STRIC
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a Install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fi If the hole stays full we v	pen directionally or re r which the work will of the involved oper- sletted. Final Abandon te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. d, a dry höle marker	complete horizontally be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we we	y, give subsurface vide the Bond No, or results in a mult be filed only after a monitoring backs vill WOC 3 hrs an	locations and on file with B iple completio Il requirement ide to insure d fill casing v	measured and NLM/BIA. Ro n or recomple s, including r injectability with cernent	d true vertical depths of equired subsequent re- etion in a new interva reclamation, have been and test for holes in to surface. ated as required by	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC <b>01</b> n casing <b>RECEI</b> the BLM	ed once has ERV/ STRIC
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a Install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fi If the hole stays full we hole After this well is plugged	pen directionally or re r which the work will of the involved oper- sletted. Final Abandon te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. d, a dry höle marker	complete horizontally be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we we	y, give subsurface vide the Bond No, on results in a mult be filed only after a monitoring backs vill WOC 3 hrs an d the location cle RECLAMA	locations and on file with B iple completio Il requirement ide to insure d fill casing v	measured and NLM/BIA. Ro n or recomplo s, including r injectability with cement then remedi	d true vertical depths equired subsequent re- etion in a new interva reclamation, have been and test for holes in to surface. ated as required by SEE ATTA	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC 01 n casing RECET the BLM	tones, days donce has ERV/ STRIC 2014
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fi If the hole stays full we w After this well is plugged See wellbore diagram at	pen directionally or re r which the work will of the involved oper- sletted. Final Abandon te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. d, a dry höle marker	complete horizontally be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we we	y, give subsurface vide the Bond No. or results in a mult be filed only after a monitoring backs vill WOC 3 hrs an d the location cle RECLAMA A	locations and on file with B iple completio Il requirement ide to insure d fill casing v ared of junk TION PROC TTACHED	measured and NLM/BIA. Ro n or recomplo s, including r injectability with cement then remedi	d true vertical depths dequired subsequent re- equired subsequent re- etion in a new interva reclamation, have been and test for holes in to surface. ated as required by SEE ATTA CONDITIC	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC <b>01</b> n casing <b>RECEI</b> the BLM	tones, days donce has ERV/ STRIC 2014
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fi If the hole stays full we w After this well is plugged See wellbore diagram at	pen directionally or re r which the work will of the involved oper- oleted. Final Abandon te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. d, a dry hole marker ttached	complete horizontality 1 be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we w will be installed and will be installed and	y, give subsurface vide the Bond No. on results in a mult be filed only after a monitoring backs vill WOC 3 hrs an d the location cle RECLAMA A	locations and on file with B iple completio Il requirement ide to insure d fill casing v ared of junk TION PROC TTACHED	measured and NLM/BIA. Ro n or recomple s, including r injectability with cernent then remedi CEDURE	d true vertical depths equired subsequent re- etion in a new interva reclamation, have been and test for holes in to surface. ated as required by SEE ATTA	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC 01 n casing RECET the BLM	tones, days donce has ERV/ STRIC 2014
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sit We propose to Plug and POH laying down rods a Install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fp If the hole stays full we v After this well is plugged See wellbore diagram al	pen directionally or re r which the work will of the involved oper- oleted. Final Abandon te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. d, a dry hole marker ttached	complete horizontality 1 be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we w will be installed and will be installed and	y, give subsurface vide the Bond No. on results in a mult be filed only after a monitoring backs vill WOC 3 hrs an d the location cle <b>RECLAMA</b>	locations and on file with B iple completio Il requirement ide to insure d fill casing v ared of junk TION PROC TTACHED	measured and BLM/BIA. Ro n or recomple s, including r injectability with cement then remedi CEDURE	d true vertical depths dequired subsequent re equired subsequent re etion in a new interva reclamation, have been and test for holes in to surface. ated as required by SEE ATTA CONDITIO	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC 01 n casing <b>RECEI</b> the BLM CHED FOR NS OF APPRO	venes, days donce has ERV/ STRIC 2014 VED
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sit We propose to Plug and POH laying down rods a Install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fp If the hole stays full we v After this well is plugged See wellbore diagram al	pen directionally or re r which the work will of the involved oper- oleted. Final Abandon te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. d, a dry hole marker ttached	complete horizontality I be performed or pro- ations. If the operation mment Notices must be spection.) as follows: Dele capacity) while r ce to TD. If cement falls we we will be installed and will be installed and correct. Name (Printed)	y, give subsurface vide the Bond No. on results in a mult be filed only after a monitoring backs vill WOC 3 hrs an d the location cle <b>RECLAMA</b> A DS Sec. 7 VTyped)	locations and on file with B iple completio Il requirement ide to insure d fill casing v ared of junk TION PROC TTACHED	measured and NLM/BIA. Ro n or recomple s, including r injectability with cement then remedi CEDURE	d true vertical depths equired subsequent re etion in a new interva reclamation, have been and test for holes in to surface. ated as required by SEE ATTA CONDITIC gance/	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC 01 n casing <b>RECEI</b> the BLM CHED FOR NS OF APPRO	venes, days donce has ERV/ STRIC 2014 VED
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a Install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fi If the hole stays full we to After this well is plugged See wellbore diagram at After the verify that the Phelps White Signature	pen directionally or re r which the work will of the involved oper- oleted. Final Abandon te is ready for final in d Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. d, a dry hole marker ttached	complete horizontality 1 be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we w will be installed and will be installed and	y, give subsurface vide the Bond No. on results in a mult be filed only after a monitoring backs vill WOC 3 hrs an d the location cle <b>RECLAMA</b> A DS Sec. 7 VTyped)	locations and on file with B iple completio Il requirement ide to insure d fill casing v ared of junk TION PROC TTACHED	measured and NLM/BIA. Ro n or recomple s, including r injectability with cement then remedi CEDURE	d true vertical depths equired subsequent re etion in a new interva reclamation, have been and test for holes in to surface. ated as required by SEE ATTA CONDITIC gance/	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC 01 n casing <b>RECEI</b> the BLM CHED FOR NS OF APPRO	venes, days donce has ERV/ STRIC 2014 VED
the proposal is to deep Attach the Bond unde following completion testing has been comp determined that the sil We propose to Plug and POH laying down rods a Install 31/2" by 2" swage Using a kill truck, pump Pump 25 sx class C to fi If the hole stays full we w After this well is plugged See wellbore diagram at After the diagram at After the curf. of 14. Thereby certify that the Phelps White	pen directionally or re rr which the work will of the involved oper- oleted. Final Abandon te is ready for final in I Abandon this well and tubing e and valve 15 bbls water (dout ill casing from surfa will call it plugged. It, a dry höle marker ttached	complete horizontality i be performed or pro- ations. If the operation ment Notices must be spection.) as follows: ble capacity) while r ce to TD. If cement falls we we will be installed and will be installed and THIS SPACE I mediane	y, give subsurface vide the Bond No. on results in a mult be filed only after a monitoring backs vill WOC 3 hrs an d the location cle RECLAMA A DS Sec. 7 VTyped) The FOR FEDER/	Iocations and on file with B iple completio Il requirement ide to insure d fill casing v ared of junk TION PROC TTACHED	measured and NLM/BIA. Ro n or recomple s, including r injectability with cement then remedi CEDURE	d true vertical depths dequired subsequent re equired subsequent re etion in a new interva reclamation, have been and test for holes in to surface. ated as required by SEE ATTA CONDITIC gance/	of all pertinent markers and 2 ports must be filed within 30 J. a Form 3160-4 must be file n completed and the operator <b>NM OIL CONSI</b> ARTESIA DIS DEC 01 n casing <b>RECEI</b> the BLM CHED FOR NS OF APPRO	venes, days donce has ERV/ STRIC 2014 VED

ł

7

# MNA Enterprises, LTD Co.



#### Well Bore Diagram

Well:	Salador Federal #14
API #	30-015-24181

### 7 5/8" 26.4# @ 82' 🖌

Proposed Plug Surface to TD

Yates@ 586

3 1/2" 9.3# J-55 and packer @ 600', cement circulated

Perforations @ 613-638'

No PBTD Recorded 4 1/2" 11.6# @ 660', Cement Circulated

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

#### Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.

3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.

4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon. **(9# brine is not mud)** 

5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.** 

8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.



# United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

#### **Reclamation Objectives and Procedures**

**Reclamation Objective:** Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

#### Jim Amos

Supervisory Petroleum Engineering Tech 575-234-5909, 575-361-2648 (Cell)

Solomon Hughes Natural Resource Specialist 575-234-5951 Cody Layton Supervisory Multi Resources 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Jeffery Robertson Natural Resource Specialist 575-234-2230

Duncan Whitlock Environmental Protection Specialist 575-234-5926

Linda Denniston Environmental Protection Specialist 575-234-5974

Douglas Hoag Civil Engineering Tech 575-234-5979