Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
. OMB NO. 1004-0135
Expires: July 31, 2010

R4	JREAU OF LAND MANAGEMENT				
SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			5. Lease Serial No. NMLC028978A	5. Lease Serial No. NMLC028978A	
			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well  ☐ Gas Well  ☐ Other				8. Well Name and No. PHOENIX 21 NC FEDERAL COM 1H	
Name of Operator     MEWBOURNE OIL COMPAN	HAN	9. API Well No. 30-015-41030-00-X1			
3a. Address P O BOX 5270 HOBBS, NM 88241	. (include area code) 03-5905	10. Field and Pool, or Exploratory SANTO NINO			
4. Location of Well (Footage, Sec., T		11. County or Parish, and State			
Sec 28 T18S R30E NENW 20		EDDY COUNTY, NM			
12. СНЕСК АРР	ROPRIATE BOX(ES) TO INDICATE	NATURE OF NOTICE	REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION		TYPE OF ACTION	V		
■ Notice of Intent	☐ Acidize ☐ Dee	pen Prod	luction (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing ☐ Frac		amation	■ Well Integrity	
☐ Subsequent Report		Construction Reco	omplete	<b>⊠</b> Other	
☐ Final Abandonment Notice	, —		porarily Abandon		
	☐ Convert to Injection ☐ Plug	Back Wat	er Disposal .	·	
Attach the Bond under which the worfollowing completion of the involved testing has been completed. Final At determined that the site is ready for f  Mewbourne Oil Company has	ally or recomplete horizontally, give subsurface it will be performed or provide the Bond No. or operations. If the operation results in a multiple pandonment Notices shall be filed only after all inal inspection.)  an approved APD for the above capticeted the APD for an additional 2 years.	n file with BLM/BIA. Required le completion or recompletion i requirements, including reclaments, and well that will expire of	I subsequent reports shall be n a new interval, a Form 316 ation, have been completed,  NM OIL CONTRACTOR	filed within 30 days 60-4 shall be filed once and the operator has	
If you have any questions plo	ase call 575-393-5905.  Previous approved  Provide approved  14/15	Condition	JAN SEE ATTACI CONDITION OVED FOR 12	26 2015 HED FOR BIOGLAPPROV	
14. Thereby certify that the foregoing is	true and correct			<u> </u>	
	Electronic Submission #283902 verifie For MEWBOURNE OIL COM mitted to AFMSS for processing by JEN	PANY, sent to the Carlsba NIFER MASON on 01/05/20	d 15 (15JAM0160SE)	1	
Name(Printed/Typed) JACKIE L	ATHAN	Title AUTHORIZED F	REPRESENTATIVE		
Signature (Electronic Submission)		Date 12/03/2014			
	THIS SPACE FOR FEDERA	AL OR STATE OFFICE	USE		
Approved By	Sphij Colp	Title FOR FIELD MANA	AGER	Date/20/15	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to conduct the applicant	Office CARLSBAD FIE	LD OFFICE			
		•			

# PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: | MEWBOURNE OIL COMPANY

LEASE NO.: LC028987A

WELL NAME & NO.: 1H-PHOENIX 21 NC FED COM

SURFACE HOLE FOOTAGE: 200'/N. & 1980'/W.

BOTTOM HOLE FOOTAGE | 330'/N. & 1980'/W. (Sec. 21)

LOCATION: | Section 28, T. 18 S., R. 30 E., NMPM

COUNTY: Eddy County, New Mexico

API: 30-015-41030

# The original COAs still stand with the following drilling modifications:

### I. DRILLING

### A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)

# **Eddy County**

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. Hydrogen Sulfide (H2S) monitors shall be installed prior to drilling out the surface shoe. If H2S is encountered in quantities greater than 10 PPM the well shall be shut in and H2S equipment shall be installed and flare line must be extended pursuant to Onshore Oil and Gas Order #6. After detection, the Hydrogen Sulfide area must meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
- 3. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works is located, this does not include the dog house or stairway area.

4. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well – vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

#### B. CASING

Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Wait on cement (WOC) time prior to drilling out for a primary cement job will be a minimum 18 hours for a water basin, 24 hours in the potash area, or 500 pounds compressive strength, whichever is greater for all casing strings. DURING THIS WOC TIME, NO DRILL PIPE, ETC. SHALL BE RUN IN THE HOLE. Provide compressive strengths including hours to reach required 500 pounds compressive strength prior to cementing each casing string. See individual casing strings for details regarding lead cement slurry requirements.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

Secretary's Potash Possible brine flows in the Salado and Artesia groups. Possible lost circulation in the Artesia group.

- 1. The 13-3/8 inch surface casing shall be set at approximately 360 feet (a minimum of 25 feet into the Rustler Anhydrite and above the salt) and cemented to the surface.
  - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.

- b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
- c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
- d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:
  - Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to potash.

Centralizers required through the curve and a minimum of one every other joint.

- 3. The minimum required fill of cement behind the 7 inch production casing is:
  - Cement to surface. If cement does not circulate, contact the appropriate BLM office.
- 4. The minimum required fill of cement behind the 4-1/2 inch production liner is:
  - ☐ Cement not required Port/Packer system to be used.
- 5. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

### C. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000** (**2M**) psi.
  - a. **For surface casing only:** If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.

- 3. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the 9-5/8 inch intermediate casing shoe shall be 3000 (3M) psi.
- 4. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
  - a. In potash areas, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. For all casing strings, casing cut-off and BOP installation can be initiated at twelve hours after bumping the plug. However, **no tests** shall commence until the cement has had a minimum of 24 hours setup time.
  - b. The tests shall be done by an independent service company utilizing a test plug **not a cup or J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).
  - c. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.
  - d. The results of the test shall be reported to the appropriate BLM office.
  - e. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
  - f. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.

#### D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

## E. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

JAM 011515