Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-00246
District III – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE S
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Santa 1 C, 1VIVI 07505	6. State Oil & Gas Lease No.
87505		
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Platt PA
PROPOSALS.)	LICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number
1. Type of Well: Oil Well	Gas Well Other P&A	4
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation	·	025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia,	NM 88210	Atoka; Glorieta-Yeso
4. Well Location		
Unit Letter M:	660 feet from the South line and	485 feet from the West line
	Township 18S Range 26E	NMPM Eddy County
Section 26	11. Elevation (Show whether DR, RKB, RT, GR, et	
	3333'GR	<i>C.)</i>
12 01 1	A CAL Deside Indicate Nickens (CNI)	Daniel an Other Date
12. Check	Appropriate Box to Indicate Nature of Notice	e, Report or Other Data
NOTICE OF I	NTENTION TO: SU	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		·
TEMPORARILY ABANDON	<u> </u>	RILLING OPNS. □ P AND A ⊠
PULL OR ALTER CASING	<u> </u>	
DOWNHOLE COMMINGLE .	_ ' '	NI JOB
CLOSED-LOOP:SYSTEM	J 7	
OTHER:	☐ OTHER:	·
9		
13. Describe proposed or con	apleted operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated date
	npleted operations. (Clearly state all pertinent details, a work). SEE RULE 19.15.7.14 NMAC. For Multiple C	
	work). SEE RULE 19.15.7.14 NMAC. For Multiple C	
of starting any proposed v	work). SEE RULE 19.15.7.14 NMAC. For Multiple C	
of starting any proposed v proposed completion or re	work). SEE RULE 19.15.7.14 NMAC. For Multiple C	ompletions: Attach wellbore diagram of
of starting any proposed of proposed completion or research 11/19/14 – Pumped 30 bbls brine of 11/20/14 – Tagged CIBP at 2730'.	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at
of starting any proposed of proposed completion or result of the starting any proposed of the starting and star	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and 60 or Section 19.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing.
of starting any proposed of proposed completion or result of the starting any proposed of the starting and star	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing.
of starting any proposed of proposed completion or result of the starting any proposed of the starting and star	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and 60 or Section 19.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing.
of starting any proposed of proposed completion or result of the starting any proposed of the starting and star	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED.
of starting any proposed of proposed completion or result of the starting any proposed of the starting and star	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 2- Spotted 50 sx Class "C" Neat cement. Calc TOC at 2- DP. Pumped 60 sx Class "C" Neat cement at 320' and 6ff wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 1258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgring of well bore only. The stretched pending receipt.
of starting any proposed of proposed completion or result of the starting any proposed of the starting and star	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgring of well bore only. The specific stretained pending receipt users Report of Well Plugging)
of starting any proposed of proposed completion or result of the starting any proposed of the starting and star	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgaing of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting any proposed of the starting and starting	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgring of well bore only. The specific stretained pending receipt users Report of Well Plugging)
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting any proposed of the starting and starting	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgaing of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting any proposed of the starting and starting	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgaing of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting any proposed of the starting and starting	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar.	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgaing of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under
of starting any proposed of proposed completion or result of 11/19/14 – Pumped 30 bbls brine of 11/20/14 – Tagged CIBP at 2730'. 1165'. Calc TOC at 943'. ND BC 12/8/14 – Dug out cellar and cut of	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-103 (Subseq which may be fou Forms, www.cmnt)	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgaing of well bore only. The specific specifi
of starting any proposed of proposed completion or result of 11/19/14 – Pumped 30 bbls brine of 11/20/14 – Tagged CIBP at 2730'. 1165'. Calc TOC at 943'. ND BC 12/8/14 – Dug out cellar and cut of	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-103 (Subseq which may be fou Forms, www.cmnt)	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sgaing of well bore only. The specific specifi
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting and proposed of the starting and proposed of the s	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-103 (Subseq which may be four Forms, www.cmnt). Rig Release Date:	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sging of well bore only. and is retained pending receipt uent Report of Well Plugging) and at OCD Web Page under destate.nm.us/ocd.
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting and proposed of the starting and proposed of the s	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-103 (Subseq which may be fou Forms, www.cmnt)	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sging of well bore only. and is retained pending receipt uent Report of Well Plugging) and at OCD Web Page under destate.nm.us/ocd.
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting and proposed of the starting and proposed of the s	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-103 (Subseq which may be four Forms, www.cmnt). Rig Release Date:	completions: Attach wellbore diagram of 5-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sging of well bore only. and is retained pending receipt uent Report of Well Plugging) and at OCD Web Page under destate.nm.us/ocd.
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting and proposed of the starting and proposed of the s	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-103 (Subseq which may be four Forms, www.cmnt). Rig Release Date:	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Spring of well bore only. 2015 on the service of
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting and proposed of the starting and proposed of the proposed of the starting and	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 5 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-103 (Subseq which may be fou Forms, www.cmnt) Rig Release Date:	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Spring of well bore only. 2015 on the state of the second second second second second second second at OCD Web Page under red. state.nm.us/ocd.
of starting any proposed of proposed completion or result of the starting any proposed of the proposed completion or result of the starting and proposed of the starting and proposed of the proposed of the starting and	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 2 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-to3 (Subseq which may be four Forms, www.cmnt Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sging of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under destate.nm.us/ocd. dige and belief. Supervisor DATE January 21, 2015
of starting any proposed of proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion of recompletion or recompletion of recompletion or recompletion of recompletion or recompletio	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 2 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-to3 (Subseq which may be four Forms, www.cmm). Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Signing of well bore only. The second is retained pending receipt users Report of Well Plugging) and at OCD Web Page under ed. state.nm.us/ocd. dige and belief. Supervisor DATE January 21, 2015
of starting any proposed opproposed completion or recompletion of recompletion or recompletion	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 2 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-to3 (Subseq which may be four Forms, www.cmm). Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sging of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under destate.nm.us/ocd. dige and belief. Supervisor DATE January 21, 2015
of starting any proposed opproposed completion or recompletion	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 2 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-to3 (Subseq which may be four Forms, www.cmm). Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sging of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under destate.nm.us/ocd. dige and belief. Supervisor DATE January 21, 2015
of starting any proposed opproposed completion or recompletion of recompletion or recompletion	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 2 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-to3 (Subseq which may be four Forms, www.cmm). Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Sging of well bore only. and is retained pending receipt users Report of Well Plugging) and at OCD Web Page under destate.nm.us/ocd. dige and belief. Supervisor DATE January 21, 2015
of starting any proposed opproposed completion or recompletion	work). SEE RULE 19.15.7.14 NMAC. For Multiple Cecompletion. down casing. NU BOP. Pumped 60 bbls brine. Set a 2 Spotted 50 sx Class "C" Neat cement. Calc TOC at 2 OP. Pumped 60 sx Class "C" Neat cement at 320' and off wellhead. Installed dry hole marker. Filled cellar. Approved for plu Liability under be of C-to3 (Subseq which may be four Forms, www.cmm). Rig Release Date: Rig Release Date: TITLE Regulatory Reporting	completions: Attach wellbore diagram of 25-1/2" CIBP at 2730'. 2258'. Spotted 25 sx Class "C" Neat cement at circulated to surface. Topped out casing. WELL IS PLUGGED AND ABANDONED. Signing of well bore only. The second is retained pending receipt users Report of Well Plugging) and at OCD Web Page under ed. state.nm.us/ocd. dige and belief. Supervisor DATE January 21, 2015