Form 3160-5 (August 2007)

UNITED STATES A DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

ARTESIA DISTRICT

FEB 06 2015

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an CEIVED abandoned well. Use form 3160-3 (APD) for such proposals CEIVED

NMNM130849

6. If Indian, Allottee or Tribe Name

abandoned we	o. It matain, Attouce	% ·			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agr	eement, Name and/or No.	
1. Type of Well Gas Well Oth		8. Well Name and No RIO BRAVO 7 B	8. Well Name and No. RIO BRAVO 7 B3NC FEDERAL 1H		
Name of Operator MEWBOURNE OIL COMPAN	Contact: JA	CKIE LATHAN pourne.com	9. API Well No. 30-015-42918-	9. API Well No. 30-015-42918-00-X1	
3a. Address P O BOX 5270 HOBBS, NM 88241		p. Phone No. (include area code) h: 575-393-5905		10. Field and Pool, or Exploratory DEADMAN DRAW	
4. Location of Well (Footage, Sec., T.		11. County or Parish	, and State		
Sec 7 T21S R25E SESW 225 32.487350 N Lat, 104.435664		EDDY COUNT	Y, NM		
12. СНЕСК АРРГ	ROPRIATE BOX(ES) TO IN	NDICATE NATURE OF N	NOTICE, REPORT, OR OTHE	ER DATA	
TYPE OF SUBMISSION.	TYPE OF ACTION				
Notice of Intent	☐ Acidize	□ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity	
	☐ Casing Repair	■ New Construction	☐ Recomplete	Other Drilling Operations	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	e e e e e e e e e e e e e e e e e e e	
13. Describe Proposed or Completed Ope	Convert to Injection	□ Plug Back	☐ Water Disposal	<u>.</u>	
Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for fine Mewbourne Oil Co. is currently system. Mewbourne requests	k will be performed or provide the operations. If the operation results andonment Notices shall be filed o nat inspection.) y permitted to run a 4 1/2" lint the following change:	Bond No. on file with BLM/BIA in a multiple completion or recoming after all requirements, included the requirements of the complete of the co	•	e filed within 30 days 60-4 shall be filed once	
Run 4 1/2" cemented liner with the same.	n packer type liner hanger @	6620'. Casing type and s	ize will remain	•	
Cement liner with: 210 sks Class "C" (60:40:0) w. Weight: 11.2#/gal, Yield: 2.97	/4% MPA5+1.2% BA10A+10 Cuft/sk	#/sk BA90+5%A10+0.65%	ESB3ATTAGHED F.	OR Approval	
Surfce, intermediate & produc	tion casing strings will remai	n the same.	CONDITIONS OF .		
्र व			Accepted for re	4/16/15	
14. I hereby certify that the foregoing is	Electronic Submission #290	OIL COMPANY, sent to the	e Carlsbad		
Name(Printed/Typed) JACKIE LATHAN		Title AUTHO	RIZED REPRESENTATIVE		
Signature (Electronic S	Submission)	Date 01/30/2	APPKUVE	<u>.U</u>	
organisme (Executonic e		FEDERAL OR STATE		15 /	
Approved By	· 	Title	1 James for	(AN EDALE TO	
Conditions of approval, if any, are attache			EUREAU OF LAND MAN CARLSEAD FIELD O	AGEMENT FICE	
ertify that the applicant holds legal or equivalent would entitle the applicant to condu	oject lease Office	UNINESPADITIEDO	1100		

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME: | Mewbourne Oil Company

LEASE NO.: NMNM-130849

WELL NAME & NO.: Rio Bravo 7 B3NC Federal 1H

SURFACE HOLE FOOTAGE: 0225' FSL & 2140' FWL BOTTOM HOLE FOOTAGE 0330' FNL & 2140' FWL

LOCATION: | Section 07, T. 21 S., R 25 E., NMPM

COUNTY: Eddy County, New Mexico

API: | 30-015-42918

The original COAs still stand with the following drilling modifications:

I. DRILLING

A. DRILLING OPERATIONS REQUIREMENTS

The BLM is to be notified in advance for a representative to witness:

- a. Spudding well (minimum of 24 hours)
- b. Setting and/or Cementing of all casing strings (minimum of 4 hours)
- c. BOPE tests (minimum of 4 hours)

⊠ Eddy County

Call the Carlsbad Field Office, 620 East Greene St., Carlsbad, NM 88220, (575) 361-2822

- 1. Operating has stated Hydrogen Sulfide (H2S) monitors shall be installed prior to drilling out the surface shoe. If H2S is detected in concentrations greater than 100 ppm, the Hydrogen Sulfide area shall meet Onshore Order 6 requirements, which includes equipment and personnel/public protection items. If Hydrogen Sulfide is encountered, provide measured values and formations to the BLM.
- 2. Unless the production casing has been run and cemented or the well has been properly plugged, the drilling rig shall not be removed from over the hole without prior approval. If the drilling rig is removed without approval an Incident of Non-Compliance will be written and will be a "Major" violation.
- 3. Floor controls are required for 3M or Greater systems. These controls will be on the rig floor, unobstructed, readily accessible to the driller and will be operational at all times during drilling and/or completion activities. Rig floor is defined as the area immediately around the rotary table; the area immediately above the substructure on which the draw works is located, this does not include the dog house or stairway area.

4. The record of the drilling rate along with the GR/N well log run from TD to surface (horizontal well – vertical portion of hole) shall be submitted to the BLM office as well as all other logs run on the borehole 30 days from completion. If available, a digital copy of the logs is to be submitted in addition to the paper copies. The Rustler top and top and bottom of Salt are to be recorded on the Completion Report.

B. CASING

Changes to the approved APD casing program need prior approval if the items substituted are of lesser grade or different casing size or are Non-API. The Operator can exchange the components of the proposal with that of superior strength (i.e. changing from J-55 to N-80, or from 36# to 40#). Changes to the approved cement program need prior approval if the altered cement plan has less volume or strength or if the changes are substantial (i.e. Multistage tool, ECP, etc.). The initial wellhead installed on the well will remain on the well with spools used as needed.

Centralizers required on surface casing per Onshore Order 2.III.B.1.f.

Wait on cement (WOC) for Water basin:

After cementing but before commencing any tests, the casing string shall stand cemented under pressure until both of the following conditions have been met: 1) cement reaches a minimum compressive strength of 500 psi at the shoe, 2) until cement has been in place at least <u>8 hours</u>. WOC time will be recorded in the driller's log. See individual casing strings for details regarding lead cement slurry requirements.

No pea gravel permitted for remedial or fall back remedial without prior authorization from the BLM engineer.

High Cave/Karst
Possibility of water flows in the San Andres
Possibility of lost circulation in the San Andres and Delaware
Abnormal pressure may be encountered within the 3rd Bone Spring Sandstone

A MINIMUM OF TWO CASING STRINGS CEMENTED TO SURFACE IS REQUIRED IN HIGH CAVE/KARST AREAS. THE CEMENT MUST BE IN A SOLID SHEATH. THEREFORE, ONE INCH OPERATIONS ARE NOT SUFFICIENT TO PROTECT CAVE KARST RESOURCES. A CASING DESIGN THAT HAS A ONE INCH JOB PERFORMED DOES NOT COUNT AS A SOLID SHEATH.

IF THE PRIMARY CEMENT JOB ON THE SURFACE CASING DOES NOT CIRCULATE, THEN THE NEXT TWO CASING STRINGS MUST BE CEMENTED TO SURFACE.

- 1. The 13-3/8 inch surface casing shall be set at approximately 400 feet and cemented to the surface.
 - a. If cement does not circulate to the surface, the appropriate BLM office shall be notified and a temperature survey utilizing an electronic type temperature survey with surface log readout will be used or a cement bond log shall be run to verify the top of the cement. Temperature survey will be run a minimum of six hours after pumping cement and ideally between 8-10 hours after completing the cement job.
 - b. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry.
 - c. Wait on cement (WOC) time for a remedial job will be a minimum of 4 hours after bringing cement to surface or 500 pounds compressive strength, whichever is greater.
 - d. If cement falls back, remedial cementing will be done prior to drilling out that string.
- 2. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:
 - □ Cement to surface. If cement does not circulate see B.1.a, c-d above. Wait on cement (WOC) time for a primary cement job is to include the lead cement slurry due to cave/karst. Excess calculates to 15% Additional cement may be required.

Centralizers required through the curve and a minimum of one every other joint.

٠.	
,	Cement as proposed by operator. Operator shall provide method of
	verification. Excess calculates to 22% - Additional cement may be
	required.

3. The minimum required fill of cement behind the 7 inch production casing is:

4. The minimum required fill of cement behind the 4-1/2 inch production Liner is:

Cement as proposed by operator. Operator shall provide method of verification.

5. If hardband drill pipe is rotated inside casing, returns will be monitored for metal. If metal is found in samples, drill pipe will be pulled and rubber protectors which have a larger diameter than the tool joints of the drill pipe will be installed prior to continuing drilling operations.

C. PRESSURE CONTROL

- 1. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.
- 2. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be **2000** (**2M**) psi.
 - a. **For surface casing only:** If the BOP/BOPE is to be tested against casing, the wait on cement (WOC) time for that casing is to be met (see WOC statement at start of casing section). Independent service company required.
- 3. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the 9-5/8 intermediate casing shoe shall be 3000 (3M) psi.
- 4. The appropriate BLM office shall be notified a minimum of 4 hours in advance for a representative to witness the tests.
 - a. In a water basin, for all casing strings utilizing slips, these are to be set as soon as the crew and rig are ready and any fallback cement remediation has been done. The casing cut-off and BOP installation can be initiated four hours after installing the slips, which will be approximately six hours after bumping the plug. For those casing strings not using slips, the minimum wait time before cut-off is eight hours after bumping the plug. BOP/BOPE testing can begin after cut-off or once cement reaches 500 psi compressive strength (including lead when specified), whichever is greater. However, if the float does not hold, cut-off cannot be initiated until cement reaches 500 psi compressive strength (including lead when specified).
 - b. The tests shall be done by an independent service company utilizing a test plug **not** a **cup** or **J-packer**. The operator also has the option of utilizing an independent tester to test without a plug (i.e. against the casing) pursuant to Onshore Order 2 with the pressure not to exceed 70% of the burst rating for the casing. Any test against the casing must meet the WOC time for water basin (18 hours) or potash (24 hours) or 500 pounds compressive strength, whichever is greater, prior to initiating the test (see casing segment as lead cement may be critical item).

- c. The test shall be run on a 5000 psi chart for a 2-3M BOP/BOP, on a 10000 psi chart for a 5M BOP/BOPE and on a 15000 psi chart for a 10M BOP/BOPE. If a linear chart is used, it shall be a one hour chart. A circular chart shall have a maximum 2 hour clock. If a twelve hour or twenty-four hour chart is used, tester shall make a notation that it is run with a two hour clock.
- d. The results of the test shall be reported to the appropriate BLM office.
- e. All tests are required to be recorded on a calibrated test chart. A copy of the BOP/BOPE test chart and a copy of independent service company test will be submitted to the appropriate BLM office.
- f. The BOP/BOPE test shall include a low pressure test from 250 to 300 psi. The test will be held for a minimum of 10 minutes if test is done with a test plug and 30 minutes without a test plug. This test shall be performed prior to the test at full stack pressure.

D. DRILL STEM TEST

If drill stem tests are performed, Onshore Order 2.III.D shall be followed.

E. WASTE MATERIAL AND FLUIDS

All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of drilling operations and completion operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area.

Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

JAM 020215