

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC NMOCD ARTESIA	Form C-141 Revised August 8, 2011

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: LINN Energy	Contact: Joe Hernandez	
Address: 2130 W Bender Blvd. - Hobbs, NM	Telephone No.: 575-942-8675	
Facility Name: HE West B Fed 43	Facility Type: Water Flood	
Surface Owner: BLM	Mineral Owner: BLM	API No.: 3001526049

LOCATION OF RELEASE

Unit Letter M	Section 9	Township 17S	Range 31E	Feet from the 660	North/South Line S	Feet from the 760	East/West Line W	County Eddy
------------------	--------------	-----------------	--------------	----------------------	-----------------------	----------------------	---------------------	----------------

Latitude: 32 50' 37.6" Longitude: -103 52' 51.5"

NATURE OF RELEASE

Type of Release: Produced water & oil	Volume of Release: 1/4	Volume Recovered: 0/1
Source of Release: Flowline	Date and Hour of Occurrence: 10/27/2011 - 0830	Date and Hour of Discovery: 10/27/2011 - 0900
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Joe Hernandez	Date and Hour: 10/27/2011 - 1330	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: 2" poly line failure. Shut in the well, repaired the line.



Describe Area Affected and Cleanup Action Taken.* : Approx. 360' long x 15' wide trail into pasture.

Impacted soils above regulatory threshold levels were manually and mechanically excavated from the spill area.

Impacted soils were transported off-site for disposal at Lea Land Landfill. Once the impacted soils were removed to acceptable levels, the production pad and the pasture areas were backfilled with like materials and smoothed to grade, then the pasture area was seeded with a BLM mix #2 & #4. Water bars were installed to prevent wind and water erosion.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by District Supervisor: 	
Printed Name: Jose Hernandez	Approval Date: 10/6/14	Expiration Date: NA
Title: Foreman	Conditions of Approval: Final	Attached <input type="checkbox"/>
E-mail Address: jhernandez@linnenergy.com		
Date: 10/17/2012	Phone: 575-738-1739	

* Attach Additional Sheets If Necessary

2RP-945