

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company : LIME ROCK RESOURCES II-A, L.P.	Contact : Jerry Smith
Address : 1111 Bagby Street Suite 4600, Houston, TX 77002	Telephone No. : 575-748-9724
Facility Name : Condor 8 Federal #001H	Facility Type: Battery

Surface Owner : Federal	Mineral Owner	Lease No. : API #30-015-35829 2RP-853
-------------------------	---------------	--

LOCATION OF RELEASE


Unit Letter F	Section 8	Township 18S	Range 27E	Feet from the 1770	North/South Line FNL	Feet from the 2525	East/West Line FWL	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	-------------

Latitude 32.76464 Longitude -104.300765

NATURE OF RELEASE

Type of Release : OIL	Volume of Release : 15 bbls	Volume Recovered: -0-
Source of Release : Overflow Oil Transport	Date and Hour of Occurrence: 7/28/11 10:07 am	Date and Hour of Discovery: 7/28/11 10:07 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? Transport Driver	Date and Hour : 7/28/11 10:07 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

During loading procedures the driver for Great Lakes Transport overflowed his transport truck.

Describe Area Affected and Cleanup Action Taken.*

Talon/LPE excavated the saturated soil from the impacted area on the location to a depth of 2-feet deep and the flow path to a depth of 1-foot deep. The impacted soil was transported to Lea Land, LLC for disposal. Talon/LPE backfilled the area with soil to match the surrounding terrain and a 250'x75' berm was installed in the southeast corner of the location. Micro blaze was applied to the impacted area of the rip rap.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Jerry Smith	Approved by District Supervisor:	
Title: Assistant Production Supervisor	Approval Date: 4/22/15	Expiration Date:
E-mail Address: jsmith@limerockresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/15/11 Phone: 575-748-9724		

* Attach Additional Sheets If Necessary

Final
2RP-853